

**ASBESTOS CONTAINING MATERIALS
INVESTIGATION REPORT**

**SOUTH TOWER RESIDENCE HALL
COLUMBIA, SOUTH CAROLINA 29201**



**UNIVERSITY OF
SOUTH CAROLINA**

REPORT PREPARED FOR:

UNIVERSITY OF SOUTH CAROLINA

**743 Green Street
Columbia, South Carolina 29208**

BY:

**F&ME CONSULTANTS
Geotechnical / Environmental / Materials**

**3112 Devine Street
Columbia, South Carolina 29205
(803) 254-4540**

February 24, 2012

E5200.04A

TABLE OF CONTENTS

I. Executive Summary1
II. Introduction.....3
III. Investigation Results.....3
IV. Asbestos Containing Materials Description and Assessment.....4
V. Recommendations.....7

APPENDIX A

- Site Vicinity Map (Figure 1)
- ACM Sample Location Plans (Figures 2 thru 19)
- Homogeneous Area Plans (Figures 20 thru 25)

APPENDIX B

- Summary of Samples (Table I)
- Summary of Asbestos Containing Materials (Table II)
- Summary of Inspection
- Physical Assessment Data Sheets
- Bulk Asbestos Analytical Reports (F&ME)
- Bulk Asbestos Analytical Reports (Provided by USC)

APPENDIX C

- Personnel Certifications

APPENDIX D

- SCDHEC Regulations
- SCDHEC Abatement Project Forms

I. EXECUTIVE SUMMARY

As requested, F&ME Consultants has completed an Asbestos Containing Materials (ACM) investigation of the USC South Tower Residence Hall located at 614 Bull Street in Columbia, South Carolina. This investigation was performed due to planned mechanical renovations to the existing building structure, and was conducted in accordance with SCDHEC, AHERA, USEPA, ASHARA, NESHAP, and OSHA regulations. This investigation was limited to the sub-basement, basement, first floor, the central core areas of floors 2 through 18, the penthouse and a visual evaluation of the roof. While the actual dormitory rooms on floors 2 through 18 were not included in the field component of this investigation, we have made assumptions about the materials located within the dorm rooms based on data provided by USC's HAZMAT personnel. The field component of our investigation was conducted and phased to correspond with time periods that would be least burdensome to the students' living environment. Phase A, which consisted of a LBP and ACM investigation of the core areas of the typical repeating dormitory floors and the first floor, was conducted during winter break on December 19th and 20th, 2011. Phase B was conducted on January 3rd and 4th, 2012, and included LBP and ACBM investigations of the subbasement, basement, penthouse and roof.

It is our understanding that the scope of the planned renovations consists of the removal and replacement of the existing two pipe fan coil unit system and the roof. We also understand that due to the magnitude of these renovations and the requirement that they occur while the building is unoccupied, the renovations will need to be sequenced over two summer breaks. Initial renovations will include the installation of hot and chilled water lines for the new four pipe system in the corridors of the typical repeating dormitory floors and will occur in the summer of 2012. Subsequent renovations will include the installation of new fan coils in the dormitory rooms and tying them into the lines installed during the initial renovations and will occur in the summer of 2013.

Our investigation identified eighteen (18) asbestos containing materials in the above mentioned areas of the building structure. The materials found to contain asbestos include the following: black mastic on thermal system insulation (TSI) pipe joints and elbows; black mastic on exterior fiberboard insulation on HVAC ductwork; mudded pipe joints and elbows; pipe wrap on fiberglass pipe insulation; drywall joint compound; spray applied textured ceiling surfacing material; fire stop at floor penetrations located in mechanical chases; black floor tile mastic under carpet and non-ACM floor tile; black stair tread adhesive; black adhesive for decorative trim on the first floor; 9" x 9" floor tile and associated mastic in the basement and dorm rooms; vinyl flooring and associated mastic; black roofing mastic on roof flashing and seams of rolled shingled roofing materials; gasket materials on valve and flange connections associated with machinery in the sub-basement and mechanical chases; Transite panels associated with insulated sandwich panels on the exterior curtain wall around the perimeter of the roof; three (3) interior Transite panels per dorm room; and caulking around interior fan coil units.

Please note that no machinery or mechanical piping systems were disassembled during this investigation. Therefore, all gasket materials utilized throughout the facility are assumed positive for asbestos and should be handled in accordance with State and Federal Regulations.

The results, conclusions and recommendations from this investigation are representative of the conditions observed at the site on the dates of the field inspections. F&ME does not assume responsibility for any changes in conditions or circumstances that occur after the inspections.


We sincerely appreciate the opportunity to assist you with this project. Should you have any questions or require additional information concerning this investigative report, please do not hesitate to contact us at (803) 254-4540.

Sincerely,

F&ME CONSULTANTS



Michael S. Mincey
Environmental Professional
Asbestos Consultant/Management Planner
SCDHEC License No: MP-00161
Expiration Date 02/15/2013



Glynn M. Ellen
Senior Environmental Professional
Asbestos Consultant/Management Planner
SCDHEC License No: ASB-22641
Expiration Date 02/15/2013

II. INTRODUCTION

As requested, F&ME Consultants has completed an Asbestos Containing Materials (ACM) investigation of the South Tower Residence Hall building located at 614 Bull Street in Columbia, South Carolina. This investigation was performed due to planned mechanical renovations to the building structures associated with the removal of the existing two pipe fan coil system and replacement with a new four pipe system. The field investigation was phased and conducted during winter break on December 19th and 20th, 2011, and January 3rd and 4th, 2012. This investigation was performed and limited to areas considered accessible, and was conducted pursuant to SCDHEC, USEPA, AHERA, NESHAP and OSHA regulations requiring an investigation prior to any renovation activity.

We understand that the South Tower was constructed in the late 1960's. Our field investigation revealed evidence of renovations and alterations that have occurred over the years, including floor tile removal and replacement; carpet installation and installation of suspended ceiling systems. A review of plans provided by the University after the completion of our field investigation indicated that the original floor plan in the first floor lobby areas was altered to include the security entrance at the front of the building. The provided plans indicated that this construction occurred in 1998, and included the installation of "new" sheetrock and joint compound. Furthermore, analyses of "old" or existing sheetrock indicated that this material is positive for asbestos. Therefore, should planned renovations to the first floor need to impact the sheetrock walls associated with these areas, samples of the "new" sheetrock will need to be collected to determine if it is negative for asbestos.

In addition, review of preliminary renovation documents indicated that plaster found throughout the building will not be impacted during the initial mechanical renovations. Therefore, due to the destructive nature necessary to collect samples, we did not sample the plaster. Analytical results obtained from USC Hazmat personnel taken from the plaster from different areas within the building indicate that the plaster may be negative for asbestos content. However, additional samples from throughout the building are necessary to deem it negative. If renovation activities are altered resulting in impacts to the plaster, additional samples will be required.

The results, conclusions and recommendations from this investigation are representative of the conditions observed at the site on the dates of the field inspection. F&ME does not assume responsibility for any changes in conditions or circumstances that occur after the inspection. Use of this document for bidding purposes is not recommended without prior consultation with F&ME. No other environmental concerns are addressed in this report.

III. INVESTIGATION RESULTS

The purpose of this investigation was to locate, sample and record the physical characteristics of suspect ACM within the interior portions of the building structure to be impacted by the initial mechanical renovations scheduled for the summer of 2012; to provide estimated quantities of those materials; and to obtain laboratory analytical results for determining the existence or non-existence of asbestos fibers. All remaining building materials (i.e. concrete, wood, brick, carpet, etc.) were not considered suspect.

Our visual inspection revealed a concrete-framed building structure with poured in place support columns and floor slabs. The exterior building envelope is constructed of precast double tee panels. The roofing system is a flat rolled shingle roof. Interior finishes include masonry block and concrete walls; plaster walls and ceilings; sheetrock walls; suspended drop ceilings; various floor tiles; quarry tile floors; and concrete floors.

Bulk samples of suspect materials were analyzed by Polarized Light Microscopy (PLM) in accordance with EPA 600/R-93/116. Confirmation Transmission Electron Microscopy (TEM) was also performed on any non-friable organically bound materials that tested negative for asbestos content as per SCDHEC regulations effective June 27, 2008. Proper sampling and chain-of-custody protocol were followed to ensure appropriate handling and delivery of samples to the analytical laboratory. See Appendix A for Sample Location Plans (Figures 2 thru 19) and Homogeneous Area Plans (Figures 20 thru 25).

Suspect materials identified during the investigation were pipe mastics on fiberglass thermal system insulation (TSI) joints and elbows; mudded pipe joints and elbows; pipe wrap on fiberglass pipe insulation; baseboard and carpet adhesives; drywall and associated joint compound; acoustical ceiling panels and tiles; felt vapor barrier under ceramic tile floors; fire stop caulking and mud at wall and floor penetrations; stair tread adhesive; spray applied textured ceiling surfacing material; trowel applied surfacing materials; floor tiles and associated mastics; vinyl flooring and associated mastic; leveling compound; ductwork mastics; black adhesive on decorative trim on the first floor; black roofing mastic on roof flashing and seams of rolled shingled roof; gasket materials associated with machinery in the sub-basement and mechanical chases; Transite curtain wall panels on roof; interior Transite panels; and caulking around interior fan coil units.

A total of one hundred and twelve (112) samples were extracted from the building structure. Due to multiple layering of the materials, one hundred and eight (108) samples were analyzed by PLM. Fifteen (15) samples were TEM confirmed. Of the materials analyzed, eleven (11) tested positive for asbestos mineral content (see Table II in Appendix B). Furthermore, seven (7) materials (vinyl flooring and associated mastic in the kitchenette, black roofing mastic, gasket materials, exterior Transite curtain wall panels, interior Transite panels, and caulking around interior fan coil unit,) were either assumed positive based on analytical data from USC Hazmat personnel or because of the inability to sample the material. The laboratory bulk sample analysis reports are located in Appendix B.

IV. ASBESTOS CONTAINING MATERIALS DESCRIPTION/ASSESSMENT

The following is a list of the asbestos containing materials (See Figures 20 thru 24 - Homogeneous Area Plans):

- HA-1 – Black Mastic on Joints of Pipe Insulation (~700 joints) (Est.)
Hot and chilled water lines associated with the original mechanical two pipe system are insulated with fiberglass and cellular foam glass. Seams at elbows and joints are sealed and coated with black mastic which contains asbestos. Overall, the majority of this material found during our field investigation was located on the first floor and the basement. However, it may be found hidden in wall cavities, closed mechanical chases and above hard plaster ceilings. Overall, this material appears to be in a good condition with little to no damage being noted.
- HA-2 – Black Mastic on HVAC Fiber Board Insulation (~4000 SF) (Est.)
Metal ductwork associated with the original HVAC system found within the building structure was insulated on the exterior with a non-asbestos fiber board. Seams of this insulation were sealed with black mastic. This material was found primarily in the first floor and basement of the building. This material may be found hidden within closed chases in the building. Overall, this material appears to be in a good condition with little to no damage being noted.

-
-
- HA-3 – TSI, Mudded Elbows and Joints on Mechanical Piping (~850/Each) (Est.)

Mechanical piping associated with domestic hot and cold water lines and drain lines for the existing fan coil system was found to have fiberglass insulation on the main pipe runs throughout the building. Elbows and joints were mudded with asbestos-containing pipe insulation. This material was found in the main mechanical chases, in some custodial closets, in some of the stairwells and above suspended ceilings on the first floor and basement. This material was found throughout the chases of the building with a significant amount of damage including debris accumulated on the floors. All chases should be maintained locked and sealed, and accessible only by personnel trained to work with asbestos containing materials. These chases will require abatement prior to any renovation activities.
 - HA-4 – TSI, Pipe Wrap on Fiberglass Pipe Insulation on Mechanical Piping (~2,500 LF)

The outer skin/wrap on fiberglass insulated pipe runs associated with the domestic hot and cold water lines and drain lines of the existing fan coil system noted above is adhered to the fiberglass with asbestos-containing black mastic. Overall, this material appears to be in a good condition with little to no damage being noted. This fiberglass pipe insulation will have to be removed, handled and disposed of as an asbestos-containing material.
 - HA-5 – Drywall Joint Compound (~70,000 SF) (Est.)

Samples collected during this investigation and samples collected previously by University hazmat personnel indicate that the original drywall joint compound utilized during the original construction of the building was an asbestos containing material. While there is evidence that non-ACM were used in other renovations within the building, the boundaries between the original and the newer drywall/JC are difficult to definitively delineate. For this reason, renovation activities associated with penetrations to and/or removal of drywall within the building should be performed and coordinated with a licensed abatement contractor.
 - HA-6 – Spray Applied Textured Ceiling Material (~71,500 SF) (Est.)

Original concrete ceilings throughout the typical repeating dormitory floor (floors 2-18) corridors, dormitory rooms, and the main stairwell were skim coated and covered with a spray applied textured ceiling surfacing material that is confirmed to contain asbestos. This material is found above suspended drop ceilings within the central core corridors of the typical repeating dormitory floors, with the exception of the eighteenth floor which was previously abated. Overall, this material appears to be in a good condition with little to no damage being noted. No evidence was found of this material on the first floor, basement, sub-basement or the penthouse levels of the building.
 - HA-7 – Gray Mudded Fire Stop at Floor Penetrations (~100 SF) (Est.)

Floor penetrations within the main mechanical chases are sealed with a gray mud/fire stop. This material is friable with evidence of physical damage being noted in all of the chases. It will need to be abated by a licensed abatement contractor prior to any renovations activities. Abatement operations will require the containment of chases above and below the penetrations simultaneously to control fiber release.

-
-
- HA-8 – Black Floor Tile Mastic (~9,700 SF) (Est.)

Review of drawings provided by the University indicated that the flooring materials utilized throughout the building were vinyl asbestos floor tiles (VAT). However, renovations during the life of the building have removed these floor tiles and they have been replaced with other floor tiles and/or carpet. Our investigation found residual black floor tile mastic under carpet and non-asbestos containing floor tile on all of the typical repeating dormitory floor corridors.
 - HA-9 – Black Stair Tread Adhesive (Unknown)

One sample of the stair tread adhesive found in the main stairwell indicated residual black mastic that tested positive for asbestos content. Further investigation efforts did not uncover any other areas with this black mastic.
 - HA-10 – Black Decorative Trim Adhesive (Unknown)

A decorative black plastic vinyl trim was utilized throughout the first floor lobby areas around doorways and at the tops of walls and interior columns. A black adhesive was used to adhere trim to the wall at three (3) door locations only. Further investigation efforts uncovered that a more common non-asbestos brown adhesive was used throughout the rest of the lobby areas.
 - HA-11 – 9”x 9” Tan Floor Tile and Associated Black Mastic (40,500 SF)

This floor tile and mastic appears to be the original floor tile utilized at the time of the building’s construction and is located throughout the main corridors and dormitory rooms. It shows evidence of wear and deterioration and is separating from its concrete substrate in areas adjacent to doorway thresholds. Damaged areas should be repaired and/or abated.
 - HA-12 – Black Roofing Mastic (~11SF)

Black roofing mastic was found on flashing and at some of the seams of the existing rolled shingle roof. Samples collected by University personnel obtained positive results on this material. Overall, this material is in a fair condition with evidence of wear and deterioration being noted. Renovations associated with the roof of the building will need to be performed by a roofing contractor with licensing and certifications necessary to remove asbestos containing roofing materials. (See Figure 18)
 - HA-13 – Valve and Flange Connection Gasket Materials (Unknown)

Valve and flange connections were noted within the main mechanical room in the sub-basement as well as in chases throughout the building. No machinery was dismantled as part of this investigation. Gaskets are considered a suspect material in regards to asbestos mineral content. Therefore, gaskets associated with the mechanical systems are assumed to be asbestos containing. Should renovation activities involve dismantling mechanical systems equipment and/or piping, either further investigation should be performed at that time to determine if the gaskets are ACM, or they should be assumed positive and removed, handled and disposed of as an asbestos containing material.

-
-
- HA-14 – Transite Wall Panels on Roof Curtain Wall (40 Each)
The existing louvered curtain wall around the perimeter of the roof is constructed with sandwich wall panels that are shown on original construction drawings to be “cement asbestos board”, also known as transite. Due to the destructive measures necessary to collect samples of these panels, they are assumed positive. Should planned renovations impact or require removal or penetration to these panels, they should be handled and removed by a licensed abatement contractor.
 - HA-15 – Vinyl Flooring and Associated Mastic in Kitchenette (2,125 SF)
The existing vinyl flooring is located in the kitchenette on floors 2 thru 18. It shows evidence of wear and deterioration and is separating from its concrete substrate in areas adjacent to doorway thresholds. The material is in overall good condition and was not part of our original scope of work. Therefore, these materials are assumed positive. Damaged areas should be repaired and/or abated.
 - HA-16 – Caulking Around Interior Fan Coil Units (1,450 LF)
The existing caulking is located around the exterior edges of the interior fan coil units. The material is in overall good condition. This material is not accessible during the time of our inspection and is therefore assumed positive. The material is in overall good condition. Should planned renovations impact or require removal of this material, it should be removed by a licensed abatement contractor.
 - HA-17 – Transite Panels Around the Fan Coil Unit (~715 Each)
The existing Transite Panels are located behind and on each side of the fan coil unit. These materials are shown on original construction drawings to be “cement asbestos board”, also known as Transite. This material is a known positive asbestos containing material. The material is in overall good condition. Should planned renovations impact or require removal or penetration to these panels, they should be handled and removed by a licensed abatement contractor.
 - HA-18 – 12” x 12” Floor Tile and Associated Mastic (~1,750 SF)
The 12” x 12” floor tiles are located in each dorm room on the 18th floor. This floor tile was added after the abatement of the original 9” x 9” floor tile. However, these materials were not part of our original scope of work and were not sampled during the investigation. Thus having no data on these materials, they are assumed positive and should be handled accordingly.

Quantities for the above-referenced asbestos containing materials are estimated based on their occurrence within the areas corresponding with the initial mechanical renovations. These quantities are not representative of the actual totals within the entire South Tower.

The Appendices include a Site Location Map (Figure 1), Sample Location Plans (Figures 2 thru 19), Homogeneous Area Plans (Figures 20 thru 25), a Summary of Samples (Table I), a Summary of Asbestos Containing Materials (Table II), Physical Assessment Data Sheets, Bulk Sample Analysis Reports, Personnel Certifications, and SCDHEC Regulations and associated Abatement Project Forms.

This report has been prepared exclusively for the University of South Carolina, and shall not be disseminated in whole or part to other parties without prior consent from the University of South Carolina or F&ME Consultants, Inc. No other environmental issues are addressed in this report.

Asbestos containing materials must be handled in accordance with state and federal regulations. Any activities that will impact these materials must be performed by licensed/certified asbestos contractors.

The SCDHEC regulates any disturbance to friable ACM, which is therefore considered to be regulated asbestos containing materials (RACM). The SCDHEC requires removal of friable ACM prior to building renovation or demolition activities. Furthermore, the disturbance of Category II non-friable ACM such as transite generally renders them to become friable, or regulated. However, the removal of Category I non-friable ACM such as floor tiles, mastics, floor sheeting and certain roofing materials is not required *if these materials are in good condition*. If it is anticipated that such materials will become crumbled or will experience severe forces, SCDHEC would also consider these materials to be RACM.

SCDHEC legally tracks the disposal of all ACM into landfills. Therefore, the SCDHEC must be notified prior to abatement and demolition projects in order to legally arrange for the proper disposal of ACM and associated contaminated debris. Most landfills will not accept ACM or asbestos-contaminated debris. This is an important consideration for the owner because it is more expensive to dispose of ACM than normal debris. If the abatement/demolition contractor selects a landfill that accepts ACM, the abatement/demolition debris could be transported to the permitted landfill. However, since the ACM would be mixed in with the total demolition debris, all of the debris would be considered to be ACM resulting in much higher disposal costs. Therefore, it is recommended that removal of all asbestos is conducted prior to and separate from building demolition activities.

OSHA regulates disturbances to all ACM. Unlike SCDHEC, OSHA does not distinguish between friable and non-friable ACM, regulated and non-regulated ACM, and/or ACM in good condition versus ACM in poor/damaged condition. Instead, OSHA regulates all contact with asbestos.

V. RECOMMENDATIONS

Due to the proposed renovation activities, it is recommended that all identified ACM are removed prior to the commencement of activities that will impact them. Based on the quantity of the ACM identified within the subject structure, this abatement project will require a project design developed by a SCDHEC-certified Asbestos Project Designer. The abatement work must be performed by AHERA-certified and SCDHEC-licensed Abatement Contractors in accordance with all applicable regulations and guidelines. The SCDHEC must be notified at least ten (10) days prior to abatement activities. All asbestos waste, including contaminated building materials (i.e. non-asbestos floor tiles with asbestos containing mastics, etc.), must be deposited in a landfill permitted by the SCDHEC for receiving ACM.

If any concealed and/or inaccessible ACM is encountered during asbestos abatement or renovation activities, the affected contractor(s) must stop work, take appropriate actions, and notify the Owner/ Abatement Contractor/ Asbestos Consultant for an appropriate response action. The SCDHEC must be notified in the event that any additional ACM is discovered, as well as if there are any changes in the condition of any identified ACM.

The SCDHEC's Standards of Performance for Asbestos Projects (R 61-86.1) includes requirements for abatement projects regarding notifications, project design, air sampling and analysis, etc. For informational purposes, some of these requirements are summarized below:

Notifications. Written notification (SCDHEC Form 3430) must be submitted to SCDHEC at least two (2) calendar weeks prior to initiation of abatement activities for renovation/demolition projects. A copy of this inspection report and applicable fee payment must be attached to the notification. Additional fees may be required. Copies of all notifications and documents pertinent to the abatement operations must be posted on the job site during abatement work. The Owner/Operators must notify all parties involved with this project of the nature of the work as well as the locations and quantities of asbestos materials to be disturbed or those located near demolition/removal work areas. This notification requirement is also extended to any persons/employees who work near the demolition/removal work areas.

Project Design. Furthermore, abatement projects that will remove more than 3,000 square, 1,500 linear or 656 cubic feet of asbestos-containing materials are required to have a licensed and certified Abatement Project Designer submit a project design to SCDHEC prior to the commencement of any abatement activities. The design must address all information as directed by the regulations and must be adhered to by the Abatement Contractor.


Air Monitoring. The Abatement Contractor is responsible for daily personal air sampling for Abatement Workers in compliance with current OSHA standard 29 CFR 1926.1101. All remaining air monitoring services required for a renovation project (i.e. backgrounds, areas, and clearances) will be provided by the Owner or the Owner's Representative, as required by SCDHEC.

APPENDIX A


Site Vicinity Map (Figure 1)

ACM Sample Location Plans (Figures 2 thru 19)

Homogeneous Areas Plans (Figures 20 thru 25)



| | | | |
|--------------------------------|---|--------------------|--|
| F&ME CONSULTANTS | SITE VICINITY MAP South Tower Dormitory Columbia, South Carolina | | |
| | Drawn By: N/A | Scale: N.T.S. | |
| University of South Carolina | Checked By: N/A | Project: E5200.040 | |
| | Approved By: N/A | Figure: 1 | |




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - SUB-BASEMENT
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | BS200.04 |
| APPROVED BY: | GME | FIGURE: | 2 |

UNIVERSITY OF SOUTH CAROLINA




F & ME
CONSULTANTS

UNIVERSITY OF SOUTH CAROLINA

SAMPLE LOCATION PLAN
SOUTH TOWER - BASEMENT
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | ES200.04 |
| APPROVED BY: | GME | FIGURE: | 3 |




F & ME
CONSULTANTS

UNIVERSITY OF SOUTH CAROLINA

SAMPLE LOCATION PLAN
SOUTH TOWER - 1ST FLOOR
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | ES200.04 |
| APPROVED BY: | GME | FIGURE: | 4 |




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 2ND FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 5




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 3RD FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 6




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 4TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 7




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 5TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 8




F & ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 6TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 9




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 7TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 10




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 8TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 11




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 9TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 12




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 11TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 13




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 13TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 14




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 14TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 15




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 15TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 16




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 16TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 17




F&ME
CONSULTANTS

SAMPLE LOCATION PLAN
SOUTH TOWER - 17TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 18



F&ME
CONSULTANTS


SAMPLE LOCATION PLAN
SOUTH TOWER - 18TH FLOOR
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04
FIGURE: 19

HA-13 - VALVE AND FLANGE GASKET MATERIALS
NOT SHOWN




F&ME
CONSULTANTS

UNIVERSITY OF SOUTH CAROLINA

HOMOGENEOUS AREA PLAN
SOUTH TOWER - SUB-BASEMENT
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | ES200.04 |
| APPROVED BY: | GME | FIGURE: | 20 |



- HA-2 - TSI BLACK MASTIC ON HVAC FIBER BOARD INSULATION
- HA-3 - TSI MUDDER ELBOWS AND JOINTS
- HA-4 - TSI PIPE WRAP ON FIBERGLASS PIPE INSULATION
- HA-5 - DRYWALL JOINT COMPOUND
- HA-11 - 9" X 9" TAN FLOOR TILE AND ASSOCIATED BLACK MASTIC
- CHASE - MAIN MECHANICAL CHASES ON ALL FLOORS CONTAINS HA-3, HA-4, OVERSPRAY FROM HA-6, HA-7 AND HA-13.

F&ME
CONSULTANTS

UNIVERSITY OF SOUTH CAROLINA

HOMOGENEOUS AREA PLAN
SOUTH TOWER - BASEMENT
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | BS200.04 |
| APPROVED BY: | GME | FIGURE: | 21 |

UP

HA-1 - BLACK MASTIC ON ELBOWS AND JOINTS OF FIBERGLASS AND FOAM GLASS PIPE INSULATION

HA-2 - TSI BLACK MASTIC ON HVAC FIBER BOARD INSULATION

HA-3 - TSI MUDDERED ELBOWS AND JOINTS


HA-4 - TSI PIPE WRAP ON FIBERGLASS PIPE INSULATION

HA-6 - SPRAY APPLIED TEXTURED CEILING MATERIAL

HA-10 - BLACK MASTIC ON DECORATIVE DOOR TRIM

CHASE - MAIN MECHANICAL CHASES ON ALL FLOORS CONTAINS HA-3, HA-4, OVERSPRAY FROM HA-6, HA-7 AND HA-13.

HA-3 MUDDERED ELBOWS NOTED ABOVE SUSPENDED CEILINGS IN THIS AREA



HA-1 BLACK MASTIC ON JOINTS AND ELBOWS NOTED IN CLOSED CHASE

F & M E
CONSULTANTS

UNIVERSITY OF SOUTH CAROLINA

HOMOGENEOUS AREA PLAN
SOUTH TOWER - 1ST FLOOR
COLUMBIA, SOUTH CAROLINA

| | | | |
|--------------|-----|----------|-----------|
| DRAWN BY: | MSM | SCALE: | 1"=10' |
| CHECKED BY: | JLS | PROJECT: | B5200.04A |
| APPROVED BY: | GME | FIGURE: | 22 |




HA-4 - TSI PIPE WRAP ON FIBERGLASS INSULATION



HA-5 - DRYWALL JOINT COMPOUND



HA-6 - SPRAY APPLIED TEXTURED CEILING MATERIAL (ALL FLOORS AND STAIRWELLS)



HA-3 MUDDER ELBOWS FOUND IN CUST. CLOSET ON FLOORS 4, 9 & 14

HA-9 BLACK MASTIC FOUND UNDER STAIR TREAD ON 3RD FLOOR IN STAIRWELL

HA-3 MUDDER ELBOWS FLOORS 2, 4, 6, 8, 9, 10, 12, 14, 16 & 18



HA-8 - BLACK MASTIC UNDER NON-ACM FLOOR TILE AND/OR CARPET



HA-16 - CAULKING AROUND INTERIOR FAN COIL UNITS

HA-11 - 9" X 9" FLOOR TILE AND ASSOCIATED MASTIC

HA-17 - TRANSITE PANELS AROUND FAN COIL UNITS



HA-15 - VINYL FLOORING AND MASTIC.



CHASE - MAIN MECHANICAL CHASES ON ALL FLOORS CONTAINS HA-3, HA-4, OVERSPRAY FROM HA-6, HA-7 AND HA-13.

F&ME
CONSULTANTS

HOMOGENEOUS AREA PLAN
SOUTH TOWER - TYPICAL LAYOUT - FLOORS 2-17
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: _____
CHECKED BY: _____
APPROVED BY: _____

SCALE: _____
PROJECT: _____
FIGURE: _____




HA-4 - TSI PIPE WRAP ON FIBERGLASS INSULATION



HA-5 - DRYWALL JOINT COMPOUND

HA-15 - VINYL FLOORING AND MASTIC.

HA-9 BLACK MASTIC FOUND UNDER STAIR TREAD ON 3RD FLOOR IN STAIRWELL



HA-3 MUDDER ELBOWS FLOORS 2, 4, 6, 8, 9, 10, 12, 14, 16 & 18



HA-16 - CAULKING AROUND INTERIOR FAN COIL UNITS



HA-17 - TRANSITE PANELS AROUND FAN COIL UNITS



HA-18 - 12" x 12" FLOOR TILE AND ASSOCIATED MASTIC



CHASE - MAIN MECHANICAL CHASES ON ALL FLOORS CONTAINS HA-3, HA-4, OVERSPRAY FROM HA-6, HA-7 AND HA-13.


F & ME
CONSULTANTS

HOMOGENEOUS AREA PLAN
SOUTH TOWER - 18th Floor
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JLS
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04A
FIGURE: 24



HA-12 - BLACK ROOFING MASTIC ON FLASHING AND SEAMS OF ROLLED SHINGLE ROOF. (NOT SHOWN)



HA-14 - TRANSITE WALL PANELS ON ROOF CURTAIN WALL.

F&ME
CONSULTANTS

GENERAL SITE PLAN
SOUTH TOWER - 19TH FLOOR (PENTHOUSE-ROOF)
COLUMBIA, SOUTH CAROLINA

UNIVERSITY OF SOUTH CAROLINA

DRAWN BY: MSM
CHECKED BY: JSL
APPROVED BY: GME

SCALE: 1"=16'
PROJECT: E5200.04A
FIGURE: 25

APPENDIX B

Summary of Samples (Table I)
Summary of Asbestos Containing Materials (Table II)
Summary of Inspection
Physical Assessment Data Sheets
Bulk Asbestos Analytical Reports (F&ME)
Bulk Asbestos Analytical Reports (Provided by USC)

TABLE I. SUMMARY OF SAMPLES

| Sample ID | Sample Description | Floor |
|------------------|--|--------------|
| ST18-1 | Baseboard Adhesive (Cream) | 18th |
| ST18-2 | Carpet Adhesive (Yellow) Only | 18th |
| ST18-3 | Black Pipe Mastic Only | 18th |
| ST18-4 | Pipe Wrap on Fiberglass Insulation | 18th |
| ST18-5 | Mudded Elbow | 18th |
| ST18-6 | Joint Compound | 18th |
| ST18-7 | 2' x 2' Textured Ceiling Panel | 18th |
| ST18-8 | Felt Vapor Barrier Under Ceramic Tile | 18th |
| ST18-9 | Brown Fire Stop Caulking | 18th |
| ST18-10 | Red Fire Stop Caulking | 18th |
| ST18-11 | Lite Gray HVAC Duct Mastic | 18th |
| ST18-12 | Sheetrock/Joint Compound | 18th |
| ST18-13 | Stair Tread Adhesive (Yellow) | 18th |
| ST18-14 | Textured Ceiling Material on Concrete Ceiling | 18th |
| ST16-15 | Crepe Pipe Mastic on Fiberglass Insulation Only | 16th |
| ST16-16 | Mud at Floor Penetrations (Chase) | 16th |
| ST16-17 | Black Mastic Under Carpet (Yellow) Adhesive Only | 16th |
| ST16-18 | Trowel Applied Surfacing Material (Brown) | 16th |
| ST16-19 | 12" x 12" White Floor Tile & Black Mastic Only | 16th |
| ST16-20 | Gypsum Backer Board | 16th |
| ST18-21 | White Leveling Compound Only | 18th |
| ST15-22 | Carpet Adhesive (Yellow) Only | 15th |
| ST15-23 | 2' x 2' Textured Ceiling Panel | 15th |
| ST15-24 | Baseboard Adhesive (Cream) | 15th |
| ST15-25 | Mudded Elbow | 15th |
| ST15-26 | Lite Gray HVAC Duct Mastic | 15th |
| ST15-27 | Black Pipe Mastic Only | 15th |
| ST14-28 | Brown Fire Stop Caulking | 14th |
| ST14-29 | Red Fire Stop Caulking | 14th |
| ST14-30 | Felt Vapor Barrier Under Ceramic Tile | 14th |
| ST14-31 | Overspray on HVAC Duct (Chase) | 14th |
| ST14-32 | Textured Ceiling Material on Concrete Ceiling | 14th |
| ST13-33 | Mud at Floor Penetrations (Chase) | 13th |
| ST13-34 | Crème Pipe Mastic on Fiberglass Insulation Only | 13th |
| ST13-35 | Sheetrock/Joint Compound | 13th |
| ST13-36 | Gypsum Backer Board | 13th |
| ST13-37 | 12" x 12" White Floor Tile & Black Mastic Only | 13th |
| ST13-38 | White Leveling Compound Only | 13th |
| ST11-39 | Overspray on HVAC Duct (Chase) | 11th |
| ST9-40 | Mudded Elbow (Stairwell) | 9th |
| ST4-41 | Mudded Elbow (Custodial Closet) | 4th |
| ST8-42 | Carpet Adhesive (Yellow) Only | 8th |
| ST7-43 | 12" x 12" White Floor Tile & Black Mastic Only | 7th |

TABLE I

TABLE I. SUMMARY OF SAMPLES

| Sample ID | Sample Description | Floor |
|------------------|---|--------------|
| ST7-44 | White Leveling Compound Only | 7th |
| ST6-45 | Pipe Wrap on Fiberglass Insulation | 6th |
| ST5-46 | Black Mastic Under Carpet (Yellow) Adhesive Only | 5th |
| ST5-47 | Red Fire Stop Caulking | 5th |
| ST5-48 | Brown Fire Stop Caulking | 5th |
| ST5-49 | Stair Tread Adhesive (Yellow) | 5th |
| ST5-50 | Textured Ceiling Material on Concrete Ceiling | 5th |
| ST5-51 | Trowel Applied Surfacing Material (Brown) | 5th |
| ST5-52 | Lite Gray HVAC Duct Mastic | 5th |
| ST4-53 | Gypsum Backer Board | 4th |
| ST4-54 | Black Pipe Mastic Only | 4th |
| ST4-55 | Felt Vapor Barrier Under Ceramic Tile | 4th |
| ST4-56 | Baseboard Adhesive (Cream) | 4th |
| ST4-57 | 2' x 2' Textured Ceiling Panels | 4th |
| ST3-58 | Trowel Applied Surfacing Material (Brown) | 3rd |
| ST3-59 | Stair Tread Adhesive (Yellow & Black) | 3rd |
| ST3-60 | Mud at Floor Penetrations (Chase) | 3rd |
| ST3-61 | Overspray on Concrete Ceiling of Chase | 3rd |
| ST3-62 | Sheetrock/Joint Compound | 3rd |
| ST2-63 | Pipe Wrap on Fiberglass Insulation | 2nd |
| ST1-64 | 2' x 2' Smooth Textured Ceiling Panels (Recessed) | 1st |
| ST1-65 | 2' x 2' Smooth Textured Ceiling Panels (Recessed) | 1st |
| ST1-66 | 2' x 2' Smooth Textured Ceiling Panels (Recessed) | 1st |
| ST1-67 | Baseboard Adhesive (Lite Brown) | 1st |
| ST1-68 | Baseboard Adhesive (Lite Brown) | 1st |
| ST1-69 | Baseboard Adhesive (Lite Brown) | 1st |
| ST1-70 | Baseboard Adhesive (Brown) | 1st |
| ST1-71 | Baseboard Adhesive (Brown) | 1st |
| ST1-72 | Baseboard Adhesive (Brown) | 1st |
| ST1-73 | Black Pipe Mastic | 1st |
| ST1-74 | Fiberglass Duct Board Gutter Skin | 1st |
| ST1-75 | Fiberglass Duct Board Gutter Skin | 1st |
| ST1-76 | Fiberglass Duct Board Gutter Skin | 1st |
| ST1-77 | Mudded Elbow | 1st |
| ST1-78 | Black Adhesive on Black Door Trim | 1st |
| ST1-79 | Black Adhesive on Black Door Trim | 1st |
| ST1-80 | Black Adhesive on Black Door Trim | 1st |
| ST16-81 | Crème Pipe Mastic Only | 16th |
| ST1-82 | Black Mastic Elbow | 1st |
| ST1-83 | Pipe Wrap on Fiberglass Insulation | 1st |
| STB-84 | Mudded Elbow | 1st |
| STB-85 | Pipe Wrap on Fiberglass Insulation | 1st |

TABLE I

TABLE I. SUMMARY OF SAMPLES

| Sample ID | Sample Description | Floor |
|------------------|---|--------------|
| STB-86 | Mudded Elbow | Basement |
| STB-87 | 9" x 9" Tan Floor Tile & Mastic | Basement |
| STB-88 | 9" x 9" Tan Floor Tile & Mastic | Basement |
| STB-89 | 9" x 9" Tan Floor Tile & Mastic | Basement |
| STB-90 | Overspray on HVAC Duct (Bathroom) | Basement |
| STB-91 | 12" x 12" Heavy Textured Ceiling Panels | Basement |
| STB-92 | 12" x 12" Heavy Textured Ceiling Panels | Basement |
| STB-93 | 12" x 12" Heavy Textured Ceiling Panels | Basement |
| STB-94 | Pipe Wrap on Fiberglass Insulation | Basement |
| STB-95 | Canvas Pipe Wrap | Basement |
| STB-96 | Canvas Pipe Wrap | Basement |
| STB-97 | Canvas Pipe Wrap | Basement |
| STSB-98 | HVAC Duct Wrap | Sub-basement |
| STSB-99 | HVAC Duct Wrap | Sub-basement |
| STSB-100 | HVAC Duct Wrap | Sub-basement |
| STSB-101 | Canvas Pipe Wrap | Sub-basement |
| STSB-102 | Canvas Pipe Wrap | Sub-basement |
| STSB-103 | Canvas Pipe Wrap | Sub-basement |
| STSB-104 | Green Board/Joint Compound | Sub-basement |
| STSB-105 | Green Board/Joint Compound | Sub-basement |
| STSB-106 | Green Board/Joint Compound | Sub-basement |
| STSB-107 | Unknown Debris | Sub-basement |
| STSB-108 | Unknown Debris | Sub-basement |
| STSB-109 | Unknown Debris | Sub-basement |
| STSB-110 | 12" x 12" Brown w/White Speckles' Floor Tile & Mastic | Sub-basement |
| STSB-111 | 12" x 12" Brown w/White Speckles' Floor Tile & Mastic | Sub-basement |
| STSB-112 | 12" x 12" Brown w/White Speckles' Floor Tile & Mastic | Sub-basement |

TABLE I

TABLE II. SUMMARY OF ASBESTOS CONTAINING MATERIALS

| Sample ID | Sample Description | % Asbestos |
|------------------|--|-------------------|
| ST18-3 | Black Pipe Mastic | 10% Chrysotile |
| ST18-5 | Mudded Elbow | 3% Amosite |
| ST18-12 | Joint Compound | 5% Chrysotile |
| ST18-14 | Textured Ceiling Material on Concrete Ceiling | 3% Chrysotile |
| ST16-16 | Mud at Floor Penetrations (Chase) | 3% Amosite |
| ST16-17 | Black Mastic Under Carpet (Yellow) Adhesive Only | 5% Chrysotile |
| ST16-19A | Black Floor Tile Mastic | 8% Chrysotile |
| ST15-25 | Mudded Elbow | 3% Amosite |
| ST15-27 | Black Pipe Mastic | 10% Chrysotile |
| ST14-31 | Overspray on Ductwork | 3% Chrysotile |
| ST14-32 | Textured Ceiling Material on Concrete Ceiling | 3% Chrysotile |
| ST14-33 | Mud at Floor Penetrations (Chase) | 3% Amosite |
| ST13-37 | Black Floor Tile Mastic | 5% Chrysotile |
| ST11-39 | Overspray on Ductwork | 3% Chrysotile |
| ST9-40 | Mudded Elbow | 3% Amosite |
| ST4-41 | Mudded Elbow | 5% Chrysotile |
| ST5-46 | Black Mastic Under Carpet (Yellow) Adhesive Only | 5% Chrysotile |
| ST5-50 | Textured Ceiling Material on Concrete Ceiling | 3% Chrysotile |
| ST4-54 | Black Pipe Mastic Only | 10% Chrysotile |
| ST3-59 | Stair Tread Adhesive (Yellow & Black) | 5% Chrysotile |
| ST3-60 | Mud at Floor Penetrations (Chase) | 3% Chrysotile |
| ST3-61 | Overspray on Concrete Ceiling | 3% Chrysotile |
| ST3-62A | Joint Compound | 5% Chrysotile |
| ST1-77 | Mudded Elbow | 5% Chrysotile |
| ST1-78 | Black Adhesive on Black Door Trim | 3% Chrysotile |
| ST1-79 | Black Adhesive on Black Door Trim | 5% Chrysotile |
| ST1-82 | Black Mastic Elbow | 10% Chrysotile |
| ST1-83 | Pipe Wrap on Fiberglass Insulation | 10% Chrysotile |
| STB-84 | Mudded Elbow | 3% Chrysotile |
| STB-86 | Mudded Elbow | 3% Chrysotile |
| STB-87 | 9" x 9" Tan Floor Tile | 5% Chrysotile |
| STB-87A | Black Floor Tile & Mastic | 10% Chrysotile |
| STB-90 | Overspray on Ductwork | 8% Chrysotile |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

TABLE II

SUMMARY OF INSPECTION

The following tables summarize the physical assessment data, sampling and assessment results.

As exhibited on these tables, coding is used to abbreviate the asbestos containing materials' (ACM) locations, characteristics and results. These codes are as follows:

TYPES OF ACM:

- Misc. = Miscellaneous
- Sur. = Surfacing
- TSI = Thermal System Insulation

ACM LOCATIONS:

Homogeneous areas = Indicated by Roman Numerals, Room Number or Area Designation

| <u>Functional Space No.:</u> | <u>Functional Space Type:</u> |
|------------------------------|--|
| 1. | H = Corridors/Hallways |
| 2. | C = Chases |
| 3. | L = 1 st Floor Lobby Areas |
| 4. | S = Storage Rooms |
| 5. | RHD = Resident Hall Director Apartment |
| 6. | A = Above Suspended Ceilings |
| 7. | B = Basement |
| 8. | SB = Sub-Basement |
| 9. | ST = Stairwell |
| 10. | CC = Custodial Closet |
| 11. | R = Roof |
| 12. | K = Kitchenette |
| 13. | D = Dorm Rooms |

ACM CHARACTERISTICS:

- F = Friable
- NF = Non-Friable

ASSESSMENT RESULTS:

(Refer to Physical Assessment Data)

POTENTIAL FOR DISTURBANCE:

(Refer to Physical Assessment Data)

PHYSICAL ASSESSMENT CATAGORIES:

1. Damaged or significantly damaged friable thermal system insulation ACM.
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. ACM with potential for significant damage.
6. ACM with potential for damage.
7. Any remaining friable ACM or friable suspect ACM.
8. Non-friable ACM.

CLASSIFICATION FOR HAZARD POTENTIAL:

(Tabular Display)

| <u>Hazard Rank</u> | <u>ACM Condition</u> | <u>ACM Disturbance Potential</u> |
|--------------------|-----------------------|----------------------------------|
| 7 | Significantly Damaged | Any |
| 6 | Damaged | Potential for Significant Damage |
| 5 | Damaged | Potential for Damage |
| 4 | Damaged | Low |
| 3 | Good | Potential for Significant Damage |
| 2 | Good | Potential for Damage |
| 1 | Good | Low |

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space No: 1,2,3,6,7 **Type:** H,C,L,A,B **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: _____ **TSI** _____ **Surfacing** X **Misc.** _____

Description: HA-1, TSI Black Mastic on Fiberglass Pipe Insulation

Approximate Amount of Material (SF or LF): ~700 Each

Condition:

Percent Damage: X >0% _____ <10% _____ >10% _____ <25% _____ >25%

Extent of Damage: _____ Localized _____ X Distributed

Type of Damage: X Deterioration _____ Water _____ Physical

Description:

Black mastic on joints and elbows of fiberglass insulation.

Overall Condition Rating: Sig. Damaged _____ Damaged _____ Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------|----------|----------|-------------|
| Frequency of Potential Contact: | _____ | _____ | <u>X</u> | _____ |
| Influence of Vibration | _____ | _____ | <u>X</u> | _____ |
| Frequency of Air Erosion | _____ | _____ | <u>X</u> | _____ |
| Potential of Water Erosion | _____ | _____ | <u>X</u> | _____ |


Overall Potential Disturbance Rating:

| | | |
|---------------------------|----------------------|--------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| _____ | _____ | <u>8</u> |

Overall Hazard Rank #:

| | | | |
|--------------|-------------|-----------------------|-----------------|
| Sig. Damaged | Pot. Damage | Sig. Potential Damage | Low Pot. Damage |
| _____ | _____ | _____ | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 1,3,6,7 **Type:** H,L,A,B **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-2, Black Mastic on Fiberboard Insulation

Approximate Amount of Material (SF or LF): ~4,000 SF (includes non-ACM fiberboard)

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

Black mastic on seams of original fiberboard duct insulation

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|----------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |

Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|-----------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> </u> | <u>8</u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|--------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> </u> | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space No: 1,2,3,6,7,9,10 **Type:** H,C,L,A,B, ST,CC **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: X **TSI** **Surfacing** **Misc.**

Description: HA-3, TSI Mudded Elbows and Joints.

Approximate Amount of Material (SF or LF): ~850 Each

Condition:

Percent Damage: >0% <10% X >10% <25% >25%

Extent of Damage : X Localized Distributed

Type of Damage: Deterioration X Water X Physical

Description:

Mudded elbows and joints of original domestic hot and cold water lines.

Overall Condition Rating: Sig. Damaged X Damaged Good

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-----------------------------|-----------------------------|-----------------------------|--------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Potential of Water Erosion | <u> </u> | <u> X </u> | <u> </u> | <u> X </u> |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|-----------------------------|-----------------------------|
| <u> 1 </u> | <u> </u> | <u> </u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|--------------|-----------------------------|-----------------------------|-----------------------------|
| <u> 7 </u> | <u> </u> | <u> </u> | <u> </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space No: 1,2,3,6,7,9,10 **Type:** H,C,L,A,B, ST,CC **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: X **TSI** **Surfacing** **Misc.**

Description: HA-4, TSI Pipe Wrap on Fiberglass Pipe Insulation

Approximate Amount of Material (SF or LF): ~2,500 LF

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

Black mastic used to adhere outer wrapping to fiberglass pipe insulation.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-----------------------------|-----------------------------|----------|-----------------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|-----------------------------|-----------------------------|--------------------------|
| <u> </u> | <u> </u> | <u>8</u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-----------------------------|-----------------------------|-----------------------------|-----------------|
| <u> </u> | <u> </u> | <u> </u> | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space No: 1,3,5,7 **Type:** H,L,RHD,B **Location:** (See Homogeneous Area Plan)

Type of Suspect

Material: _____ **TSI** X **Surfacing** _____ **Misc.**

Description: HA-5, Drywall Joint Compound

Approximate Amount of Material (SF or LF): ~70,000 SF (Includes entire wall system)

Condition:

Percent Damage: _____ >0% X <10% _____ >10% _____ <25% _____ >25%

Extent of Damage: X Localized _____ X Distributed

Type of Damage: X Deterioration _____ Water _____ X Physical

Description:

Original joint compound used on drywall.

Overall Condition Rating: Sig. Damaged _____ Damaged _____ Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------|----------|----------|-------------|
| Frequency of Potential Contact: | _____ | <u>X</u> | _____ | _____ |
| Influence of Vibration | _____ | _____ | <u>X</u> | _____ |
| Frequency of Air Erosion | _____ | _____ | <u>X</u> | _____ |
| Potential of Water Erosion | _____ | _____ | <u>X</u> | _____ |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|----------------------|--------------------------|
| _____ | <u>6</u> | _____ |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|--------------|------------------|------------------|-----------------|
| _____ | _____ | <u>2</u> | _____ |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  Date: 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space No: 1,2,6,7,9 **Type:** H,C,A,B,ST **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** Misc.

Description: HA-6, Spray Applied Texture Ceiling Surfacing Material

Approximate Amount of Material (SF or LF): ~71,000 SF

Condition:

Percent Damage: >0% <10% >10% <25% >25%

Extent of Damage: Localized Distributed

Type of Damage: Deterioration Water Physical

Description:

Spray applied textured surfacing found on original concrete and hard plaster ceilings. Overspray from this material was found in chases on concrete deck above and metal ductwork. Overspray is in a friable condition.

Overall Condition Rating: Sig. Damaged Damaged Good

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|--------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| Frequency of Potential Contact: | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Influence of Vibration | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Frequency of Air Erosion | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Potential of Water Erosion | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|-------------------------------------|--------------------------|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6 | | |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|--------------------------|--------------------------|-------------------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | | | |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 2 **Type:** C **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: X **TSI** _____ **Surfacing** _____ **Misc.** _____

Description: HA-7, Gray Mudded Floor Penetrations

Approximate Amount of Material (SF or LF): ~100 SF

Condition:

Percent Damage: _____ >0% _____ <10% X >10% _____ <25% _____ >25%

Extent of Damage : X Localized _____ X Distributed

Type of Damage: X Deterioration _____ Water _____ X Physical

Description:

Gray mud utilized as a fire stop at floor penetrations throughout chases in the building. This material has obtained physical damage in these areas and is friable.

Overall Condition Rating: Sig. Damaged X Damaged _____ Good _____

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------|----------|----------|-------------|
| Frequency of Potential Contact: | _____ | <u>X</u> | _____ | <u>X</u> |
| Influence of Vibration | _____ | _____ | <u>X</u> | <u>X</u> |
| Frequency of Air Erosion | _____ | _____ | <u>X</u> | <u>X</u> |
| Potential of Water Erosion | _____ | _____ | <u>X</u> | <u>X</u> |

Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|----------------------|--------------------------|
| _____ | <u>1</u> | _____ |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|--------------|------------------|------------------|-----------------|
| _____ | <u>7</u> | _____ | _____ |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 1,4 **Type:** H,S **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-8, Black Floor Tile Mastic

Approximate Amount of Material (SF or LF): ~9,700 SF

Condition:

Percent Damage: >0% X <10% >10% <25% >25%

Extent of Damage: Localized X Distributed

Type of Damage: X Deterioration Water X Physical

Description:

Residual black mastic from floor tile that has been removed throughout corridors of the typical repeating dormitory floors was found under carpet and non-asbestos floor tile.

Overall Condition Rating: Sig. Damaged Damaged X Good

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|--------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |

Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|------------------------------|-------------------------|-----------------------------|
| <u> </u> | <u> 8 </u> | <u> </u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-------------------|---------------------|---------------------|--------------------|
| <u> </u> | <u> </u> | <u> 4 </u> | <u> </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 11/03/11

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 9 **Type:** ST **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-9, Black Adhesive Under Stair Treads

Approximate Amount of Material (SF or LF): (Unknown)

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

Black roofing mastic around roof penetrations of the Dry Valve – Hose Stations and MCC buildings on the ground level of the LDA.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|------------------------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |


Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|------------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> </u> | <u> 8 </u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|------------------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> </u> | <u> 1 </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 6 **Type:** LDA **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-10, Black Decorative Trim Adhesive

Approximate Amount of Material (SF or LF): (Unknown)

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

Black adhesive was found around three doors in the first floor lobby areas. Efforts to better delineate this material indicate it to be isolated to this area. However, complete removal of the decorative trim may uncover hidden locations where this material was used.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|----------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |

Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|-----------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> </u> | <u>8</u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|--------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> </u> | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 1,7 **Type:** H,B **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-11, 9"x 9" Tan Floor Tile and Associated Black Mastic

Approximate Amount of Material (SF or LF): ~475 SF

Condition:

Percent Damage: >0% X <10% >10% <25% >25%

Extent of Damage : X Localized X Distributed

Type of Damage: X Deterioration Water X Physical

Description:

This 9"x9" floor tile is found in the basement corridors. Overall, the material showed signs of wear with localized damage and delaminating tiles at doorway thresholds.

Overall Condition Rating: Sig. Damaged Damaged X Good

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|-------------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> X </u> | <u> </u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |


Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|-----------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> 8 </u> | <u> </u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|--------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> 5 </u> | <u> </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 11 **Type:** R **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-12, Black Roofing Mastic

Approximate Amount of Material (SF or LF): ~4,500 SF (Includes entire roof system)

Condition:

Percent Damage: >0% X <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration X Water Physical

Description:

Black roofing mastic on flashing on the roof obtained positive results from samples collected by USC hazmat personnel. A visual inspection of the existing roof evidenced that this material was used on seams of rolled shingle roof as well..

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|-------------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | X | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | X | <u> </u> |
| Frequency of Air Erosion | <u> </u> | X | <u> </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | X | <u> </u> | <u> </u> |

Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|-----------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | 8 | <u> </u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|--------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | 2 | <u> </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 2,8 **Type:** B,SB **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-13, Valve and Flanged Connection Gasket Materials

Approximate Amount of Material (SF or LF): (Unknown)

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

Flanged connections at valves and joints of mechanical piping are assumed positive.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|------------------------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|----------------------|------------------------------|
| <u> </u> | <u> </u> | <u> 8 </u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-------------------|-------------------|-------------------|------------------------------|
| <u> </u> | <u> </u> | <u> </u> | <u> 1 </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  Date: 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 11 **Type:** R **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-14, Transite Curtain Wall Panels

Approximate Amount of Material (SF or LF): 40 Each

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration X Water Physical

Description:

Wall panels of the existing parapet walls on the roof appear to be transite. This material is assumed positive due to the destructive measures necessary to collect samples.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|------------------------------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> </u> |

Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|------------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> </u> | <u> 8 </u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|------------------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> </u> | <u> 1 </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 12 **Type:** K **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-15, Vinyl Flooring in Kitchenette

Approximate Amount of Material (SF or LF): 2,125 SF

Condition:

Percent Damage: >0% X <10% >10% <25% >25%

Extent of Damage: Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

The vinyl flooring and associated mastic is located in the kitchenette on floors 2 thru 18. This material was not included in our scope of work during the investigation and is therefore assumed positive.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|-----|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | X | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | X | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | X | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | X | <u> </u> |

Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|------------------------------|-------------------------|-----------------------------|
| <u> </u> | <u> </u> | 8 |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-------------------|---------------------|---------------------|--------------------|
| <u> </u> | <u> </u> | <u> </u> | 1 |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 13 **Type:** D **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-16, Caulking Around Interior Fan Coil in Dorm Rooms

Approximate Amount of Material (SF or LF): 1,450 LF

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

The caulking around interior fan coils is located in the dorm rooms on floors 2 thru 18. This material was not included in our scope of work during the investigation and is therefore assumed positive.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|----------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |

Overall Potential Disturbance Rating:

| | | |
|------------------------------|-------------------------|-----------------------------|
| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
| <u> </u> | <u> </u> | <u>8</u> |

Overall Hazard Rank #:

| | | | |
|-------------------|---------------------|---------------------|--------------------|
| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
| <u> </u> | <u> </u> | <u> </u> | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 13 **Type:** D **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI X **Surfacing** **Misc.**

Description: HA-17, Transite Panels on the Interior Wall Surrounding the Fan Coil

Approximate Amount of Material (SF or LF): 715 Each

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

The Transite panels are located on the interior wall surrounding the fan coils of each dorm room on floors 2 thru 18. This material is a known asbestos containing material and is assumed positive.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|------------------------------|------------------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u> X </u> | <u> X </u> |


Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|---------------------------|----------------------|------------------------------|
| <u> </u> | <u> </u> | <u> 8 </u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-------------------|-------------------|-------------------|------------------------------|
| <u> </u> | <u> </u> | <u> </u> | <u> 1 </u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12

PHYSICAL ASSESSMENT DATA SHEET

Building: South Tower Residence Hall Building

Functional Space Number: 13 **Type:** D **Location:** (See Homogeneous Area Plan)

Type of Suspect Material: TSI **Surfacing** X **Misc.**

Description: HA-18, 12" x 12" Floor Tile and Associated Mastic

Approximate Amount of Material (SF or LF): 1,750 SF

Condition:

Percent Damage: X >0% <10% >10% <25% >25%

Extent of Damage : Localized X Distributed

Type of Damage: X Deterioration Water Physical

Description:

The 12" x 12" floor tile and mastic is located in the dorm rooms of the 18th floor. These materials were not part of our original scope of work and were not sampled. Due to the lack of analytical data on these materials, they are assumed positive.

Overall Condition Rating: Sig. Damaged Damaged Good X

Potential for Disturbance:

| | High | Moderate | Low | Friable ACM |
|---------------------------------|-------------------|-------------------|----------|-------------------|
| Frequency of Potential Contact: | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Influence of Vibration | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Frequency of Air Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |
| Potential of Water Erosion | <u> </u> | <u> </u> | <u>X</u> | <u> </u> |

Overall Potential Disturbance Rating:

| Potential for Sig. Damage | Potential for Damage | Low Potential for Damage |
|------------------------------|-------------------------|-----------------------------|
| <u> </u> | <u> </u> | <u>8</u> |

Overall Hazard Rank #:

| Sig. Damaged | Pot. Sig. Damage | Potential Damage | Low Pot. Damage |
|-------------------|---------------------|---------------------|--------------------|
| <u> </u> | <u> </u> | <u> </u> | <u>1</u> |

Comments: Potential for Disturbance and Hazard Ranking assessed is based on current usage of the facility. Impending renovation activities may impact this material.

Signed:  **Date:** 01/06/12



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------|------------------------------------|--|--------------------------------|--------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST18-1 021107512-0001 | Baseboard Adhesive | Beige Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST18-2 021107512-0002 | Carpet Adhesive Only | Tan Non-Fibrous Heterogeneous | 1% Cellulose 1% Synthetic | 98% Non-fibrous (other) | None Detected |
| ST18-3 021107512-0003 | Pipe Mastic Only | Black Fibrous Heterogeneous | 1% Cellulose | 89% Non-fibrous (other) | 10% Chrysotile |
| ST18-4 021107512-0004 | Pipe Wrap on Fiberglass Insulation | Silver/Beige Fibrous Heterogeneous | 60% Cellulose | 40% Non-fibrous (other) | None Detected |
| ST18-5 021107512-0005 | Mudded Elbow | Gray Fibrous Heterogeneous | 20% Min. Wool 15% Cellulose | 62% Non-fibrous (other) | 3% Amosite |
| ST18-6 021107512-0006 | Joint Compound | White Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Inital Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: E5200.04/South Tower - USC/Asbestos Assessment

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | | Asbestos |
|-------------------------------------|---------------------------------------|---|--------------|---------------------------|--------------------------|---------------|
| | | | % | Fibrous | % Non-Fibrous | % Type |
| ST18-7 021107512-0007 | Textured Ceiling Panel | White/Beige Fibrous Heterogeneous | 40% | Cellulose | 40% Non-fibrous (other) | None Detected |
| ST18-8 021107512-0008 | Felt Vapor Barrier under Ceramic Tile | Brown/Black Fibrous Heterogeneous | 65% | Cellulose 1% Synthetic | 34% Non-fibrous (other) | None Detected |
| ST18-9 021107512-0009 | Fire Stop Caulking | Brown/Black Non-Fibrous Heterogeneous | <1% | Cellulose | 100% Non-fibrous (other) | None Detected |
| ST18-10 021107512-0010 | Fire Stop Caulking | Red Fibrous Heterogeneous | 5% | Glass | 95% Non-fibrous (other) | None Detected |
| ST18-11 021107512-0011 | HVAC Duct Mastic | Grayish Non-Fibrous Heterogeneous | 3% | Cellulose | 97% Non-fibrous (other) | None Detected |
| ST18-12-Sheetrock 021107512-0012 | Sheetrock/Joint Compound | Brown/Gray Fibrous Heterogeneous | 10% | Cellulose | 90% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---|---|---|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST18-12-Joint Compound 021107512-0012A | Sheetrock/Joint Compound | Tan Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |
| ST18-13 021107512-0013 | Stair Tread Adhesive | Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST18-14 021107512-0014 | Textured Ceiling Material on Concrete Ceiling | Grayish Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST17-15 021107512-0015 | Pipe Mastic on Fiberglass Insulation | Beige Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST16-16 021107512-0016 | Mud at Floor Penetrations | Gray Fibrous Heterogeneous | 20% Min. Wool | 77% Non-fibrous (other) | 3% Amosite |
| ST16-17 021107512-0017 | Mastic under Carpet Adhesive Only | Black Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------------------|-----------------------------------|--|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST16-18 021107512-0018 | Trowel Applied Surfacing Material | Tan Non-Fibrous Heterogeneous | 1% Cellulose | 99% Non-fibrous (other) | None Detected |
| ST16-19-Floor Tile 021107512-0019 | Floor Tile & Mastic Only | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| ST16-19-Mastic 021107512-0019A | Floor Tile & Mastic Only | Black Non-Fibrous Heterogeneous | | 92% Non-fibrous (other) | 8% Chrysotile |
| ST16-20 021107512-0020 | Gypsum Backer Board | Brown/Gray Fibrous Heterogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| ST18-21 021107512-0021 | Leveling Compound Only | White Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST15-22 021107512-0022 | Carpet Adhesive Only | Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------|------------------------|---|--------------------------------|--------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST15-23 021107512-0023 | Textured Ceiling Panel | White/Beige Fibrous Heterogeneous | 40% Cellulose 20% Min. Wool | 40% Non-fibrous (other) | None Detected |
| ST15-24 021107512-0024 | Baseboard Adhesive | Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST15-25 021107512-0025 | Mudded Elbow | Gray/Tan Fibrous Heterogeneous | 20% Min. Wool 15% Cellulose | 62% Non-fibrous (other) | 3% Amosite |
| ST15-26 021107512-0026 | HVAC Duct Mastic | Grayish Non-Fibrous Heterogeneous | 3% Cellulose | 97% Non-fibrous (other) | None Detected |
| ST15-27 021107512-0027 | Pipe Mastic Only | Black Fibrous Heterogeneous | | 90% Non-fibrous (other) | 10% Chrysotile |
| ST14-28 021107512-0028 | Fire Stop Caulking | Brown/Black Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------|---|---|-------------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST14-29 021107512-0029 | Fire Stop Caulking | Red/Black Fibrous Heterogeneous | 5% Glass | 95% Non-fibrous (other) | None Detected |
| ST14-30 021107512-0030 | Felt Vapor Barrier under Ceramic Tile | Brown/Black Fibrous Heterogeneous | 70% Cellulose | 30% Non-fibrous (other) | None Detected |
| ST14-31 021107512-0031 | Overspary on HVAC Duct | Grayish Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST14-32 021107512-0032 | Textured Ceiling Material on Concrete Ceiling | Beige Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST13-33 021107512-0033 | Mud at Floor Penetration | Gray Fibrous Heterogeneous | 20% Min. Wool 2% Cellulose | 75% Non-fibrous (other) | 3% Amosite |
| ST13-34 021107512-0034 | Pipe Mastic on Fiberglass Insulation | Beige Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Inital Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensboro@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------------------|--------------------------|---|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST13-35 021107512-0035 | Sheetrock/Joint Compound | Brown/Gray Fibrous Heterogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| ST13-36 021107512-0036 | Gypsum Backer Board | Brown/Gray Fibrous Heterogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| ST13-37-Floor Tile 021107512-0037 | Floor Tile & Mastic | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| ST13-37-Mastic 021107512-0037A | Floor Tile & Mastic | Black Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |
| ST13-38 021107512-0038 | Leveling Compound Only | White Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST11-39 021107512-0039 | Overspray on HVAC Duct | Beige/Grayish Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: E5200.04/South Tower - USC/Asbestos Assessment

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------|--|--|--------------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST9-40 021107512-0040 | Mudded Elbow | Gray/Tan Fibrous Heterogeneous | 20% Min. Wool 10% Cellulose | 67% Non-fibrous (other) | 3% Amosite |
| ST4-41 021107512-0041 | Mudded Elbow | Brown/Gray/Tan Fibrous Heterogeneous | 15% Min. Wool | 80% Non-fibrous (other) | 5% Chrysotile |
| ST7-44 021107512-0042 | Leveling Compound Only | White Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST6-45 021107512-0043 | Pipe Wrap on Fiberglass Insulation | Silver/Beige Fibrous Heterogeneous | 70% Cellulose | 30% Non-fibrous (other) | None Detected |
| ST5-46 021107512-0044 | Mastic Under Carpet Adhesive Only | Black Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |
| ST5-49 021107512-0045 | Stair Tread Adhesive | Tan Non-Fibrous Heterogeneous | 1% Cellulose 1% Synthetic | 98% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample # | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------|---|--|-------------------------------|--------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST5-50 021107512-0046 | Textured Ceiling Material on Concrete Ceiling | Grayish Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST5-51 021107512-0047 | Trowel Applied Surfacing Material | Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST4-53 021107512-0048 | Gypsum Backer Board | Brown/Gray Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| ST4-54 021107512-0049 | Pipe Mastic Only | Black Fibrous Heterogeneous | | 90% Non-fibrous (other) | 10% Chrysotile |
| ST4-57 021107512-0050 | Textured Ceiling panels | Tan/White Fibrous Heterogeneous | 55% Cellulose 5% Min. Wool | 40% Non-fibrous (other) | None Detected |
| ST3-58 021107512-0051 | Trowel Applied Surfacing Material | Gray/Tan Non-Fibrous Heterogeneous | 1% Cellulose | 99% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--|-------------------------------|---|-------------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST3-59-Yellow Mastic 021107512-0051A | Stair Tread Adhesive | Tan/Yellow Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST3-59-Black Mastic 021107512-0051B | Stair Tread Adhesive | Brown/Black Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |
| ST3-60 021107512-0052 | Mud at Floor Penetrations | Grayish Fibrous Heterogeneous | 15% Min. Wool 1% Cellulose | 81% Non-fibrous (other) | 3% Chrysotile |
| ST3-61 021107512-0053 | Overspray on Concrete Ceiling | Beige Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST3-62-Sheetrock 021107512-0054 | Sheetrock/joint Compound | Brown/Gray Fibrous Heterogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| ST3-62-Joint Compound 021107512-0054A | Sheetrock/joint Compound | Tan Non-Fibrous Heterogeneous | | 95% Non-fibrous (other) | 5% Chrysotile |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | | Asbestos |
|--------------------------|------------------------------------|--|--------------------------------|--------------------------|---------------|----------|
| | | | % Fibrous | % Non-Fibrous | % Type | |
| ST2-63 021107512-0055 | Pipe Wrap on Fiberglass Insulation | Black/Silver/Beige Fibrous Heterogeneous | 55% Cellulose 5% Glass | 40% Non-fibrous (other) | None Detected | |
| ST1-64 021107512-0056 | Smooth Textured Ceiling Panels | Gray/White Fibrous Heterogeneous | 90% Min. Wool | 10% Non-fibrous (other) | None Detected | |
| ST1-65 021107512-0057 | Smooth Textured Ceiling Panels | Gray/White Fibrous Heterogeneous | 90% Min. Wool | 10% Non-fibrous (other) | None Detected | |
| ST1-66 021107512-0058 | Smooth Textured Ceiling Panels | Gray/White Fibrous Heterogeneous | 90% Min. Wool <1% Cellulose | 10% Non-fibrous (other) | None Detected | |
| ST1-67 021107512-0059 | Baseboard Adhesive | Tan Non-Fibrous Heterogeneous | <1% Synthetic | 100% Non-fibrous (other) | None Detected | |
| ST1-68 021107512-0060 | Baseboard Adhesive | Tan/Gold Non-Fibrous Heterogeneous | <1% Synthetic <1% Cellulose | 100% Non-fibrous (other) | None Detected | |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------|-----------------------------------|---|---------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST1-70 021107512-0061 | Baseboard Adhesive | Brown Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST1-71 021107512-0062 | Baseboard Adhesive | Brown/Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| ST1-74 021107512-0063 | Fiberglass Duct Board Gutter Skin | Black Non-Fibrous Heterogeneous | 2% Cellulose 3% Glass | 95% Non-fibrous (other) | None Detected |
| ST1-75 021107512-0064 | Fiberglass Duct Board Gutter Skin | Brown/Black Fibrous Heterogeneous | 10% Cellulose 3% Glass | 87% Non-fibrous (other) | None Detected |
| ST1-76 021107512-0065 | Fiberglass Duct Board Gutter Skin | Black/Gold Fibrous Heterogeneous | 8% Cellulose 8% Glass | 84% Non-fibrous (other) | None Detected |
| ST1-77 021107512-0066 | Mudded Elbow | Gray/Tan Fibrous Heterogeneous | 20% Min. Wool | 75% Non-fibrous (other) | 5% Chrysotile |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborofab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/27/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------------------|------------------------------------|---|---------------------------|-------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| ST1-78 021107512-0067 | Adhesive on Door Trim | Black Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| ST1-79 021107512-0068 | Adhesive on Door Trim | Brown/Black Fibrous Heterogeneous | 1% Cellulose | 94% Non-fibrous (other) | 5% Chrysotile |
| ST1-82 021107512-0069 | Mudded Elbow | Black Fibrous Heterogeneous | | 90% Non-fibrous (other) | 10% Chrysotile |
| ST1-83-Black Mastic 021107512-0070 | Pipe Wrap on Fiberglass Insulation | Black Fibrous Heterogeneous | | 90% Non-fibrous (other) | 10% Chrysotile |
| ST1-83-Pipe Wrap 021107512-0070A | Pipe Wrap on Fiberglass Insulation | Gray/Silver/Beige Fibrous Heterogeneous | 30% Cellulose 5% Glass | 65% Non-fibrous (other) | None Detected |

Report Amended: 01/03/2012 11:14:00 Replaces the Initial Report 12/27/2011 08:54:34. Reason Code: Data Entry-Change to Location

Analyst(s)

Kristie Elliott (72)
Scott Combs (5)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
Customer PO: E5200.03
Received: 12/21/11 10:30 PM
EMSL Order: 021107512

EMSL Proj:
Analysis Date: 12/28/2011

**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM
via EPA/600/R-93/116 Section 2.5.5.1**

| SAMPLE ID | DESCRIPTION | APPEARANCE | % MATRIX MATERIAL | % NON-ASBESTOS FIBERS | ASBESTOS TYPES |
|--|-------------|--|-------------------|-----------------------|----------------------|
| ST1-42-Yellow Mastic 021107512-0071 | | Yellow Non-Fibrous Heterogeneous | 99.8 | None | <0.25% Chrysotile |
| ST7-43-Floor Tile 021107512-0072 | | Beige Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST5-47 021107512-0073 | | Red Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST5-48 021107512-0074 | | Brown Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST5-52 021107512-0075 | | Gray Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST4-55 021107512-0076 | | Brown Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST4-56 021107512-0077 | | Beige Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |

Initial report from 12/27/2011 08:54:34

Analyst(s)

Stephen Bennett (11)

Stephen Bennett, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC



EMSL Analytical, Inc.
 706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
 Project: **E5200.04/South Tower - USC/Asbestos Assessment**

Customer ID: FMEC62
 Customer PO: E5200.03
 Received: 12/21/11 10:30 PM
 EMSL Order: 021107512


EMSL Proj:
 Analysis Date: 12/28/2011

**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM
 via EPA/600/R-93/116 Section 2.5.5.1**

| SAMPLE ID | DESCRIPTION | APPEARANCE | % MATRIX MATERIAL | % NON-ASBESTOS FIBERS | ASBESTOS TYPES |
|-------------------------------------|-------------|---|-------------------|-----------------------|----------------------|
| ST4-59- Mastic 021107512-0078 | Yellow/Tan | Tan /Yellow Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST1-69 021107512-0079 | | Tan Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST1-72 021107512-0080 | | Brown /Tan Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| ST16-81 021107512-0081 | | Tan Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |

Initial report from 12/27/2011 08:54:34

Analyst(s)
 Stephen Bennett (11)


 Stephen Bennett, Laboratory Manager
 or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
 Samples analyzed by EMSL Analytical, Inc. Kernersville, NC

Chain of Custody

7512

EMSL Analytical, Inc.
706 Gralin Street
Kernersville, NC 27284

Asbestos Lab Services

Phone: (336) 992-1025
Fax: (336) 992-4175
<http://www.emsl.com>

Please print all information legibly.

| | | | |
|-----------------------------|--|-----------------------|--------------------------|
| Company: | F&ME Consultants | Bill To: | F&ME Consultants |
| Address 1: | 3112 Devine Street | Address 1: | P.O. Box 5855 |
| Address 2: | | Address 2: | |
| City/State: | Columbia, South Carolina | City/State: | Columbia, South Carolina |
| Zip/Post Code: | 29205 | Zip/Post Code: | 29250 |
| Country: | USA | Country: | USA |
| Contact Name: | Glynn Ellen | Att: | Jim Kelleher |
| Phone: | 803 254-4540 | Phone: | 803 777-1208 |
| Fax: | 803 254-4542 | Fax: | 803 777-1028 |
| Email: | glynn@fmecon.com | Email: | jkelleher@fmecon.com |
| EMSL Rep: | Jason McDonald | P.O. Number: | E5200.04 |
| Project Name/Number: | E5200.04/South Tower - USC/Asbestos Assessment | | |

| MATRIX | | | TURNAROUND | | | |
|--|---|------------------------------------|---|---|---|---|
| <input type="checkbox"/> Air | <input type="checkbox"/> Soil | <input type="checkbox"/> Micro-Vac | <input type="checkbox"/> 3 Hours | <input type="checkbox"/> 6 Hours | <input type="checkbox"/> Same Day or 12 Hours* | <input type="checkbox"/> 24 Hours (1day) |
| <input checked="" type="checkbox"/> Bulk | <input type="checkbox"/> Drinking Water | | <input type="checkbox"/> 48 Hours (2 days) | <input checked="" type="checkbox"/> 72 Hours (3 days) | <input checked="" type="checkbox"/> 96 Hours (4 days) | <input type="checkbox"/> 120 Hours (5 days) |
| <input type="checkbox"/> Wipe | <input type="checkbox"/> Wastewater | | <input type="checkbox"/> 144+ hours (6-10 days) | | | |

TEM AIR, 3 hours, 6 hours, Please call ahead to schedule. There is a premium charge for 3-hour tat, please call 1-800-220-3675 for price prior to sending samples. You will be asked to sign an authorization form for this service.

*12 hours (must arrive by 11:00a.m. Mon - Fri), Please Refer to Price Quote

| PCM - Air | TEM Air | TEM WATER |
|---|---|---|
| <input type="checkbox"/> NIOSH 7400(A) Issue 2: August 1994 | <input type="checkbox"/> AHERA 40 CFR, Part 763 Subpart E | <input type="checkbox"/> EPA 100.1 |
| <input type="checkbox"/> OSHA w/TWA | <input type="checkbox"/> NIOSH 7402 | <input type="checkbox"/> EPA 100.2 |
| <input type="checkbox"/> Other: | <input type="checkbox"/> EPA Level II | <input type="checkbox"/> NYS 198.2 |
| PLM - Bulk | TEM BULK | TEM Microvac/Wipe |
| <input checked="" type="checkbox"/> EPA 600/R-93/116 | <input type="checkbox"/> Drop Mount (Qualitative) | <input type="checkbox"/> ASTM D 5755-95 (quantitative method) |
| <input type="checkbox"/> EPA Point Count | <input type="checkbox"/> Chatfield SOP - 1988-02 | <input type="checkbox"/> Wipe Qualitative |
| <input type="checkbox"/> NY Stratified Point Count | <input checked="" type="checkbox"/> TEM NOB (Gravimetric) NYS 198.4 | |
| <input type="checkbox"/> PLM NOB (Gravimetric) NYS 198.1 | <input type="checkbox"/> EMSL Standard Addition: | XRD |
| <input type="checkbox"/> NIOSH 9002: | | <input type="checkbox"/> Asbestos |
| <input type="checkbox"/> EMSL Standard Addition: | PLM Soil | <input type="checkbox"/> Silica NIOSH 7500 |
| SEM Air or Bulk | <input type="checkbox"/> EPA Protocol Qualitative | |
| <input type="checkbox"/> Qualitative | <input type="checkbox"/> EPA Protocol Quantitative | OTHER |
| <input type="checkbox"/> Quantitative | <input type="checkbox"/> EMSL MSD 9000 Method fibers/gram | <input type="checkbox"/> |

7512

Chain of Custody

Asbestos Lab Services

EMSL Analytical, Inc.
706 Gralin Street
Kernersville, NC 27284

Phone: (336) 992-1025
Fax: (336) 992-4175
<http://www.emsl.com>

Please print all information legibly.

Client Sample # ST18-1 to ST1-83

Total Samples #: 83

Relinquished: Mike Mincey *Mike Mincey* Date: 12/20/11

Time: 17:00

Received: *MV* Date: 12/21/11

Time: 10:30

Relinquished: _____ Date: _____

Time: _____

Received: _____ Date: _____

Time: _____

| SAMPLE NUMBER | SAMPLE DESCRIPTION/LOCATION | VOLUME (if applicable) |
|---|--|------------------------|
| NOTE: RUN TEM ONLY ON SAMPLES DESIGNATED AND PLM ON SAMPLES NOT DESIGNATED TEM. SOUTH CAROLINA GUIDELINES. | | |
| ST18-1 | Baseboard Adhesive (Cream) | |
| ST18-2 | Carpet Adhesive (Yellow) Only | |
| ST18-3 | Black Pipe Mastic Only | |
| ST18-4 | Pipe Wrap on Fiberglass Insulation | |
| ST18-5 | Mudded Elbow | |
| ST18-6 | Joint Compound | |
| ST18-7 | 2' x 2' Textured Ceiling Panel | |
| ST18-8 | Felt Vapor Barrier Under Ceramic Tile | |
| ST18-9 | Brown Fire Stop Caulking | |
| ST18-10 | Red Fire Stop Caulking | |
| ST18-11 | Lite Gray HVAC Duct Mastic | |
| ST18-12 | Sheetrock/Joint Compound | |
| ST18-13 | Stair Tread Adhesive (Yellow) | |
| ST18-14 | Textured Ceiling Material on Concrete Ceiling | |
| ST17-15 | Crème Pipe Mastic on Fiberglass Insulation Only | |
| ST16-16 | Mud at Floor Penetrations (Chase) | |
| ST16-17 | Black Mastic Under Carpet (Yellow) Adhesive Only | |
| ST16-18 | Trowel Applied Surfacing Material (Brown) | |
| ST16-19 | 12" x 12" White Floor Tile & Black Mastic Only | |
| ST16-20 | Gypsum Backer Board | |
| ST18-21 | White Leveling Compound Only | |
| ST15-22 | Carpet Adhesive (Yellow) Only | |
| ST15-23 | 2' x 2' Textured Ceiling Panel | |
| ST15-24 | Baseboard Adhesive (Cream) | |

| | | |
|---------|---|------------------------------|
| ST15-25 | Mudded Elbow | |
| ST15-26 | Lite Gray HVAC Duct Mastic | |
| ST15-27 | Black Pipe Mastic Only | |
| ST14-28 | Brown Fire Stop Caulking | |
| ST14-29 | Red Fire Stop Caulking | |
| ST14-30 | Felt Vapor Barrier Under Ceramic Tile | |
| ST14-31 | Overspray on HVAC Duct (Chase) | |
| ST14-32 | Textured Ceiling Material on Concrete Ceiling | |
| ST13-33 | Mud at Floor Penetrations (Chase) | |
| ST13-34 | Crème Pipe Mastic on Fiberglass Insulation Only | |
| ST13-35 | Sheetrock/Joint Compound | |
| ST13-36 | Gypsum Backer Board | |
| ST13-37 | 12" x 12" White Floor Tile & Black Mastic Only | |
| ST13-38 | White Leveling Compound Only | |
| ST11-39 | Overspray on HVAC Duct (Chase) | |
| ST9-40 | Mudded Elbow (Stairwell) | |
| ST4-41 | Mudded Elbow (Custodial Closet) | |
| ST8-42 | Carpet Adhesive (Yellow) Only | TEM Only if 2 & 22 are Neg. |
| ST7-43 | 12" x 12" White Floor Tile & Black Mastic Only | TEM Only if 19 & 37 are Neg. |
| ST7-44 | White Leveling Compound Only | |
| ST6-45 | Pipe Wrap on Fiberglass Insulation | |
| ST5-46 | Black Mastic Under Carpet (Yellow) Adhesive Only | |
| ST5-47 | Red Fire Stop Caulking | TEM Only if 10 & 29 are Neg. |
| ST5-48 | Brown Fire Stop Caulking | TEM Only if 9 & 28 are Neg. |
| ST5-49 | Stair Tread Adhesive (Yellow) | |
| ST5-50 | Textured Ceiling Material on Concrete Ceiling | |
| ST5-51 | Trowel Applied Surfacing Material (Brown) | |
| ST5-52 | Lite Gray HVAC Duct Mastic | TEM Only if 11 & 26 are Neg. |
| ST4-53 | Gypsum Backer Board | |
| ST4-54 | Black Pipe Mastic Only | |
| ST4-55 | Felt Vapor Barrier Under Ceramic Tile | TEM Only if 8 & 30 are Neg. |
| ST4-56 | Baseboard Adhesive (Cream) | TEM Only if 1 & 24 are Neg. |
| ST4-57 | 2' x 2' Textured Ceiling Panels | |
| ST3-58 | Trowel Applied Surfacing Material (Brown) | |
| ST3-59 | Stair Tread Adhesive (Yellow & Black) | TEM Both |
| ST3-60 | Mud at Floor Penetrations (Chase) | |
| ST3-61 | Overspray on Concrete Ceiling of Chase | |
| ST3-62 | Sheetrock/Joint Compound | |
| ST2-63 | Pipe Wrap on Fiberglass Insulation | |
| ST1-64 | 2' x 2' Smooth Textured Ceiling Panels (Recessed) | |
| ST1-65 | 2' x 2' Smooth Textured Ceiling Panels (Recessed) | |



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

EMSL Proj:
Analysis Date: 1/6/2012

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | | Asbestos |
|-------------------------------------|--|---|--------------|---|-------------------------|------------------------------|
| | | | % | Fibrous | % Non-Fibrous | % Type |
| STB-84 021200053-0001 | Mudded Elbow | Gray/Tan Fibrous Heterogeneous | 40% | Min. Wool 2% Cellulose 1% Synthetic | 54% Non-fibrous (other) | 3% Chrysotile |
| STB-85 021200053-0002 | Pipe Wrap on Fiberglass Insulation | Tan/Black/Silver/Y ellow Fibrous Heterogeneous | 20% | Cellulose 10% Glass 1% Synthetic | 69% Non-fibrous (other) | None Detected |
| STB-86 021200053-0003 | Mudded Elbow | Gray Fibrous Heterogeneous | 20% | Min. Wool 5% Cellulose | 72% Non-fibrous (other) | 3% Chrysotile |
| STB-87-Floor Tile 021200053-0004 | Floor Tile & Mastic | Brown/Tan Non-Fibrous Heterogeneous | | | 95% Non-fibrous (other) | 5% Chrysotile |
| STB-87-Mastic 021200053-0004A | Floor Tile & Mastic | Black Fibrous Heterogeneous | 2% | Cellulose | 88% Non-fibrous (other) | 10% Chrysotile |
| STB-88 021200053-0005 | Floor Tile & Mastic | | | | | Stop Positive (Not Analyzed) |

Initial report from 01/06/2012 15:03:20

Analyst(s)

Kristie Elliott (10)
Scott Combs (22)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

EMSL Proj:
Analysis Date: 1/6/2012

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------|--|--|-------------------------------|-------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| STB-90 021200053-0006 | Overspray on HVAC Duct | Gray Fibrous Heterogeneous | 3% Cellulose 1% Synthetic | 88% Non-fibrous (other) | 8% Chrysotile |
| STB-91 021200053-0007 | Heavy Textured Ceiling Panels | Gray/White Fibrous Heterogeneous | 75% Min. Wool 1% Cellulose | 24% Non-fibrous (other) | None Detected |
| STB-92 021200053-0008 | Heavy Textured Ceiling Panels | Gray/White Fibrous Heterogeneous | 75% Min. Wool 1% Cellulose | 24% Non-fibrous (other) | None Detected |
| STB-93 021200053-0009 | Heavy Textured Ceiling Panels | Gray/Beige Fibrous Heterogeneous | 75% Min. Wool 1% Cellulose | 24% Non-fibrous (other) | None Detected |
| STB-94 021200053-0010 | Pipe Wrap on Fiberglass Insulation | Tan/Black/Silver Fibrous Heterogeneous | 45% Cellulose 10% Glass | 45% Non-fibrous (other) | None Detected |
| STB-95 021200053-0011 | Canvas Pipe Wrap | Beige/Cream Fibrous Heterogeneous | 70% Cellulose | 30% Non-fibrous (other) | None Detected |

Initial report from 01/06/2012 15:03:20

Analyst(s)

Kristie Elliott (10)
Scott Combs (22)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

EMSL Proj:
Analysis Date: 1/6/2012

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | | Asbestos |
|----------------------------|------------------|--|------------------|---------------------------------|-------------------------|---------------|
| | | | % | Fibrous | % Non-Fibrous | % Type |
| STB-96 021200053-0012 | Canvas Pipe Wrap | Beige/Cream Non-Fibrous Heterogeneous | 70% | Cellulose | 30% Non-fibrous (other) | None Detected |
| STB-97 021200053-0013 | Canvas Pipe Wrap | Beige Fibrous Heterogeneous | 70% | Cellulose | 30% Non-fibrous (other) | None Detected |
| STSB-98 021200053-0014 | HVAC Duct Wrap | Tan/White/Silver Fibrous Heterogeneous | 40% 15% 1% | Cellulose Glass Synthetic | 44% Non-fibrous (other) | None Detected |
| STSB-99 021200053-0015 | HVAC Duct Wrap | Gray/White/Silver Fibrous Heterogeneous | 50% 5% 1% | Cellulose Glass Synthetic | 44% Non-fibrous (other) | None Detected |
| STSB-100 021200053-0016 | HVAC Duct Wrap | White/Beige Fibrous Heterogeneous | 55% 1% 1% | Cellulose Synthetic Glass | 43% Non-fibrous (other) | None Detected |
| STSB-101 021200053-0017 | Canvas Pipe Wrap | Gray/Silver/Yellow Fibrous Heterogeneous | 80% 5% 1% | Cellulose Glass Synthetic | 14% Non-fibrous (other) | None Detected |

Initial report from 01/06/2012 15:03:20

Analyst(s)

Kristie Elliott (10)
Scott Combs (22)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

EMSL Proj:
Analysis Date: 1/6/2012


**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | | Asbestos |
|--|----------------------------|--|--------------|---------------------------------------|--------------------------|---------------|
| | | | % | Fibrous | % Non-Fibrous | % Type |
| STSB-102 021200053-0018 | Canvas Pipe Wrap | Gray/Silver/Yellow Fibrous Heterogeneous | 80% | Cellulose 5% Glass 1% Synthetic | 14% Non-fibrous (other) | None Detected |
| STSB-103 021200053-0019 | Canvas Pipe Wrap | Beige Fibrous Heterogeneous | 75% | Cellulose 5% Glass | 20% Non-fibrous (other) | None Detected |
| STSB-104-Green Board 021200053-0020 | Green Board/Joint Compound | Brown/Gray/Green Fibrous Heterogeneous | 5% | Cellulose 1% Glass | 94% Non-fibrous (other) | None Detected |
| STSB-104-Joint Compound 021200053-0020A | Green Board/Joint Compound | White Non-Fibrous Heterogeneous | <1% | Cellulose | 100% Non-fibrous (other) | None Detected |
| STSB-105-Green Board 021200053-0021 | Green Board/Joint Compound | Brown/Gray/Green Fibrous Heterogeneous | 5% | Cellulose 1% Glass | 94% Non-fibrous (other) | None Detected |
| STSB-105-Joint Compound 021200053-0021A | Green Board/Joint Compound | White Non-Fibrous Heterogeneous | <1% | Cellulose | 100% Non-fibrous (other) | None Detected |

Initial report from 01/06/2012 15:03:20

Analyst(s)

Kristie Elliott (10)
Scott Combs (22)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen
F & ME Consultants
3112 Divine Street**

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

EMSL Proj:
Analysis Date: 1/6/2012

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--|----------------------------|---------------------------------------|--------------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| STSB-106-Green Board 021200053-0022 | Green Board/Joint Compound | Brown/Gray Fibrous Heterogeneous | 10% Cellulose 1% Glass | 89% Non-fibrous (other) | None Detected |
| STSB-106-Joint Compound 021200053-0022A | Green Board/Joint Compound | White Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| STSB-107 021200053-0023 | Unknown Debris | Gray/Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| STSB-108 021200053-0024 | Unknown Debris | Gray/Tan Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| STSB-109 021200053-0025 | Unknown Debris | Gray/Tan Non-Fibrous Heterogeneous | <1% Synthetic <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| STB-110-Floor Tile 021200053-0026 | Floor Tile & Mastic | Tan Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |

Initial report from 01/06/2012 15:03:20

Analyst(s) _____

Kristie Elliott (10)
Scott Combs (22)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
Project: **E5200.04/South Tower-USC/Asbestos Assessment of
Basement /Sub-basement and Penthouse**

Customer ID: FMEC62
Customer PO: E5200.04
Received: 01/05/12 10:15 AM
EMSL Order: 021200053

EMSL Proj:
Analysis Date: 1/6/2012

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA
600/M4-82-020 Method(s) using Polarized Light Microscopy**

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------------------|---------------------|--|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| STB-110-Mastic 021200053-0026A | Floor Tile & Mastic | Tan/Yellow/Grayish Non-Fibrous Heterogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| STB-111-Floor Tile 021200053-0027 | Floor Tile & Mastic | Tan Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| STB-111-Mastic 021200053-0027A | Floor Tile & Mastic | Tan Non-Fibrous Heterogeneous | 1% Cellulose | 99% Non-fibrous (other) | None Detected |

Initial report from 01/06/2012 15:03:20

Analyst(s)

Kristie Elliott (10)
Scott Combs (22)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
 706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Glynn Ellen**
F & ME Consultants
3112 Divine Street

Customer ID: FMEC62
 Customer PO: E5200.04
 Received: 01/05/12 10:15 AM
 EMSL Order: 021200053

Columbia, SC 29205

Fax: (803) 254-4542 Phone: (803) 254-4540
 Project: **E5200.04/South Tower-USC/Asbestos Assessment of
 Basement /Sub-basement and Penthouse**

EMSL Proj:
 Analysis Date: 1/9/2012


**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM
 via EPA/600/R-93/116 Section 2.5.5.1**

| SAMPLE ID | DESCRIPTION | APPEARANCE | % MATRIX MATERIAL | % NON-ASBESTOS FIBERS | ASBESTOS TYPES |
|--------------------------------------|---------------------|-------------------------------------|-------------------|-----------------------|----------------------|
| STB-112-Floor Tile 021200053-0028 | Floor Tile & Mastic | Tan Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| STB-112-Mastic 021200053-0029 | Floor Tile & Mastic | Tan Non-Fibrous Heterogeneous | 99.7 | None | 0.32% Chrysotile |

Initial report from 01/06/2012 15:03:20

Analyst(s)

 Stephen Bennett (2)



 Stephen Bennett, Laboratory Manager
 or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
 Samples analyzed by EMSL Analytical, Inc. Kernersville, NC

Chain of Custody **0053**

EMSL Analytical, Inc.
706 Gralin Street
Kernersville, NC 27284

Asbestos Lab Services

Phone: (336) 992-1025
Fax: (336) 992-4175
<http://www.emsl.com>

Please print all information legibly.

| | | | |
|----------------------|---|----------------|--------------------------|
| Company: | F&ME Consultants | Bill To: | F&ME Consultants |
| Address 1: | 3112 Devine Street | Address 1: | P.O. Box 5855 |
| Address 2: | | Address 2: | |
| City/State: | Columbia, South Carolina | City/State: | Columbia, South Carolina |
| Zip/Post Code: | 29205 | Zip/Post Code: | 29250 |
| Country: | USA | Country: | USA |
| Contact Name: | Glynn Ellen | Att: | Jim Kelleher |
| Phone: | 803 254-4540 | Phone: | 803 777-1208 |
| Fax: | 803 254-4542 | Fax: | 803 777-1028 |
| Email: | glynn@fmecol.com | Email: | jkelleher@fmecol.com |
| EMSL Rep: | Jason McDonald | P.O. Number: | B5200.04 |
| Project Name/Number: | B5200.04/South Tower - USC/Asbestos Assessment of Basement/Sub-basement and Penthouse | | |


| MATRIX | | | TURNAROUND | | | |
|--|---|------------------------------------|---|---|---|---|
| <input type="checkbox"/> Air | <input type="checkbox"/> Soil | <input type="checkbox"/> Micro-Vac | <input type="checkbox"/> 3 Hours | <input type="checkbox"/> 6 Hours | <input type="checkbox"/> Same Day or 12 Hours* | <input type="checkbox"/> 24 Hours (1day) |
| <input checked="" type="checkbox"/> Bulk | <input type="checkbox"/> Drinking Water | | <input type="checkbox"/> 48 Hours (2 days) | <input checked="" type="checkbox"/> 72 Hours (3 days) | <input checked="" type="checkbox"/> 96 Hours (4 days) | <input type="checkbox"/> 120 Hours (5 days) |
| <input type="checkbox"/> Wipe | <input type="checkbox"/> Wastewater | | <input type="checkbox"/> 144+ hours (6-10 days) | | | |

TEM AIR, 3 hours, 6 hours, Please call ahead to schedule. There is a premium charge for 3-hour tat, please call 1-800-220-3675 for price prior to sending samples. You will be asked to sign an authorization form for this service.

*12 hours (must arrive by 11:00a.m. Mon -Fri.), Please Refer to Price Quote

| PCM - Air | TEM Air | TEM WATER |
|---|---|---|
| <input type="checkbox"/> NIOSH 7400(A) Issue 2: August 1994 | <input type="checkbox"/> AHERA 40 CFR, Part 763 Subpart E | <input type="checkbox"/> EPA 100.1 |
| <input type="checkbox"/> OSHA w/TWA | <input type="checkbox"/> NIOSH 7402 | <input type="checkbox"/> EPA 100.2 |
| <input type="checkbox"/> Other: | <input type="checkbox"/> EPA Level II | <input type="checkbox"/> NYS 198.2 |
| PLM - Bulk | TEM BULK | TEM Microvac/Wipe |
| <input checked="" type="checkbox"/> EPA 600/R-93/116 | <input type="checkbox"/> Drop Mount (Qualitative) | <input type="checkbox"/> ASTM D 5755-95 (quantative method) |
| <input type="checkbox"/> EPA Point Count | <input type="checkbox"/> Chatfield SOP - 1988-02 | <input type="checkbox"/> Wipe Qualitative |
| <input type="checkbox"/> NY Stratified Point Count | <input checked="" type="checkbox"/> TEM NOB (Gravimetric) NYS 198.4 | |
| <input type="checkbox"/> PLM NOB (Gravimetric) NYS 198.1 | <input type="checkbox"/> EMSL Standard Addition: | XRD |
| <input type="checkbox"/> NIOSH 9002: | | <input type="checkbox"/> Asbestos |
| <input type="checkbox"/> EMSL Standard Addition: | PLM Soil | <input type="checkbox"/> Silica NIOSH 7500 |
| SEM Air or Bulk | <input type="checkbox"/> EPA Protocol Qualitative | |
| <input type="checkbox"/> Qualitative | <input type="checkbox"/> EPA Protocol Quantitative | OTHER |
| <input type="checkbox"/> Quantitative | <input type="checkbox"/> EMSL MSD 9000 Method fibers/gram | <input type="checkbox"/> |

0053



Chain of Custody

Asbestos Lab Services

EMSL Analytical, Inc.
706 Gralin Street
Kernersville, NC 27284

Phone: (336) 992-1025
Fax: (336) 992-4175
<http://www.emsl.com>

Please print all information legibly.

Client Sample # STB-84 TO STB-112

Total Samples #: 29

Relinquished: Mike Mincey *Mike Mincey* Date: 01/04/12

Time: 17:00

Received: *mv* Date: 1/5/12

Time: 10:15

Relinquished: _____ Date: _____

Time: _____

Received: _____ Date: _____

Time: _____

| SAMPLE NUMBER | SAMPLE DESCRIPTION/LOCATION | VOLUME (if applicable) |
|---|---|------------------------|
| NOTE: RUN TEM ONLY ON SAMPLES DESIGNATED AND PLM ON SAMPLES NOT DESIGNATED TEM. SOUTH CAROLINA GUIDELINES. | | |
| STB-84 | Mudded Elbow | |
| STB-85 | Pipe Wrap on Fiberglass Insulation | |
| STB-86 | Mudded Elbow | |
| STB-87 | 9" x 9" Tan Floor Tile & Mastic | |
| STB-88 | 9" x 9" Tan Floor Tile & Mastic | |
| STB-89 | 9" x 9" Tan Floor Tile & Mastic | TEM |
| STB-90 | Overspray on HVAC Duct (Bathroom) | |
| STB-91 | 12" x 12" Heavy Textured Ceiling Panels | |
| STB-92 | 12" x 12" Heavy Textured Ceiling Panels | |
| STB-93 | 12" x 12" Heavy Textured Ceiling Panels | |
| STB-94 | Pipe Wrap on Fiberglass Insulation | |
| STB-95 | Canvas Pipe Wrap | |
| STB-96 | Canvas Pipe Wrap | |
| STB-97 | Canvas Pipe Wrap | |
| STSB-98 | HVAC Duct Wrap | |
| STSB-99 | HVAC Duct Wrap | |
| STSB-100 | HVAC Duct Wrap | |
| STSB-101 | Canvas Pipe Wrap | |
| STSB-102 | Canvas Pipe Wrap | |
| STSB-103 | Canvas Pipe Wrap | |
| STSB-104 | Green Board/Joint Compound | |
| STSB-105 | Green Board/Joint Compound | |
| STSB-106 | Green Board/Joint Compound | |
| STSB-107 | Unknown Debris | |



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **122 South Towers**

Customer ID: UNSC62
Customer PO:
Received: 02/16/11 10:00 AM
EMSL Order: 021101023
EMSL Proj:
Analysis Date: 2/16/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|--------------------------|---|---------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 1-Skim Coat 021101023-0001 | Plaster Ceiling Material | White/Beige Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 1-Rough Coat 021101023-0001A | Plaster Ceiling Material | Gray/Tan Non-Fibrous Heterogeneous | <1% Hair <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| 2-Skim Coat 021101023-0002 | Plaster Ceiling Material | White/Beige Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2-Rough Coat 021101023-0002A | Plaster Ceiling Material | Gray/Tan Non-Fibrous Heterogeneous | <1% Hair <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| 3-Rough Coat 021101023-0003 | Plaster Ceiling Material | Beige Fibrous Heterogeneous | 1% Hair <1% Cellulose | 99% Non-fibrous (other) | None Detected |
| 3-Finish Coat 021101023-0003A | Plaster Ceiling Material | White/Beige Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Initial report from 02/16/2011 17:24:46

Analyst(s)

Stephen Bennett (2)
Scott Combs (4)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321

1023



Chain of Custody EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX: (856) 786-5974

EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

South Towers

| | | | |
|---|---------------------------|---|----------|
| Company: <u>USC</u> | | EMSL-Bill to: <input type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments** | |
| Street: <u>743 Grand St</u> | | Third Party Billing requires written authorization from third party | |
| City: <u>OLA</u> | State/Province: <u>SC</u> | Zip/Postal Code: | Country: |
| Report To (Name): <u>D Washington</u> | | Fax #: | |
| Telephone #: | | Email Address: | |
| Project Name/Number: | | | |
| Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Purchase Order: <input type="checkbox"/> U.S. State Samples Taken: <input type="checkbox"/> | | | |

Turnaround Time (TAT) Options* - Please Check

3 Hour 6 Hour 24 Hour 48 Hour 72 Hour 96 Hour 1 Week 2 Week

*For RUSH TAT's Please Call Ahead to Confirm Lab Hours and Availability. Not all TAT options are valid for every test. Materials Science and IAQ TATs are in Business Days rather than Hours (i.e. 24 Hour = End of Next Business Day)

Asbestos

| | | |
|---|--|--|
| PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ 8hr. TWA TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA ONLY) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Water Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking | PLM - Bulk <input checked="" type="checkbox"/> PLM EPA 600/R-99/116 <input type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> NYS 198.1 (friable-NY) <input type="checkbox"/> NYS 198.6 (non-friable-NY) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/ Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) | TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> EPA Reg. 1 Screening Protocol (Qualitative) Other: |
|---|--|--|

| | |
|---|---|
| Lead (Pb) | Materials Science |
| Flame Atomic Absorption <input type="checkbox"/> Chips SW846-7000B or AOAC 974.02 <input type="checkbox"/> Soil SW846-7000B/7420 <input type="checkbox"/> Air NIOSH 7082 <input type="checkbox"/> Wastewater SM3111B or SW846-7000B/7420 <input type="checkbox"/> ASTM Wipe SW846-7000B/7420 <input type="checkbox"/> non ASTM Wipe SW846-7000B/7420 <input type="checkbox"/> TCLP SW846-1311/7420/SM 3111B Graphite Furnace Atomic Absorption <input type="checkbox"/> Soil SW846-7421 <input type="checkbox"/> Wastewater EPA 200.9 <input type="checkbox"/> Air NIOSH 7105 <input type="checkbox"/> Drinking Water EPA 200.9 | <input type="checkbox"/> Common Particle ID (large particles) <input type="checkbox"/> Full Particle ID (environmental dust) <input type="checkbox"/> Basic Material ID (solids) <input type="checkbox"/> Advanced Material ID <input type="checkbox"/> Physical Testing (Tensile, Compression) <input type="checkbox"/> Combustion-by-products (soot, char, etc.) <input type="checkbox"/> X-Ray Fluorescence (elem. analysis) <input type="checkbox"/> X-Ray Diffraction (Crystalline Part.) <input type="checkbox"/> MMVF's (Fibrous glass, RCF's) <input type="checkbox"/> Particle Size (sieve/microscopy/laser) <input type="checkbox"/> Combustible Dust <input type="checkbox"/> Petrographic Examination Other: |

Microbiology

| | | |
|---|--|---|
| Wipe and Bulk Samples <input type="checkbox"/> Mold & Fungi - Direct Examination <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi Culture (Genus & Species) <input type="checkbox"/> Bacterial Count & ID (Up to Three Types) <input type="checkbox"/> Bacterial Count & ID (Up to Five Types) <input type="checkbox"/> MRSA <input type="checkbox"/> <i>Pseudomonas aeruginosa</i> | Air Samples <input type="checkbox"/> Mold & Fungi (Spore Trap) <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi (Genus & Species) <input type="checkbox"/> Bacterial Culture & ID (Up to Three Types) <input type="checkbox"/> Bacterial Culture & ID (Up to Five Types) <input type="checkbox"/> Endotoxin Testing Real Time Q-PCR (See Analytical Guide for Code) Code: Legionella <input type="checkbox"/> Level 1 <input type="checkbox"/> Level 2 <input type="checkbox"/> Level 3 <input type="checkbox"/> Level 4 Other: | IAQ Nuisance Dust NIOSH <input type="checkbox"/> 0500 <input type="checkbox"/> 0600 Airborne Dust <input type="checkbox"/> PM10 <input type="checkbox"/> TSP Silica Analysis: <input type="checkbox"/> All Species Silica Analysis - Single Species <input type="checkbox"/> Alpha Quartz <input type="checkbox"/> Cristobalite <input type="checkbox"/> Tridymite <input type="checkbox"/> HVAC Efficiency <input type="checkbox"/> Carbon Black <input type="checkbox"/> Airborne Oil Mist Radon Testing: Call for Kit and COC Other: |
|---|--|---|

****Comments/Special Instructions:**

| | | | |
|---------------------------|----------------------|---------------------|---|
| Client Sample #'s | - | Total # of Samples: | 3 |
| Relinquished (Client): | Date: | Time: | |
| Received (Lab): <u>mv</u> | Date: <u>2-16-11</u> | Time: <u>10:00</u> | |

1023



Building # 122 SOUTH TOWERS

Type of Analysis: Lead / Asbestos

Date: 02-14-2011

Sample Analysis Turn Around Time 24 HRS

| Area | Sample ID | Material Sampled | Material Location | F/NF | Cond | Quantity | Pot to Disturb |
|------|-----------|--------------------------|---------------------------------------|------|------|-----------|----------------|
| A | 1 | PLASTER CEILING MATERIAL | CEILING OF BATHROOM RLC APT 1ST FLOOR | F | D | 100 SQ FT | LOW |
| A | 2 | PLASTER CEILING MATERIAL | CEILING OF BATHROOM RLC APT 1ST FLOOR | F | D | 100 SQ FT | LOW |
| A | 3 | PLASTER CEILING MATERIAL | CEILING OF BATHROOM RLC APT 1ST FLOOR | F | D | 100 SQ FT | LOW |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

License # ASBI-00568 FM# FM00356991 Signature Requestor HANK SULLY

Send lab results in PDF format as soon as possible to: Ed Pitts 803-777-3296 720 College St Columbia, SC 29208 EHP@fmc.sc.edu

Ty Russell 803-777-1208 720 College St Columbia, SC 29208 NTRusse@fmc.sc.edu

Fax # 803-777-3990



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-3296
Project: **122 South Towers Bld**


Customer ID: UNSC62
Customer PO:
Received: 08/03/09 10:00 AM
EMSL Order: 020904360
EMSL Proj:
Analysis Date: 8/3/2009

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------|--------------------|--|--------------|-------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 1 020904360-0001 | Joint Compound | Tan Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 2 020904360-0002 | Sheetrock | Brown/Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 3 020904360-0003 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |
| 4 020904360-0004 | Joint Compound | Tan Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 5 020904360-0005 | Sheetrock | Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 6 020904360-0006 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |
| 7 020904360-0007 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |

Analyst(s)

Kristie Hein (21)



Stephen Bennett, Laboratory Manager
or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-3296
Project: **122 South Towers Bld**

Customer ID: UNSC62
Customer PO:
Received: 08/03/09 10:00 AM
EMSL Order: 020904360
EMSL Proj:
Analysis Date: 8/3/2009

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------|--------------------|--|--------------|-------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 8 020904360-0008 | Joint Compound | Tan Non-Fibrous Heterogeneous | | 98% Non-fibrous (other) | 2% Chrysotile |
| 9 020904360-0009 | Sheetrock | Brown/Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 10 020904360-0010 | Joint Compound | Tan Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 11 020904360-0011 | Sheetrock | Gray Fibrous Heterogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 12 020904360-0012 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |
| 13 020904360-0013 | Joint Compound | Tan Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 14 020904360-0014 | Sheetrock | Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |

Analyst(s) _____

Kristie Hein (21)

Stephen Bennett, Laboratory Manager
or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-3296
Project: 122 South Towers Bld


Customer ID: UNSC62
Customer PO:
Received: 08/03/09 10:00 AM
EMSL Order: 020904360
EMSL Proj:
Analysis Date: 8/3/2009

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---|--------------------|--|---------------|-------------------------|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 15 020904360-0015 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |
| 16 020904360-0016 | Joint Compound | Tan Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 17 020904360-0017 | Sheetrock | Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 18 020904360-0018 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |
| 19 020904360-0019 | Joint Compound | Brown/Gray Fibrous Heterogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| Sample Does Not Match C.O.C. Description. No Joint Compound Present. Only Sheetrock | | | | | |
| 20 020904360-0020 | Sheetrock | Gray Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 21 020904360-0021 | Hard Wall Material | Gray Fibrous Heterogeneous | | 70% Non-fibrous (other) | 30% Chrysotile |

Analyst(s)

Kristie Hein (21)



Stephen Bennett, Laboratory Manager
or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



107 Haddon Avenue, Westmont, New Jersey 08108

1-800-220-3675

http://www.emsl.com

4360

EMSL ANALYTICAL, Inc. CHAIN OF CUSTODY

EMSL Rep:

Third Party Billing requires written authorization from third party

Your Name: City of South Carolina

EMSL-Bill to:

Company: Ed Potts

Street: _____

Street: _____

Box #: _____

Box #: _____

City/State: _____ Zip: _____

City/State: _____ Zip: _____

Phone Results to:

Fax Results to:

Name: _____

Name: _____

Telephone #: _____

Fax #: _____

Project Name/Number: #122 South Town
122

Purchase Order #: _____

TURNAROUND TIME

| | | | | | | | | |
|----------------------------------|----------------------------------|-----------------------------------|--|-----------------------------------|-----------------------------------|---------------------------------|---------------------------------|------------------------------------|
| <input type="checkbox"/> 3 Hours | <input type="checkbox"/> 6 Hours | <input type="checkbox"/> 12 Hours | <input checked="" type="checkbox"/> 24 Hours | <input type="checkbox"/> 48 Hours | <input type="checkbox"/> 72 Hours | <input type="checkbox"/> 4 Days | <input type="checkbox"/> 5 Days | <input type="checkbox"/> 6-10 Days |
|----------------------------------|----------------------------------|-----------------------------------|--|-----------------------------------|-----------------------------------|---------------------------------|---------------------------------|------------------------------------|

SAMPLE MATRIX

| | | | | | | | | |
|------------------------------|--|-------------------------------|-------------------------------|-------------------------------------|---|-------------------------------------|--------------------------------|--------------------------------|
| <input type="checkbox"/> Air | <input checked="" type="checkbox"/> Bulk | <input type="checkbox"/> Soil | <input type="checkbox"/> Wipe | <input type="checkbox"/> Aflato-Vac | <input type="checkbox"/> Drinking Water | <input type="checkbox"/> Wastewater | <input type="checkbox"/> Chips | <input type="checkbox"/> Other |
|------------------------------|--|-------------------------------|-------------------------------|-------------------------------------|---|-------------------------------------|--------------------------------|--------------------------------|

ASBESTOS ANALYSIS

PCM - Air

- NIOSH 7400 (A) Issue 2: August 1994
- OSHA w/TWA

TEM AIR

- AHERA 40 CFR, Part 763 Subpart E
- NIOSH 7402 Issue 2

EPA Level II

PLM - Bulk

- EPA 600/R-93/116
- NY Stratified Point Count
- California Air Resource Board (CARB) 435
- NIOSH 9002

PLM NOB (Gravimetric) NYS 198.1

- EPA Point Count (400 Points)
- EPA Point Count (1,000 Points)
- Standard Addition Point Count

SOILS

- EPA Protocol Qualitative
- EPA Protocol Quantitative
- EMSL MSD 9000 Method fibers/gram
- Superfund EPA 540-R097-028 (dust generation)

TEM BULK

- Drop Mount (Qualitative)
- Cleafield SOP-1988-02
- TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC

- ASTM D 5755-95 (Quantitative)

TEM WIPE

- ASTM D-6480-99
- Qualitative

TEM WATER

- EPA 108.1
- EPA 100.2
- NYS 198.3

OTHER _____

LEAD ANALYSIS

Flame Atomic Absorption

- Wipe, SW846-7420 ASTM non ASTM
- Soil, SW846-7420
- Air, NIOSH 7082

Chips, SW846-7420 or LOAC 5.009 (974.02)

Wastewater, SW 846-7420

TCLP LEAD SW846-1311/7420

Graphite Furnace Atomic Absorption

- Air, NIOSH 7105
- Wastewater, SW846-7411
- Soil, SW846-7421
- Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma

- Wipe, SW846-6010 ASTM non ASTM
- Soil, SW846-6010
- Air, NIOSH 7300

MATERIALS ANALYSIS

- Full Particle Identification
- Optical Particle Identification
- Dust Mites and Insect Fragments
- Particle Size & Distribution
- Product Comparison
- Paint Characterization
- Failure Analysis
- Corrosion Analysis
- Glove Box Containment Study
- Petrographic Examination of Concrete
- Portland Cement in Workplace Atmospheres (OSHA ID-143)
- Man Made Vitreous Fibers - MMVF's
- Synthetic Fiber Identification
- Other: _____

MICROBIAL ANALYSIS

Air Samples

- Mold & Fungi by Air O Cell
- Mold & Fungi by Agar Plate count & id
- Bacterial Count and Gram Stain
- Bacterial Count and Identification

Water Samples

- Total Coliforms, Fecal Coliforms
- Escherichia Coli, Fecal Streptococcus
- Legionella
- Salmonella
- Giardia and Cryptosporidium

Wipe and Bulk Samples

- Mold & Fungi - Direct Examination
- Mold & Fungi - (Culture follow up to direct examination if necessary)
- Mold & Fungi - Culture (Count & ID)
- Mold & Fungi - Culture (Count only)
- Bacterial Count & Gram Stain
- Bacterial Count & Identification (3 most prominent types)
- Other: _____

IAQ ANALYSIS

- Nuisance Dust (NIOSH 0500 & 0600)
- Airborne Dust (PM10, TSP)
- Silica Analysis by XRD NIOSH 7500
- HVAC Efficiency
- Carbon Black
- Airborne Oil Mist
- Other: _____

Client Sample # (S)

Relinquished: _____
 Received: _____
 Relinquished: _____
 Received: _____

NS

Date: _____
 Date: _____
 Date: _____
 Date: _____

8/3


TOTAL SAMPLE #

21

Time: _____
 Time: _____
 Time: _____
 Time: _____

16:00

4360



1013

122

Building # SOUTH TOWERS BLD

Type of Analysis: Lead / Asbestos

Date: 07-31-2009

Turn Around Time 24 HRSA

| Area | Sample ID | Material Sampled | Material Location | F/NF | Cond | Quantity | Pot to Disturb |
|------|-----------|--------------------|--|------|------|-----------|----------------|
| A | 1 | JOINT COMPOUND | 18TH FLOOR STUDY ROOM | F | GOOD | 400 SQ FT | LOW |
| A | 2 | SHEET ROCK | 18TH FLOOR STUDY ROOM | F | GOOD | 150 SQ FT | LOW |
| A | 3 | HARD WALL MATERIAL | EXTERIOR WALL UNDER WINDOW SECTION | F | GOOD | 100 SQ FT | LOW |
| A | 4 | JOINT COMPOUND | 17TH FLOOR STUDY RM NORTH WALL | F | GOOD | 40 SQ FT | LOW |
| A | 5 | SHEET ROCK | 17TH FLOOR STUDY RM NORTH WALL | F | GOOD | 150 SQ FT | LOW |
| A | 6 | HARD WALL MATERIAL | EXTERIOR WALL UNDER WINDOW SECTION OF ROOM | F | GOOD | 100 SQ FT | LOW |
| A | 7 | HARD WALL MATERIAL | RM 1205 LEFT @ WINDOW | F | GOOD | 100 SQ FT | LOW |
| A | 8 | JOINT COMPOUND | JOINT COMPOUND | F | GOOD | 35 SQ FT | LOW |
| A | 9 | SHEET ROCK | RM 1205 WALL MATERIAL | F | GOOD | 100 SQ FT | LOW |
| A | 10 | JOINT COMPOUND | RM 810 LEFT HAND WALL | F | GOOD | 40 SQ FT | LOW |

License # 00568

FM# FM00311313

Signature

Requestor JEFF TAYLOR

Send lab results in PDF format as soon as possible to:


Ed Pitts 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashD@fmc.sc.edu

Iy Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRussell@fmc.sc.edu

Fax # 803-777-3990

4360



293

#122

Building # South Tower

Type of Analysis: Lead Asbestos

Date: 7-31-09

Turn Around Time

24 hr

| Area | Sample ID | Material Sampled | Material Location | F/NF | Cond | Quantity | Pot to Disturb |
|------|-----------|--------------------|------------------------------------|------|------|-----------|----------------|
| A | 11 | SHEET ROCK | RM 810 RIGHT HAND WALL | F | GOOD | 150 SQ FT | LOW |
| A | 12 | HARD WALL MATERIAL | RM 810 WALL EXTERIOR UNDER WINDOW | F | GOOD | 100 SQ FT | LOW |
| A | 13 | JOINT COMPOUND | 2ND FLOOR STUDY ROOM | F | GOOD | 30 SQ FT | LOW |
| A | 14 | SHEET ROCK | 2ND FLOOR STUDY ROOM | F | GOOD | 150 SQ FT | LOW |
| A | 15 | HARD WALL MATERIAL | 2ND FLOOR STUDY ROOM UNDER WINDOW | F | GOOD | 100 SQ FT | LOW |
| A | 16 | JOINT COMPOUND | RM 407 CORNER WALL | F | GOOD | 40 SQ FT | LOW |
| A | 17 | SHEETROCK WALL | RM 407 WALL MATERIAL | F | GOOD | 140 SQ FT | LOW |
| A | 18 | HARD WALL MATERIAL | EXTERIOR WALL UNDER WINDOWS RM 407 | F | GOOD | 100 SQ FT | LOW |
| A | 19 | JOINT COMPOUND | RM 607 WALL MATERIAL | F | GOOD | 40 SQ FT | LOW |
| A | 20 | SHEET ROCK | RM 607 WALL | F | GOOD | 140 SQ FT | LOW |

License #

FM#

Signature

Requestor

Send lab results in PDF format as soon as possible to:

Ed Potts 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashingtonD@fmc.sc.edu

Ty Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRussell@fmc.sc.edu

Fax # 803-777-3990

**EMSL Analytical, Inc.**

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborofab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: **South Towers Roofing**

Customer ID: UNSC62
 Customer PO:
 Received: 07/12/11 10:15 AM
 EMSL Order: 021104131
 EMSL Proj:
 Analysis Date: 7/14/2011

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---|------------------------|---|----------------------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 1-Shingle-Like Material 021104131-0001 | Flat Roofing Materials | Gray/Black/Green Fibrous Heterogeneous | 10% Glass <1% Cellulose | 90% Non-fibrous (other) | None Detected |
| 1-Loose Tar-Based Material 021104131-0001A | Flat Roofing Materials | White/Black Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| 2-Shingle-Like Material 021104131-0002 | Flat Roofing Materials | Gray/Black/Green Fibrous Heterogeneous | 10% Glass <1% Cellulose | 90% Non-fibrous (other) | None Detected |
| 2-Loose Tar-Based Material 021104131-0002A | Flat Roofing Materials | White/Black Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |
| 3-Shingle-Like Material 021104131-0003 | Flat Roofing Materials | Gray/Black/Green Fibrous Heterogeneous | 10% Glass <1% Cellulose | 90% Non-fibrous (other) | None Detected |
| 3-Loose Tar-Based Material 021104131-0003A | Flat Roofing Materials | White/Black Non-Fibrous Heterogeneous | <1% Cellulose | 100% Non-fibrous (other) | None Detected |

Initial report from 07/14/2011 14:34:58

Analyst(s)

Kristie Elliott (2)
 Scott Combs (6)

Stephen Bennett, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
 706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
 Customer PO:
 Received: 07/12/11 10:15 AM
 EMSL Order: 021104131

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: **South Towers Roofing**

EMSL Proj:
 Analysis Date: 7/14/2011


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------|-----------------|--|---------------------------|-------------------------|------------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 4 021104131-0004 | Mastic/Flashing | Gray/Black Fibrous Heterogeneous | 15% Glass 1% Cellulose | 84% Non-fibrous (other) | <1% Chrysotile |
| 5 021104131-0005 | Mastic/Flashing | Brown/Gray/Black Fibrous Heterogeneous | 8% Glass 3% Cellulose | 84% Non-fibrous (other) | 5% Chrysotile |
| 6 021104131-0006 | Mastic/Flashing | | | | Stop Positive (Not Analyzed) |

Initial report from 07/14/2011 14:34:58

Analyst(s)

 Kristie Elliott (2)
 Scott Combs (6)



 Stephen Bennett, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
 Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Galin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **South Towers Roofing**

Customer ID: UNSC62
Customer PO:
Received: 07/15/11 10:15 AM
EMSL Order: 021104131
EMSL Proj:
Analysis Date: 7/19/2011

**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM
via EPA/600/R-93/116 Section 2.5.5.1**

| SAMPLE ID | DESCRIPTION | APPEARANCE | % MATRIX MATERIAL | % NON-ASBESTOS FIBERS | ASBESTOS TYPES |
|--|-----------------------|---|-------------------|-----------------------|----------------------|
| 3-Shingle-Like Material 021104131-0007 | Flat Roofing Material | Black Fibrous Heterogeneous | 100 | None | No Asbestos Detected |
| 3-Loose Tar-Based Material 021104131-0008 | Flat Roofing Material | Brown /White /Black Non-Fibrous Heterogeneous | 100 | None | No Asbestos Detected |

Initial report from 07/14/2011 14:34:58

Analyst(s)

Stephen Bennett (2)

Stephen Bennett, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. Kernersville, NC

4131



107 Haddon Avenue, Westmont, New Jersey 08108

1-800-220-3675

http://www.emsl.com

EMSL ANALYTICAL, Inc. CHAIN OF CUSTODY

EMSL Rep:

Your Name: _____
 Company: University of South Carolina
 Street: 243 Game St
 Box #: _____
 City/State: Columbia, SC Zip: 29208
 Phone Results to:
 Name: _____
 Telephone #: _____
 Project Name/Number: 122 South Tower's

EMSL-Bill to: _____
 Street: _____
 Box #: _____
 City/State: _____ Zip: _____
 Fax Results to:
 Name: _____
 Fax #: _____
 Purchase Order #: _____

Third Party Billing requires written authorization from third party

TURNAROUND TIME
 3 Hours 6 Hours 12 Hours 24 Hours 48 Hours 72 Hours 4 Days 5 Days 6-10 Days

SAMPLE MATRIX
 Air Bulk Soil Wipe Micro-Vac Drinking Water Wastewater Sludge Other

ASBESTOS ANALYSIS

PCM - Air
 NIOSH 7400 (A) base 2: August 1994
 OSHA w/ IAWA

TEM AIR
 AHERA 40 CFR, Part 763 Subpart II
 NIOSH 7402 Issue 2
 EPA Level II

PLM - Bulk
 EPA 600/R-93/116
 NY Stratified Point Count
 California Air Resource Board (CARB) 413
 NIOSH 9002
 PLM NOB (Gravimetric) NYS 198.1
 EPA Point Count (400 Points)
 EPA Point Count (1,000 Points)
 Standard Addition Point Count

SOILS
 EPA Protocol Qualitative
 EPA Protocol Quantitative
 EMSL MSD 9000 Method fibers/gram
 Superfund EPA 840-R097-028 (dust generation)

TEM BULK
 Drop Mount (Qualitative)
 Chatfield SOP-1985-02
 TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC
 ASTM D 3755-93 (Quantitative)

TEM WIPE
 ASTM D-6480-99
 Qualitative

TEM WATER
 EPA 160.1
 EPA 160.2
 NYS 198.2

OTHER _____

LEAD ANALYSIS

Flame Atomic Absorption
 Wipe, SW 846-7420 ASTM non ASTM
 Soil, SW 846-7420
 Air, NIOSH 7082
 Chips, SW 846-7420 or AOAC 5.009 (974.02)
 Wastewater, SW 846-7420
 TCLP LEAD SW 846-1311/7420

Graphite Furnace Atomic Absorption
 Air, NIOSH 7105
 Wastewater, SW 846-7421
 Soil, SW 846-7421
 Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma
 Wipe, SW 846-6010 ASTM non ASTM
 Soil, SW 846-6010
 Air, NIOSH 7300

MATERIALS ANALYSIS

Full Particle Identification
 Optical Particle Identification
 Dust Mites and Insect Fragments
 Particle Size & Distribution
 Product Comparison
 Paint Characterization
 Failure Analysis
 Corrosion Analysis
 Glove-Box Containment Study
 Petrographic Examination of Concrete
 Portland Cement in Workplace Atmospheres (OSHA 10-143)
 Man Made Vitreous Fibers - SIMVT's
 Synthetic Fiber Identification
 Other _____

MICROBIAL ANALYSIS

Air Samples
 Mold & Fungi by Air O-Cell
 Mold & Fungi by Agar Plate count & ID
 Bacterial Count and Gram Stain
 Bacterial Count and Identification

Water Samples
 Total Coliforms, Fecal Coliforms
 Escherichia Coli, Fecal Streptococci
 Legionella
 Salmonella
 Giardia and Cryptosporidium

Wipe and Bulk Samples
 Mold & Fungi - Direct Examination
 Mold & Fungi - Culture (follow up to direct examination if necessary)
 Mold & Fungi - Culture (Count & ID)
 Mold & Fungi - Culture (Count only)
 Bacterial Count - Gram Stain
 Bacterial Count - Identification (3 most prominent types)
 Other _____

IAQ ANALYSIS

Nuisance Dust (NIOSH 0500 & 0601)
 Airborne Dust (PM10, TSP)
 Silica Analysis by XRD Fresh Silica
 HVAC Efficiency
 Carbon Black
 Airborne Oil Mists
 Other _____

Client Sample # (S) _____

Relinquished: _____ Date: _____
 Received: _____ Date: _____
 Relinquished: KE Date: _____
 Received: _____ Date: 7/12

TOTAL SAMPLE # 6

Time: _____
 Time: _____
 Time: _____
 Time: 10:15

Page 1 of 2

Reset Form

Print Form

4131



to Soil Positive

Building # SOUTH TOWERS ROOFING

Sample Analysis Type of Analysis: Lead / Asbestos

Date: 07-11-2011

Turn Around Time 72 HRS

| Area | Sample ID | Material Sampled | Material Location | F/NF | Cond | Quantity | Pot to Disturb |
|------|-----------|------------------------|--|------|------|------------|----------------|
| A | 1 | FLAT ROOFING MATERIALS | ENTIRE ROOF OF SOUTH TOWERS | NF | G | 4850 SQ FT | LOW |
| A | 2 | FLAT ROOFING MATERIALS | ENTIRE ROOF OF SOUTH TOWERS | NF | G | 4850 SQ FT | LOW |
| A | 3 | FLAT ROOFING MATERIALS | ENTIRE ROOF OF SOUTH TOWERS | NF | G | 4850 SQ FT | LOW |
| B | 4 | MASTIC / FLASHING | AROUND PERIMETER AND ON JOINTS OF ROOF | NF | G | 4850 SQ FT | LOW |
| B | 5 | MASTIC / FLASHING | AROUND PERIMETER AND ON JOINTS OF ROOF | NF | G | 4850 SQ FT | LOW |
| B | 6 | MASTIC / FLASHING | AROUND PERIMETER AND ON JOINTS OF ROOF | NF | G | 4850 SQ FT | LOW |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

License # ASBI-00568

FM# FM00364706

Signature *[Signature]*

Requestor DALE BRANHAM

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashinD@fmc.sc.edu


Ty Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRussel@fmc.sc.edu

Fax # 803-777-3990



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: University of South Carolina
743 Greene St
Columbia, SC 29208

Attn: Darryl Washington

Lab Order ID: 1202898

Analysis ID: 1202898PLM

Date Received: 2/21/2012

Date Reported: 2/21/2012

Project: 122 South Dorm

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|--------------|---------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 1 | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_1 | single layer | | | | Crushed |
| 2 | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_2 | single layer | | | | Crushed |
| 3 | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_3 | single layer | | | | Crushed |
| 4 | Jt compound | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_4 | | | | | Crushed |
| 5 | Jt compound | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_5 | | | | | Crushed |
| 6 | Jt compound | 3% Chrysotile | | 97% Other | White Non Fibrous Homogeneous |
| 1202898PLM_6 | | | | | Crushed |
| 7 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous |
| 1202898PLM_7 | | | Teased | | |
| 8 | Sheetrock | None Detected | 15% Cellulose | 85% Gypsum | White, Brown Fibrous Heterogeneous |
| 1202898PLM_8 | | | Teased | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Sharon Donald (30)

Analyst

Nathaniel Durham, MS or Approved Signatory

Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888

Page 1 of 4



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP[®]
NVLAP Lab Code: 200664-0

Customer: University of South Carolina
743 Greene St
Columbia, SC 29208

Attn: Darryl Washington

Lab Order ID: 1202898

Analysis ID: 1202898PLM

Date Received: 2/21/2012

Date Reported: 2/21/2012

Project: 122 South Dorm

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|-------------|---------------|--------------------|------------------------|------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 9 | Sheetrock | None Detected | 15% Cellulose | 85% Gypsum | Brown, White Fibrous Heterogeneous |
| 1202898PLM_9 | | | | | Teased |
| 10 - A | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_10 | finish | | | | Crushed |
| 10 - B | Plaster | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1202898PLM_27 | base | | | | Crushed |
| 11 - A | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_11 | finish | | | | Crushed |
| 11 - B | Plaster | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1202898PLM_28 | base | | | | Crushed |
| 12 - A | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1202898PLM_12 | finish | | | | Crushed |
| 12 - B | Plaster | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1202898PLM_29 | base | | | | Crushed |
| 13 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_13 | | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Sharon Donald (30)

Analyst


Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888

Nathaniel Durham, MS or Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: University of South Carolina
743 Greene St
Columbia, SC 29208

Attn: Darryl Washington

Lab Order ID: 1202898

Analysis ID: 1202898PLM

Date Received: 2/21/2012

Date Reported: 2/21/2012

Project: 122 South Dorm

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|-------------|---------------|--------------------|------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 14 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_14 | | | | | Crushed |
| 15 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_15 | | | | | Crushed |
| 16 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous |
| 1202898PLM_16 | | | Teased | | |
| 17 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous |
| 1202898PLM_17 | | | Teased | | |
| 18 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous |
| 1202898PLM_18 | | | Teased | | |
| 19 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_19 | | | | | Crushed |
| 20 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_20 | | | | | Crushed |
| 21 | Jt comp | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1202898PLM_21 | | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Sharon Donald (30)


Analyst

Nathaniel Durham, MS or Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: University of South Carolina
743 Greene St
Columbia, SC 29208

Attn: Darryl Washington

Lab Order ID: 1202898

Analysis ID: 1202898PLM

Date Received: 2/21/2012

Date Reported: 2/21/2012

Project: 122 South Dorm

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes | |
|---------------|----------------|---------------|--------------------|------------------------|---------------------------------------|---------|
| Lab Sample ID | Lab Notes | | | | Treatment | |
| 22 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous | Teased |
| 1202898PLM_22 | | | | | | |
| 23 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous | Teased |
| 1202898PLM_23 | | | | | | |
| 24 | Sheetrock | None Detected | 10% Cellulose | 90% Gypsum | White Non Fibrous Heterogeneous | Teased |
| 1202898PLM_24 | | | | | | |
| 25 | Plaster | None Detected | | 100% Other | White Non Fibrous Homogeneous | Crushed |
| 1202898PLM_25 | joint compound | | | | | |
| 26 - A | Plaster | None Detected | | 100% Other | White Non Fibrous Heterogeneous | Crushed |
| 1202898PLM_26 | finish | | | | | |
| 26 - B | Plaster | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous | Crushed |
| 1202898PLM_30 | base | | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Sharon Donald (30)

Analyst

Nathaniel Durham, MS or Approved Signatory

Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888

Page 4 of 4



Scientific Analytical Institute
 302-L Pomona Dr. Greensboro, NC 27407
 Phone: 336.292.3888 Fax: 336.292.3313
 www.sailab.com lab@sailab.com

Lab Use Only
 Lab Order ID: 1202898
 Client Code: _____

| Company Contact Information | |
|-----------------------------|--|
| Company: _____ | Contact: _____ |
| Address: _____ | Phone <input type="checkbox"/> : _____ |
| _____ | Fax <input type="checkbox"/> : _____ |
| _____ | Email <input type="checkbox"/> : _____ |

| Asbestos Test Types | |
|----------------------------|-------------------------------------|
| PLM EPA 600/R-93/116 | <input checked="" type="checkbox"/> |
| <i>Passive stop</i> | <input checked="" type="checkbox"/> |
| PLM Point Count | <input type="checkbox"/> |
| PCM NIOSH 7400 | <input type="checkbox"/> |
| TEM AHERA | <input type="checkbox"/> |
| TEM Level II | <input type="checkbox"/> |
| TEM NIOSH 7402 | <input type="checkbox"/> |
| TEM Bulk Qualitative | <input type="checkbox"/> |
| TEM Bulk Chatfield | <input checked="" type="checkbox"/> |
| TEM Bulk Quantitative | <input type="checkbox"/> |
| TEM Wipe ASTM D6480-99 | <input type="checkbox"/> |
| TEM Microvne ASTM D5735-02 | <input type="checkbox"/> |
| TEM Water EPA 100.2 | <input type="checkbox"/> |
| Other: _____ | <input type="checkbox"/> |

| Billing/Invoice Information | Turn Around Times | |
|----------------------------------|-----------------------------------|------------------------------------|
| Company: <u>Un of SC</u> | 90 Min. <input type="checkbox"/> | 48 Hours <input type="checkbox"/> |
| Contact: <u>Potts - Woodhull</u> | 3 Hours <input type="checkbox"/> | 72 Hours <input type="checkbox"/> |
| Address: _____ | 6 Hours <input type="checkbox"/> | 96 Hours <input type="checkbox"/> |
| _____ | 12 Hours <input type="checkbox"/> | 120 Hours <input type="checkbox"/> |
| _____ | 24 Hours <input type="checkbox"/> | 144 Hours <input type="checkbox"/> |

Bottom 3 Down

PO Number: South Down
 Project Name/Number: _____

| Sample ID # | Description/Location | Volume/Area | Comments |
|-------------|----------------------|-------------|----------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Total # of Samples 26

| Relinquished by | Date/Time | Received by | Date/Time |
|-----------------|-----------|--------------------|----------------|
| | | <i>[Signature]</i> | <u>2/20/03</u> |

Accepted
 Rejected

1202898



Building # 122 South Dorm

Sample Analysis

Type of Analysis: Lead Asbestos Date: 02-20-12

Turn Around Time 24hr

| Area | Sample ID | Material Sampled | Material Location | F/NF | Cond | Quantity | Pot to Disturb |
|------|-----------|------------------|--------------------|------|------|-----------|----------------|
| A | 1tur3 | plaster | basement | F | G | <2000sqft | Low |
| B | 4thru6 | jt comp | basement | F | G | <1000 | Low |
| C | 7thru9 | sheetrock | basement | F | G | <1000 | Low |
| D | 10thru12 | plaster | first floor | F | G | 2000 | Low |
| E | 13thru15 | jt comp | first floor | F | G | <1000 | Low |
| F | 16thru18 | sheetrock | first floor | F | G | <1000 | Low |
| G | 19thru21 | jt comp | sub basement-green | F | G | 4sqft | Low |
| H | 22thru24 | sheetrock | sub basement-green | F | G | 500sqft | Low |
| D | 25&26 | plaster | 1st floor | F | G | 2000 | Low |

License # 21534

FM#

Signature

Requestor

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296
 Darryl Washington 803-777-2399
 720 College St.
 Columbia, SC 29208
 EHP@fmc.sc.edu

Ty Russell 803-777-1208
 720 College St.
 Columbia, SC 29208
 NTRussse@fmc.sc.edu

Fax # 803-777-3990

APPENDIX C

Personnel Certifications

**SCDHEC ISSUED
Asbestos ID Card**

Michael Mincey

Expires



AIR SAMPLER
CONSULTANT
SUPERVISOR

AS-00272 05/04/12
MP-00161 02/11/12
SA-01424 05/04/12

SCDHEC ISSUED
Asbestos ID Card

Glynn M Ellen



AIRSAMPLER
CONSULTMP
CONSULTPD
SUPERHERA

Expires

AS-00079 01/06/12
ASB-22641 02/11/12
PD-00098 06/30/12
SA-00455 01/06/12

APPENDIX D

SCDHEC Regulations

SCDHEC Abatement Project Forms

Air Quality

Asbestos - Regulatory Information

RENOVATIONS & DEMOLITIONS

Note: This information should serve as a guide only and is not intended to replace the regulations. For additional information concerning DHEC and EPA regulations, contact DHEC's Asbestos Section at (803) 898-4289. Information regarding the OSHA asbestos standards may be obtained from the South Carolina Department of Labor, Licensing and Regulation at (803) 734-9669.

APPLICABILITY

Renovation and demolition of most facilities, including buildings, structures, and other installations, are subject to State and Federal asbestos regulations. Certain residential buildings may be exempt unless the property was used in the past for non-residential purposes (contact the Asbestos Section for additional information) or is part of a larger development such as highway right-of-way, mall development, urban renewal or other type of similar development. The facility owner and the renovation or demolition contractor are both responsible for ensuring compliance with these regulations.

DEFINITIONS

Renovation means altering a facility or one or more facility components in any way, including the stripping or removal of regulated asbestos-containing material (RACM) from a facility component. "Remodeling" is considered renovation.

Demolition is the wrecking or taking out of any load-supporting structural member of a facility and any related handling operations. Structural burns are prohibited by State Open Burning Regulations.

INSPECTION FOR ASBESTOS

Before a facility or a portion of a facility is renovated or demolished, the owner/operator of the facility or renovation or demolition activity must ensure that the facility or portion of the facility being renovated or demolished has been thoroughly inspected for the presence of asbestos. The inspection must be performed by a person who has been trained and licensed as an Asbestos Building Inspector or management planner in accordance with State training and licensing requirements.

The inspector must identify, quantify, and assess the condition of all suspect asbestos-containing materials, either friable or non-friable, on interior and exterior portions of the facility. The inspector must also comply with the procedures specified in 40 CFR 763.86 in determining sampling locations and the number of representative samples to be collected. In addition, the

inspector is required to prepare a written report detailing the findings of the inspection. At a minimum, the report must include information required in 40 CFR 763.85 (a)(4)(vi)(A)-(E), as well as the date of inspection and the name, license number, and signature of the licensed Asbestos Building Inspector or Management Planner who performed the inspection and completed the report. A legible copy of the building inspection report must be provided to the Department prior to each demolition, and upon request for renovations. (Note: **"BUILDING INSPECTIONS"** can be consulted for a detailed explanation of the aforementioned sampling and reporting protocols.)

A building inspection will only be acceptable if performed **within three years** prior to the demolition or renovation. If an inspection report is more than three years old, then it must be confirmed and verified by a licensed Asbestos Building Inspector or Management Planner.-

FRIABLE ASBESTOS-CONTAINING MATERIALS

If friable asbestos-containing materials (e.g., pipe insulation) are present, they must be removed prior to being disturbed during renovation or demolition activities. Removal (abatement) must be performed by trained, licensed persons using procedures detailed in State and Federal regulations.

A project design must be prepared for each asbestos abatement project involving the abatement of greater than 3,000 square feet, 1,500 linear feet and/or 656 cubic feet of RACM in a facility to be reoccupied. Such designs must be prepared by a person licensed by the Department as an Asbestos Project Designer.

NON-FRIABLE ASBESTOS-CONTAINING MATERIALS

During renovations, removal of non-friable materials (e.g., vinyl-asbestos floor tiles and sheet flooring, mastics, asphaltic roofing, and asbestos-cement siding and roofing tiles) may be regulated. Applicability is dependent upon the removal methods to be used. If it can be anticipated that non-friable materials will be ground, crumbled, sanded, abraded, chipped or pulverized, the removal is subject to the same rules as removal of friable materials.

Prior to any demolition, non-friable asbestos-cement products (e.g., transite siding, exterior siding and roofing shingles) must be removed. Asbestos-containing sheet flooring and floor tiles, as well as asphaltic roofing products, need not be removed if they are in good condition and have not become brittle and are not peeling, cracking, or crumbling. Otherwise, they must also be removed prior to demolition. If it can be anticipated that non-friable materials will be ground, crumbled, sanded, abraded, chipped or pulverized, the materials must be removed and the removal is subject to the same rules as removal of friable materials. The amount of any non-friable asbestos that will remain in place during demolition must also be indicated on the written notification form.

All asbestos-containing materials must be removed if the facility will be demolished by non-standard demolition techniques such as implosion, explosion, or intentional burning.

NOTIFICATION FOR RENOVATIONS AND DEMOLITIONS

Prior to removing regulated asbestos-containing materials, written notification must be submitted to the Department (up to 10 working days in advance, depending on the amount of asbestos to be removed). The notification must include certain required items of information about the owner, the contractor, the facility, and the asbestos removal project. Required fees must be submitted along with the notification. You must obtain a permit from the Department prior to the renovation activity.

Prior to the demolition of any regulated facility, written notification must be submitted to the Department *at least 10 working days* in advance **even if a building inspector determines that asbestos is not present at the facility**. The notification must include certain required items of information about the owner, the contractor, the facility, and the demolition project. Required fees and a copy of the building inspector's report must be submitted along with the notification of demolition. You must obtain a permit from the Department prior to the demolition activity.

DISPOSAL

Never burn any asbestos-containing waste material.

Non-asbestos-containing demolition debris and debris which contains only non-regulated roofing or flooring may be disposed of at a DHEC-approved disposal site for cellulosic or inert waste. Waste consolidation activities involving grinding, cutting, or compacting of non-friable asbestos-containing materials will subject these materials to more stringent State and Federal asbestos disposal regulations.

Regulated asbestos waste must be handled by properly licensed asbestos abatement personnel and disposed of at a landfill permitted to accept regulated asbestos waste. A list of approved landfills may be obtained from the Asbestos Section.

REGULATORY REQUIREMENTS FOR BUILDING INSPECTION

As required by the National Emission Standard for Hazardous Air Pollutants (NESHAP) and SCDHEC Regulation 61-86.1, an owner/operator shall ensure that a building inspection to detect the presence of asbestos-containing materials (ACM) has been performed prior to any renovation or demolition activity at a regulated facility.

Under SCDHEC Regulation 61-86.1, Section VI.A.6., an inspection cannot have been performed more than three years prior to a renovation or demolition activity. If more than three years have elapsed since the most recent inspection, the previous inspection shall be confirmed and verified by a licensed building inspector and/or management planner.

SCDHEC Regulation 61-86.1 requires that all inspections be performed by persons trained and licensed as either a building inspector and/or management planner. In order to be licensed in these disciplines, persons must have successfully completed a Department approved initial training course specific to inspecting for ACM in a building and/or a course specific to

management planning for ACM in a building. Persons must also have taken and passed an examination at the end of the course with a score of 70 percent or above.

In performing inspections, SCDHEC Regulation 61-86.1 requires that a building inspector and/or management planner comply with the requirements of Section VI, Asbestos Building Inspection Requirements. An inspection shall include samples from suspect friable and non-friable ACM on interior and exterior portions of a facility or its facility components.

In performing inspections, SCDHEC Regulation 61-86.1 requires that a building inspector and/or management planner follow specific sampling procedures. According to Section IV.B.3.a of the regulation, a building inspector and/or management planner shall comply with the procedures specified in **40 CFR 763.86** in determining sampling locations and the number of representative samples to be collected. An inspection shall include samples from suspect friable and non-friable ACM on interior and exterior portions of a facility or its facility components.

Under 40 CFR Part 763.86, suspect ACM are divided into three categories: surfacing materials, thermal system insulation (commonly referred to as TSI), and miscellaneous materials. SCDHEC Regulation 61-86.1, Section VI contains sampling procedures specific to each category of material.

Surfacing material includes, but is not limited to, joint compound, plaster, and painted, troweled on, or spray-applied textured material. To remain in compliance with SCDHEC Regulation 61-86.1, surfacing materials on exterior and interior portions of a facility shall be sampled according to procedures outlined in SCDHEC Regulation 61-86.1, Section VI.D.1. (a)-(c):

- A licensed asbestos inspector shall collect, in a statistically random manner, a minimum of three bulk samples from each homogeneous area of any surfacing that is not assumed to be ACM, and shall collect the samples as follows:
 - At least three bulk samples shall be collected from each homogeneous area that is 1,000 or fewer square feet (sf) or linear feet (Lf) in size.
 - At least five bulk samples shall be collected from each homogeneous area that is greater than 1,000 but fewer than or equal to 5,000 sf or Lf.
 - At least seven bulk samples shall be collected from each homogeneous area that is greater than 5,000 sf or Lf.

Thermal system insulation (TSI) is any material that is applied to pipes, fittings, boilers, breeching, tanks, ducts, or other facility components for the purpose of preventing heat loss or gain, water condensation, or for other purposes. **Miscellaneous Material** is any material that is not considered a surfacing material or thermal system insulation and includes, but is not limited to, flooring, roofing, mastics, gaskets, cementitious materials, caulking, ceiling tiles, fire doors, wall boards, and flexible duct connections. To remain in compliance with SCDHEC Regulation 61-86.1, TSI and miscellaneous materials on exterior and interior portions of a facility shall be sampled in accordance with procedures outlined in SCDHEC Regulation 61-86.1, Section VI.D.2:

- A licensed asbestos inspector shall collect, in a statistically random manner, at least three bulk samples from each homogeneous area of TSI and any miscellaneous material that is not assumed to be ACM.
- In accordance with ASTM E2356, and any subsequent amendments and editions, negative results for non-friable organically bound materials (NOB) shall be verified with at least one TEM analysis.
- NOBs include flooring, roofing, mastics, adhesives, caulks, and glazing.
- If an accredited inspector has determined the thermal system insulation to be fiberglass, foam glass, rubber, or other non-suspect material, then bulk samples are not required.

SCDHEC Regulation 61-86.1, Section VI.C requires that a building inspector and/or management planner prepare a written asbestos building inspection report to include the following:

- A title page denoting: (1) The client's name, company, address, and telephone number, and the name and exact location of the facility inspected; (2) the date the inspection was performed; (3) the date the inspection report was written; and (4) the printed name and telephone number of the inspector(s), and his or her affiliated company name, address, and telephone number.
- A cover letter to the building owner or owner's representative that describes the purpose of the inspection; a general synopsis of the inspection and results; and the name, title, and signature of the inspector(s) and report writer, if different.
- A detailed narrative of the physical description of the building or part of the building affected by the renovation or demolition operation that includes: (1) The square footage of the building or part of the building affected by the renovation or demolition operation; (2) The building materials used in the construction of the exterior, roof, interior, and basement or crawlspace of the building affected by the demolition or affected by the renovation materials operation; (3) An estimated or exact quantity (square or linear feet) for all suspect materials whether sampled for or assumed to be asbestos that may be affected by the renovation or demolition operation; (4) Also include a description of non-suspect materials excluding: glass, metals, kiln brick, cement, fiberglass, concrete, pressed wood, cinder block, and rubber.
- An executive summary that details: (1) The type of suspect ACM (e.g., TSI, floor tile, mastic), total square or linear footage, and the total number of samples collected for each separate homogenous area affected by the renovation or demolition operation; (2) The date of the inspection, type, condition, quantity, sample results, and exact location of ACM positively identified or assumed to be ACM in the part of the building affected by the renovation or demolition operation; (3) A list of the homogeneous areas identified; (4) Whether the material is accessible for the building or part of the building affected by the renovation or demolition operation; and (5) The material's potential for disturbance for the building or part of the building affected by the renovation or demolition operation.
- For renovation and demolition operations, the inspector's determination that ACM is friable or non-friable.
- Except when suspect ACM materials are assumed to be asbestos, include a complete, clear, legible copy of all laboratory bulk sample results.

- Clear, legible drawings and/or photographs to clarify the scope of the renovation or demolition operation. Illustrate the exact location of each sample collected. For facilities that involve a trade secret or confidential component or an affected area process, a request for a variance may be submitted.
- The printed name and signature of each accredited inspector who collected the samples, and a clear legible copy of his or her Department issued asbestos building inspector or management planner license



ASBESTOS ABATEMENT PROJECT LICENSE APPLICATION
 BUREAU OF AIR QUALITY • ASBESTOS SECTION • 2600 BULL STREET • COLUMBIA • SC • 29201

TYPE OF OPERATION: Standard Removal Emergency Removal Enclosure Encapsulation Cleanup Disposal

| | | |
|--|--|---|
| FOR OFFICE USE Postmark/Received: _____ | Original/Revised/Cancellation (circle one) | Project License I.D. (For Revisions/Cancellations): _____ |
|--|--|---|

I. FACILITY OWNER: _____
 MAILING ADDRESS: _____
 CITY: _____ STATE: _____ ZIP: _____
 CONTACT PERSON: _____ PHONE: (____) _____

II. REMOVAL CONTRACTOR: _____
 MAILING ADDRESS: _____
 CITY: _____ STATE: _____ ZIP: _____
 CONTACT PERSON: _____ PHONE: (____) _____
 DHEC CONTRACTOR LICENSE NO. (If applicable): _____ EXPIRATION DATE: _____

III. FACILITY NAME: _____
 STREET ADDRESS: _____
 CITY: _____ STATE: _____ COUNTY: _____
 SITE (ROOM, FLOOR, WING, UNIT, MACHINE, ETC.): _____
 BUILDING SIZE: _____ NO. OF FLOORS: _____ AGE IN YEARS: _____
 PRESENT USE: _____ PRIOR USE: _____ FUTURE USE: _____

IV. PROCEDURES, INCLUDING ANALYTICAL METHOD IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:
 FACILITY OR FACILITY COMPONENT SURVEYED BY (INSPECTOR NAME): _____
 COMPANY: _____ PHONE: (____) _____
 DHEC LICENSE NUMBER: _____ EXPIRATION DATE: _____

V. PROJECT DESIGN PERFORMED BY (IF APPLICABLE): _____
 COMPANY: _____ PHONE: (____) _____
 DHEC LICENSE NUMBER: _____ EXPIRATION DATE: _____

VI. ASBESTOS-CONTAINING MATERIALS (ACM) **TO BE REMOVED ONLY:**

| TYPE (TSI, SURFACING, FLOORING, ROOFING, ETC.) | AMOUNT (SQUARE FEET, LINEAR FEET, CUBIC FEET) | CONDITION (CIRCLE ONE) |
|--|---|---|
| | | <input type="checkbox"/> Friable <input type="checkbox"/> Non-Friable |
| | | <input type="checkbox"/> Friable <input type="checkbox"/> Non-Friable |
| | | <input type="checkbox"/> Friable <input type="checkbox"/> Non-Friable |
| | | <input type="checkbox"/> Friable <input type="checkbox"/> Non-Friable |

VII. SCHEDULED DATES OF REMOVAL: START DATE: _____ COMPLETION DATE: _____
 WORK DAYS: _____ WORK HOURS: _____

| | |
|---|--|
| <p>APPLICATIONS MUST BE SUBMITTED WITH FEES PRIOR TO THE SCHEDULED START DATE AS FOLLOWS:</p> <p>NESHAP PROJECTS: 10 WORKING DAYS SMALL PROJECTS: 5 CALENDAR DAYS MINOR PROJECTS: PRIOR TO ABATEMENT Non-Friable (NESHAP-sized) Projects: 4 working days. No fee for non-friable ACM.</p> | <p>FEE SCHEDULE FOR FRIABLE ASBESTOS-CONTAINING MATERIALS:</p> <p>10 CENTS PER SQUARE FOOT OR LINEAR FOOT MINIMUM FEE OF \$25.00 MAXIMUM FEE OF \$1000.00</p> |
|---|--|

VIII. DESCRIPTION OF PLANNED ABATEMENT WORK & METHOD(S) TO BE USED:

IX. DESCRIPTION OF WORK PRACTICES & ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE RENOVA-

X. WASTE TRANSPORTER #1: _____

MAILING ADDRESS: _____

CITY: _____ STATE: _____ ZIP: _____

CONTACT PERSON: _____ PHONE: (_____) _____

WASTE TRANSPORTER #2: _____

MAILING ADDRESS: _____

CITY: _____ STATE: _____ ZIP: _____

CONTACT PERSON: _____ PHONE: (_____) _____

XI. WASTE DISPOSAL SITE: _____

MAILING ADDRESS: _____

CITY: _____ STATE: _____ ZIP: _____

CONTACT PERSON: _____ PHONE: (_____) _____

TEMPORARY ASBESTOS STORAGE CONTAINMENT AREA LICENSE NUMBER (IF APPLICABLE): _____

XII. DESCRIPTION OF EMERGENCY REMOVAL (PLEASE ATTACH A LETTER FROM THE FACILITY OWNER EXPLAINING THE NATURE OF THE EMERGENCY)

DATE & HOUR OF EMERGENCY (MM/DD/YY): _____

DESCRIPTION OF SUDDEN, UNEXPECTED EVENT:

EXPLANATION OF HOW THE EVENT CAUSED UNSAFE CONDITIONS AND/OR WOULD CAUSE EQUIPMENT DAMAGE AND/OR AN UNREASONABLE FINANCIAL BURDEN:

XIII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NON-FRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED OR REDUCED TO POWDER:

XIV. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF REGULATION (40 CFR PART 61, SUBPART M) WILL BE ON-SITE DURING THE RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

(SIGNATURE OF OWNER/OPERATOR)

(DATE)

XIV. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.

(SIGNATURE OF OWNER/OPERATOR)

(DATE)



DEMOLITION LICENSE APPLICATION

BUREAU OF AIR QUALITY • ASBESTOS SECTION • 2600 BULL STREET • COLUMBIA • SC • 29201

TYPE OF OPERATION: Total Demolition Partial Demolition Ordered Demolition

FOR OFFICE USE

Postmark/Received:

Original/Revised/Cancellation (circle one)

Project License I.D. (For Revisions/Cancellations):

I. FACILITY OWNER:

MAILING ADDRESS: 1403 Jaret Court

CITY: West Columbia STATE: South Carolina ZIP: 29072

CONTACT PERSON: Reese Quick PHONE: (803) 808-3966

II. IS ASBESTOS PRESENT IN THE FACILITY?: YES / NO (check one)

III. DEMOLITION CONTRACTOR: Tefon Construction Company, Inc. FEDERAL ID NO.: 57-095338

MAILING ADDRESS: 657 Tittman Drive

CITY: Sumter STATE: South Carolina ZIP: 29154

CONTACT PERSON: Ted Hardy PHONE: (803) 938-3510

ASBESTOS REMOVAL CONTRACTOR (if applicable): (Unknown at this time)

MAILING ADDRESS:

CITY: STATE: ZIP:

CONTACT PERSON: PHONE: ()

IV. FACILITY NAME: Park North Apartments

STREET ADDRESS: 200 Brookhill Road West

CITY: Lexington STATE: South Carolina COUNTY: Lexington

SITE (ROOM, FLOOR, WING, UNIT, MACHINE, ETC.): Unit 9

BUILDING SIZE: ~11,000 SF NO. OF FLOORS: Two AGE IN YEARS: 30 years

PRESENT USE: Apartments PRIOR USE: Same FUTURE USE: Same

V. PROCEDURES, INCLUDING ANALYTICAL METHOD IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:

FACILITY OR FACILITY COMPONENT SURVEYED BY (INSPECTOR NAME): ACM Inspection, Glynn M. Ellen

COMPANY: F&ME Consultants PHONE: (803) 254-4540

DHEC LICENSE NUMBER: ASB-22641 EXPIRATION DATE: 02/16/2010

VI. NON-FRIABLE MASTIC, GLUE, AND ADHESIVE ASBESTOS-CONTAINING MATERIALS **REMAINING IN PLACE DURING DEMOLITION** (IF APPLICABLE):

| TYPE (MASTIC, GLUE, AND ADHESIVE) | AMOUNT (SQUARE FEET) |
|-----------------------------------|----------------------|
| Sheet Vinyl Flooring | ~600 SF |
| | |
| | |
| | |
| | |

VII. SCHEDULED DATES OF DEMOLITION (YOU MUST SPECIFY DATES):

START DATE: 05/28/2009 COMPLETION DATE: 06/10/2009

WORK DAYS: 10 WORK HOURS: 8 hours/day

- APPLICATIONS MUST BE MAILED ALONG WITH A \$50.00 FEE (PAYABLE TO SCDHEC) AT LEAST 10 WORKING DAYS PRIOR TO THE SCHEDULED START DATE. FAXES WILL NOT BE ACCEPTED.
- A COPY OF AN ASBESTOS SURVEY REPORT (NO OLDER THAN 3 YEARS) MUST ACCOMPANY THE APPLICATION.

VIII. DESCRIPTION OF PLANNED DEMOLITION METHOD(S) TO BE USED:

BULLDOZER LOADER WRECKING BALL MANUAL BURNING IMPLOSION/EXPLOSION

IF OTHER PLEASE DESCRIBE:

IX. DESCRIPTION OF WORK PRACTICES & ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION SITE:

Replacement of roof truss system that was damaged during a fire. This will be the only work to be completed prior to the removal of asbestos containing materials that were found in the building structure during the asbestos inspection. All other renovation work will be completed after the abatement.

X. WASTE TRANSPORTER #1: No ACBM waste will be handled as part of this renovation/demolition activity.

MAILING ADDRESS: _____

CITY: _____ STATE: _____ ZIP: _____

CONTACT PERSON: _____ PHONE: (____) _____

WASTE TRANSPORTER #2: _____

MAILING ADDRESS: _____

CITY: _____ STATE: _____ ZIP: _____

CONTACT PERSON: _____ PHONE: (____) _____

XI. WASTE DISPOSAL SITE: TNT Sands, Inc.

MAILING ADDRESS: 1047 HIGHWAY CHURCH ROAD

CITY: ELGIN STATE: SC ZIP: 29045

CONTACT PERSON: _____ PHONE: (803) 964-9730

XII. IF DEMOLITION ORDERED BY GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: (PLEASE ATTACH A COPY OF THE ORDER)

NAME: _____ TITLE: _____

AUTHORITY: _____

DATE OF ORDER (MM/DD/YY): _____ DATE ORDERED TO BEGIN(MM/DD/YY): _____

XIII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

If previously unidentified suspect materials are encountered during renovation/demolition activities, contractor will stop work immediately and notify the owner and the owners representative so that samples can be collected and analyzed. No activities are expected to impact asbestos containing materials during the renovation/demolition activities. All asbestos containing materials will be removed from building.

XIV. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF REGULATION (40 CFR PART 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION INVOLVING RACM AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

N/A / _____
(SIGNATURE OF OWNER/OPERATOR) (DATE)

XV. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.

_____/_____
(SIGNATURE OF OWNER/OPERATOR) (DATE)

- APPLICATIONS MUST BE MAILED ALONG WITH A \$50.00 FEE PAYABLE TO SCDHEC AT LEAST 10 WORKING DAYS PRIOR TO THE SCHEDULED START DATE. FAXES WILL NOT BE ACCEPTED.
- A COPY OF AN ASBESTOS SURVEY REPORT (NO OLDER THAN 3 YEARS) MUST ACCOMPANY THE APPLICATION.



Asbestos Waste Shipment Record

1. SCDHEC ASBESTOS ABATEMENT PROJECT LICENSE:

Generator Information

| | | |
|---|---|---|
| 2. Waste Generator/Owner Name & Address: | Work Site Name & Physical Address: | Waste Generator/Owner Telephone Number () |
| 3. Abatement Contractor Name & Address: | | Abatement Contractor Telephone Number () |
| 4. Name of waste disposal site (WDS), mailing address, and physical site location: | | WDS Telephone Number: () |
| 5. Description of Waste Materials (please circle): Friable (Regulated) / Nonfriable (Nonregulated) | 6. Bags of Containers: No. Type _____ Drums _____ Bags _____ Bulk Load | 7. Total Quantity: m3 (yd3) |
| 8. Special handling instructions & additional information: | | |

9. Generator's/Contractor's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled. The contents are in all respects in proper condition for transport by highway according to applicable international and government regulations.

| | | |
|-------------|------------|-------|
| Print Name: | Signature: | Date: |
|-------------|------------|-------|

Transporter Information (Acknowledgment of Receipt of Materials):

| | | |
|---|------------|-------|
| 10. Name, title, address, telephone number: | Signature: | Date: |
| 11. Name, title, address, telephone number: | Signature: | Date: |

Disposal Site Operator

| | | |
|---|---------------------------|-----------------------|
| 12. Discrepancy: | <u>Bags or Containers</u> | <u>Total Quantity</u> |
| 13. Waste Disposal Site Owner or Operator certification of receipt of asbestos materials covered by this manifest except as noted in item 11. | | |
| Print Name: | Signature: | Date: |

Please forward a completed copy of this record to: SCDHEC, Bureau of Air Quality, Asbestos Section, 2600 Bull Street, Columbia, SC 29201
(803) 898-4389 office. (803) 898-4281 fax.

