BID ADDENDUM	

State Project No: FP00000218	PROJECT NAME: Colonial Life Arena Miscellaneous Roof Repairs	ADDENDUM NO.: Two ADDENDUM ISSUE DATE: February 14, 2019

TO ALL BIDDERS: This addendum is issued for the purposes of modifying or interpreting the project manual, including any specifications or drawings, through addition, deletion, clarification or correction as outlined herein. The information provided in this addendum supersedes any information previously provided in the referenced documents and sections of the project manual or in any separate specifications or drawings incorporated into the project manual. This addendum and the information contained herein shall be used in the preparation of any bid submitted by the Bidder and shall become an integral part of the contract documents for any contract awarded for the project specified.

CHANGES TO PRIOR ADDENDA: NA

CHANGES TO BIDDING REQUIREMENTS: NA

CHANGES TO CONDITIONS OF THE CONTRACT: NA

CHANGES TO SPECIFICATIONS: NA

CHANGES TO DRAWINGS: NA

ACCEPTED SUBSTITUTION REQUESTS:
Section 09 97 23, 2.01, A: Sherwin Williams Loxon XP.

CLARIFICATIONS:
(Q) = Question
(R) = Response

(Q1) = Item number 25 under Sector B - is the extent of the repair just that one elevation and is there a detail for this repair?
(R1) = The extent of the repair is one window head joint where indicated. The self-adhered flashing will extend from the back up substrate to the face of the existing head flashing.

(Q2) = Item number 20 under Sector E - is the caulking required to be included in the base bid or the alternate?
(R2) = Sealant replacement shall be included in the Base Bid.

(Q3) = Section 09 01 90- Elastomeric Coating Restoration – Where does this repair occur?
(R3) = EIFS at walls above Sectors B, E and I are to receive Elastomeric Coasting Restoration.

ALL OTHER REQUIREMENTS AND PROVISIONS OF THE BIDDING DOCUMENTS REMAIN UNCHANGED. ACKNOWLEDGE RECEIPT OF THIS ADDENDUM ON THE BID FORM. FAILURE TO DO SO MAY BE CAUSE FOR REJECTION OF THE BID.

END OF ADDENDUM