

Addendum No. 1

TO: ALL BIDDERS OF RECORD

The following items shall take precedence over the drawings and specifications for the above named project and shall become part of the contract documents. Where any item called for in the specifications or indicated on the drawings is not supplemented hereby, the original requirements shall remain in effect. Where any original item is amended, voided or superseded hereby, the provisions of such item not specifically amended, voided or superseded shall remain in effect.

BIDDER SHALL ACKNOWLEDGE RECEIPT OF ADDENDUM IN THE SPACE PROVIDED ON THE BID FORM. FAILURE TO DO SO MAY CONSTITUTE INFORMALITY IN THE BID.

I. General

1. A non-mandatory Pre-Bid Conference was held at the Office of University Facilities on October 30, 2012. The sign-in sheet is attached with this addendum.
2. Bids will be due November 13, 2012 at 2 pm 743 Greene St, Columbia, SC. Bids received after that time will not be accepted. Contact Juaquana Brookins at USC (803)777-3596 if bids are delivered other than in person (by mail, etc.).
3. Blatt PE Center is open 7:00am-8:00pm Monday-Friday and closed on weekends
4. Working after hours or weekends can be setup (occasionally there are events on weekends, but you will be informed of the dates well in advance.) This will be needed for any of the construction that has loud noise; we do not want to disturb classes.
5. See attached fall schedule. Generally, Monday/Wednesday & Tuesday/Thursday classes are consistent.
6. There will not be an additional scheduled site visit, if you would like an additional viewing of the building please call Pete Fisher at 803.777.9346.

II. CHANGES TO TECHNICAL SPECIFICATIONS AND DRAWINGS

<u>Item No.</u>	<u>Description</u>
1.	<u>Refer to Specification Section 16721, Page 9</u> Edwards System Technologies (EST) is an additional approved fire alarm system manufacturer.
2.	<u>Refer to Drawings E1.1A, E1.1B, E1.2A, E1.2B, E1.3A, and E1.3B:</u>

Change note on drawings from:

“All conduit in this room shall be RMC type (Galvanized Rigid Steel) with threaded fittings.”

To read:

“All conduit and associated fittings in this room shall be Aluminum RMC type with threaded fittings.”

3. Refer to Drawing E1.2C: Add one relay-type addressable interface module (AIU) and associated wiring and programming to control power to existing magnetic door holders at the existing double doors located in Vestibule V201 that lead into Corridor H215.
4. General Note: There is an existing wet-pipe sprinkler system in the building that serves various spaces. Include labor and materials to monitor an existing wet-pipe sprinkler riser system – Include two addressable interface units (AIU’s); One to monitor an existing flow switch and one to monitor 5 sprinkler valves. Also include 5 rising-stem and/or rip-cord type valve tamper switches and all associated wiring, raceway, and programming necessary to properly monitor the existing sprinkler system in accordance with NFPA 13 and NFPA 72.

End: Addendum No. 1

Start	End	Customer	Event	Location
Monday, November 12, 2012				
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 310	110
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 520-01	111
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 515-01	135
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 310	Classroom 118
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 515-01	Gym 305 A
9:05 AM	9:55 AM	Dept. of Physical Education	PEDU 366-01	110
9:05 AM	9:55 AM	Dept. of Physical Education	PEDU 570-01	111
9:05 AM	10:20 AM	Dept. of Physical Education	PEDU 575-01	134
9:05 AM	9:55 AM	Dept. of Physical Education	PEDU 300-01	135
9:05 AM	10:55 AM	Dept. of Physical Education	PEDU 292-01	217
9:05 AM	9:55 AM	Dept. of Physical Education	PEDU 300-01	Classroom 118
9:05 AM	10:20 AM	Dept. of Physical Education	PEDU 575-01	Gym 307
9:05 AM	9:55 AM	Dept. of Physical Education - PA	PEDU 104-01	Gym 305 A
10:10 AM	11:00 AM	Dept. of Physical Education	PEDU 300-02	135
10:10 AM	11:00 AM	Dept. of Physical Education	PEDU 300-02	Classroom 118
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 146-03	111
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 107-02	Aerobic Studio
10:10 AM	11:40 AM	Dept. of Physical Education - PA	PEDU 100J-03	Dance 107
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 123-04	Dance 114
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 136-05	Dance 116
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 119	Field A
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 195-01	Gym 305 A/B
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 117-01	Gym 308
10:10 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 105-01	Weight Room 306
11:15 AM	12:05 PM	Department of Theater & Dance	THEA 170-02	134
11:15 AM	12:05 PM	Dept. of Exercise Science	EXSC 303	111
11:15 AM	12:05 PM	Dept. of Physical Education	PEDU 300-04	135
11:15 AM	12:05 PM	Dept. of Physical Education	PEDU 300-04	Classroom 118
11:15 AM	12:05 PM	Dept. of Physical Education - PA	PEDU 102-02	110
11:15 AM	1:10 PM	Dept. of Physical Education - PA	PEDU 350L-01	217
11:15 AM	12:00 PM	Dept. of Physical Education - PA	PEDU 107-06	Aerobic Studio
11:15 AM	12:05 PM	Dept. of Physical Education - PA	PEDU 195-02	Gym 305 A/B

Start	End	Customer	Event	Location
Monday, November 12, 2012				
11:15 AM	12:05 PM	Dept. of Physical Education - PA	PEDU 101-05	Gym 307
11:15 AM	12:05 PM	Dept. of Physical Education - PA	PEDU 102-02	Gym 308
11:15 AM	12:05 PM	Dept. of Physical Education - PA	PEDU 105-02	Weight Room 306
12:20 PM	1:10 PM	Dept. of Physical Education	PEDU 300-05	135
12:20 PM	1:10 PM	Dept. of Physical Education	PEDU 300-05	Classroom 118
12:20 PM	1:10 PM	Dept. of Physical Education - PA	PEDU 139-01	134
12:20 PM	1:10 PM	Dept. of Physical Education - PA	PEDU 139-01/02	Blossom St.
12:20 PM	1:50 PM	Dept. of Physical Education - PA	PEDU 123-05	Dance 114
12:20 PM	1:10 PM	Dept. of Physical Education - PA	PEDU 139-01	Field A
12:20 PM	1:50 PM	Dept. of Physical Education - PA	PEDU 101-04	Gym 307
12:20 PM	1:50 PM	Dept. of Physical Education - PA	PEDU 123-05	Gym 308
1:00 PM	2:00 PM	Dept. of Exercise Science	PHYT 785	111
1:25 PM	2:40 PM	Dept. of Physical Education	PEDU 451	135
1:25 PM	2:15 PM	Dept. of Physical Education - PA	PEDU 100L-01	Dance 107
1:25 PM	2:15 PM	Dept. of Physical Education - PA	PEDU 112-1	Gym 305 A/B
1:25 PM	2:15 PM	Dept. of Physical Education - PA	PEDU 105-04	Weight Room 306
2:30 PM	3:45 PM	Dept. of Exercise Science	UNIV 101	110
2:30 PM	3:45 PM	Dept. of Physical Education	PEDU 263-01	111
2:30 PM	4:00 PM	Dept. of Physical Education - PA	PEDU 177-07	Aerobic Studio
2:30 PM	3:20 PM	Dept. of Physical Education - PA	PEDU 100J-09	Dance 107
2:30 PM	3:20 PM	Dept. of Physical Education - PA	PEDU 137-01	Gym 308
2:45 PM	4:00 PM	Dept. of Physical Education	PEDU263-02	134
3:35 PM	4:25 PM	Dept. of Physical Education - PA	PEDU 100J-01	Dance 107
4:00 PM	5:15 PM	Dept. of Exercise Science	EXSC 531	111
4:00 PM	5:30 PM	Dept. of Physical Education - PA	PEDU 177-04	Aerobic Studio
4:30 PM	5:45 PM	Dept. Of Dance	DANC E380	Dance 107
5:00 PM	6:15 PM	Dept. of Physical Education	PEDU 575-02	135
5:00 PM	6:15 PM	Dept. of Physical Education	PEDU 575-02	Gym 305 A/B
5:30 PM	6:45 PM	Dept. of Physical Education	PEDU 310-04	111

Start	End	Customer	Event	Location
Monday, November 12, 2012				
6:00 PM	8:00 PM	Dept. of Physical Education - PA	PEDU 177-01	Dance 114
6:30 PM	8:00 PM	Dept. of Physical Education - PA	PEDU 180-04	Gym 307
Tuesday, November 13, 2012				
8:00 AM	9:15 AM	Dept. of Physical Education	PEDU 348-01	134
8:00 AM	9:15 AM	Dept. of Physical Education	PEDU 300-03	135
8:00 AM	9:15 AM	Dept. of Physical Education	PEDU 736	217
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 100G-01	Aerobic Studio
8:00 AM	9:15 AM	Dept. of Physical Education	PEDU 300-03	Classroom 118
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 100G-01	Gym 305 A
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 100G-01	Pool Lane A
8:00 AM	8:50 AM	Dept. of Physical Education	PEDU 100G-01	Pool Lane B
8:00 AM	8:50 AM	Dept. of Physical Education - PA	PEDU 100J-07	Dance 107
8:00 AM	9:30 AM	Dept. of Physical Education - PA	PEDU 123-09	Dance 114
9:30 AM	10:45 AM	Dept. of Exercise Science	UNIV 101	110
9:30 AM	12:15 PM	Dept. of Physical Education	PEDU 462	134
9:30 AM	12:15 PM	Dept. of Physical Education	PEDU 360-01	135
9:30 AM	10:45 AM	Dept. of Physical Education	PEDU 348L-02	217
9:30 AM	12:15 PM	Dept. of Physical Education	PEDU 340-01	Gym 305 A/B
9:30 AM	12:15 PM	Dept. of Physical Education	PEDU 440	Gym 307
9:30 AM	10:45 AM	Dept. of Physical Education - PA	PEDU 350-01	111
9:30 AM	11:00 AM	Dept. of Physical Education - PA	PEDU 107-04	Aerobic Studio
9:30 AM	10:20 AM	Dept. of Physical Education - PA	PEDU 100J-08	Dance 107
9:30 AM	10:20 AM	Dept. of Physical Education - PA	PEDU 105-03	Weight Room 306
11:00 AM	12:15 PM	Dept. of Exercise Science	EXSC 351	111
11:00 AM	12:15 PM	Dept. of Physical Education	PEDU 350L-02	217
11:00 AM	12:15 PM	Dept. of Physical Education - PA	PEDU 102-01	110
11:00 AM	12:30 PM	Dept. of Physical Education - PA	PEDU 100I-01	Dance 107
11:00 AM	12:15 PM	Dept. of Physical Education - PA	PEDU 102-01	Gym 308
11:00 AM	12:30 PM	Dept. of Physical Education - PA	PEDU 106-01	Weight Room 306
12:00 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 185-01	Pool Lane A
12:00 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 185-01	Pool Lane B

Start	End	Customer	Event	Location
Tuesday, November 13, 2012				
12:30 PM	1:45 PM	Dept. of Exercise Science	EXSC 780	111
12:30 PM	1:45 PM	Dept. of Physical Education	PEDU 492	217
12:30 PM	1:45 PM	Dept. of Physical Education - PA	PEDU 232-01	134
12:30 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 123-07	Classroom 118
12:30 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 100I-02	Dance 107
12:30 PM	1:20 PM	Dept. of Physical Education - PA	PEDU 100J-04	Gym 307
12:30 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 177-03	Gym 308
12:30 PM	2:00 PM	Dept. of Physical Education - PA	PEDU 106-02	Weight Room 306
2:00 PM	5:00 PM	Dept. of Exercise Science	EXSC 563	110
2:00 PM	3:15 PM	Dept. of Exercise Science	UNIV 101	111
2:00 PM	3:15 PM	Dept. of Physical Education	PEDU 510-01	134
2:00 PM	3:15 PM	Dept. of Physical Education	PEDU 575-03	135
2:00 PM	3:15 PM	Dept. of Physical Education	PEDU 575-03	Gym 305 A/B
2:00 PM	3:15 PM	Dept. of Physical Education	PEDU 510-01	Gym 308
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 100J-05	Aerobic Studio
2:00 PM	3:30 PM	Dept. of Physical Education - PA	PEDU 177-02	Dance 107
2:00 PM	3:30 PM	Dept. of Physical Education - PA	PEDU 180-03	Gym 307
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 129-01	R4
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 129-01	R5
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 129-01	R6
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 129-01	R7
2:00 PM	2:50 PM	Dept. of Physical Education - PA	PEDU 129-01	R8
3:30 PM	5:45 PM	Dept. of Exercise Science	EXSC 191	111
3:30 PM	5:30 PM	Dept. of Physical Education - PA	PEDU 100E-01	Aerobic Studio
3:30 PM	5:00 PM	Dept. of Physical Education - PA	PEDU 100J-06	Dance 107
4:30 PM	7:15 PM	Dept. of Physical Education	PEDU 730	135
5:00 PM	6:15 PM	Dept. of Physical Education	PEDU 575-04	134
5:00 PM	6:15 PM	Dept. of Physical Education	PEDU 575-04	Gym 305 A/B
5:30 PM	7:00 PM	Dept. of Physical Education - PA	PEDU 177-10/11	Dance 114

Start	End	Customer	Event	Location
Tuesday, November 13, 2012				
6:00 PM	6:50 PM	Dept. of Physical Education - PA	PEDU 174-01	Dance 107
7:00 PM	7:50 PM	Dept. of Physical Education - PA	PEDU 170-01	Dance 107



EMSL Analytical, Inc.
 706 Gralin Street, Kernersville, NC 27284
 Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
 Customer PO:
 Received: 11/06/09 10:00 AM
 EMSL Order: 020906494
 EMSL Proj:
 Analysis Date: 11/10/2009

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: #138 Blatt PE Center

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1 020906494-0001	Fireproofing	Tan Fibrous Heterogeneous	97% Cellulose	3% Non-fibrous (other)	None Detected
2 020906494-0002	Sheetrock	Brown/Gray Fibrous Heterogeneous	40% Cellulose	60% Non-fibrous (other)	None Detected
3 020906494-0003	Joint Compound	Gray Non-Fibrous Heterogeneous	1% Cellulose	96% Non-fibrous (other)	3% Chrysotile
4 020906494-0004	Joint Compound	Gray/White Non-Fibrous Heterogeneous	<1% Cellulose	98% Non-fibrous (other)	2% Chrysotile
5 020906494-0005	Ceiling Tile	Gray/Tan/White Fibrous Heterogeneous	40% Cellulose 40% Min. Wool	20% Non-fibrous (other)	None Detected
6 020906494-0006	Sheetrock	Brown/Gray/Tan Fibrous Heterogeneous	55% Cellulose 1% Glass	44% Non-fibrous (other)	None Detected
7 020906494-0007	Ceiling Tile	Gray/White Fibrous Heterogeneous	55% Cellulose 5% Min. Wool	40% Non-fibrous (other)	None Detected

Analyst(s)

Scott Combs (24)

Stephen Bennett, Laboratory Manager
 or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
 Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
 706 Gralin Street, Kernersville, NC 27284
 Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
 Customer PO:
 Received: 11/06/09 10:00 AM
 EMSL Order: 020906494
 EMSL Proj:
 Analysis Date: 11/10/2009

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: #138 Blatt PE Center

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
8-Sheetrock 020906494-0008	Sheetrock	Brown/Gray Fibrous Heterogeneous	60% Cellulose	40% Non-fibrous (other)	None Detected
8-Joint Compound 020906494-0008A	Sheetrock	White Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
9 020906494-0009	Joint Compound	White/Beige Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
10 020906494-0010	Ceiling Tile	Gray/White Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected
11 020906494-0011	Sheetrock	Brown/Gray Fibrous Heterogeneous	55% Cellulose 1% Glass	44% Non-fibrous (other)	None Detected
12 020906494-0012	Joint Compound	White Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
13 020906494-0013	Ceiling Tile	Gray/White Fibrous Heterogeneous	70% Cellulose	30% Non-fibrous (other)	None Detected

Analyst(s)

Scott Combs (24)

Stephen Bennett, Laboratory Manager
 or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
 Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
 706 Gralin Street, Kernersville, NC 27284
 Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
 Customer PO:
 Received: 11/06/09 10:00 AM
 EMSL Order: 020906494

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: #138 Blatt PE Center

EMSL Proj:
 Analysis Date: 11/10/2009

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
14 020906494-0014	Joint Compound	White Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
15 020906494-0015	Sheetrock	Brown/Gray Non-Fibrous Heterogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected
16 020906494-0016	Ceiling Tile	Gray/White Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected
17-Sheetrock 020906494-0017	Sheetrock	Brown/Gray Fibrous Heterogeneous	30% Cellulose 1% Glass	69% Non-fibrous (other)	None Detected
17-Texture 020906494-0017A	Sheetrock	Gray/Tan/Beige Non-Fibrous Heterogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected
18 020906494-0018	Joint Compound	Gray Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
19 020906494-0019	Ceiling Tile	Gray/White Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected

Analyst(s)

Scott Combs (24)

Stephen Bennett, Laboratory Manager
 or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
 Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Ed Pitts**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
Customer PO:
Received: 11/06/09 10:00 AM
EMSL Order: 020906494

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: #138 Blatt PE Center

EMSL Proj:
Analysis Date: 11/10/2009

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
20 020906494-0020	Joint Compound	White Non-Fibrous Heterogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
21 020906494-0021	Sheetrock	Brown/Gray Fibrous Heterogeneous	30% Cellulose 1% Glass	69% Non-fibrous (other)	None Detected
22 020906494-0022	Stucco	Gray Non-Fibrous Heterogeneous	<1% Cellulose	97% Non-fibrous (other)	3% Chrysotile

Analyst(s)

Scott Combs (24)

Stephen Bennett, Laboratory Manager
or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

Samples analyzed by EMSL Analytical, Inc. Kernersville 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321

Reading No	Time	Type	Duration	Units	Sequence	Component	Substrate	Side
2036	11/4/2009 11:46	PAINT		1.36 mg / cm ^2	Final	WALL	CONCRETE	
2037	11/4/2009 11:46	PAINT		3.24 mg / cm ^2	Final	WALL	CONCRETE	
2038	11/4/2009 11:47	PAINT		3.5 mg / cm ^2	Final	WALL	CONCRETE	
2039	11/4/2009 11:47	PAINT		4.57 mg / cm ^2	Final	WALL	CONCRETE	
2040	11/4/2009 11:48	PAINT		2.99 mg / cm ^2	Final	WALL	CONCRETE	
2041	11/4/2009 11:49	PAINT		3.24 mg / cm ^2	Final	WALL	CONCRETE	
2042	11/4/2009 11:49	PAINT		4.06 mg / cm ^2	Final	WALL	CONCRETE	
2043	11/4/2009 11:49	PAINT		3.51 mg / cm ^2	Final	WALL	CONCRETE	
2044	11/4/2009 11:50	PAINT		3.52 mg / cm ^2	Final	WALL	CONCRETE	
2045	11/4/2009 11:52	PAINT		3.51 mg / cm ^2	Final	WALL	CONCRETE	
2046	11/4/2009 11:52	PAINT		3.24 mg / cm ^2	Final	WALL	CONCRETE	
2047	11/4/2009 11:53	PAINT		3.8 mg / cm ^2	Final	WALL	CONCRETE	
2048	11/4/2009 11:53	PAINT		3.52 mg / cm ^2	Final	WALL	CONCRETE	
2049	11/4/2009 11:54	PAINT		3.5 mg / cm ^2	Final	WALL	CONCRETE	
2050	11/4/2009 11:55	PAINT		4.59 mg / cm ^2	Final	WALL	CONCRETE	
2051	11/4/2009 11:55	PAINT		3.24 mg / cm ^2	Final	WALL	CONCRETE	
2052	11/4/2009 11:56	PAINT		3.24 mg / cm ^2	Final	WALL	CONCRETE	
2053	11/4/2009 12:00	PAINT		3.25 mg / cm ^2	Final	WALL	CONCRETE	
2054	11/4/2009 12:00	PAINT		3.52 mg / cm ^2	Final	WALL	CONCRETE	
2055	11/4/2009 12:01	PAINT		5.41 mg / cm ^2	Final	WALL	CONCRETE	
2056	11/4/2009 12:02	PAINT		4.87 mg / cm ^2	Final	WALL	CONCRETE	

Condition	Color	Site	Inspector	Floor	Room	Misc 1	Misc 2
PEELING	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HALL		
PEELING	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HALL		
PEELING	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HALL		
PEELING	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HALL		
PEELING	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HALL		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HANDBALL ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HANDBALL ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HANDBALL ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	SECOND	HANDBALL ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	BASKETBALL COURT		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	BASKETBALL COURT		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	BASKETBALL COURT		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	BASKETBALL COURT		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	WEIGHT ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	WEIGHT ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	WEIGHT ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	THIRD	WEIGHT ROOM		
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	FIRST		102	
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	FIRST		103	
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	FIRST		111	
INTACT	WHITE	BLATT PE CENTER	D WASHINGTON	FIRST		113	

Results	Depth Index	Action Level	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
Null	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		2.62
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.04
Negative	6.03		0.7 < LOD	0.09 < LOD		0.09 < LOD		1.2
Negative	1.61		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.05
Negative	2.08		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.67
Negative	1.04		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.03
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.05
Negative	1.18		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.16
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.07
Negative	1.26		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.05
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.01
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.05
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.03
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1
Negative	1.93		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.05
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		0.96
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1.02
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		1
Negative	1		0.7 < LOD	0.03 < LOD		0.03 < LOD		0.95
Negative	1.42		0.7 < LOD	0.03 < LOD		0.03 < LOD		0.78
Negative	1.91		0.7 < LOD	0.03 < LOD		0.03 < LOD		0.9

FM00324395

USC Work Order

Description HAZMAT SURVEY-138

Site	COLUMBIA	Assigned To	JPROVENCE
Building	138 BLATT PHYSICAL EDUCATION CENTE	Crew	HAZMAT
Floor	Room:	Start Date	Priority 5
Equipment		Due date	11-FEB-10
		Request Date	12-JAN-10 by KALLEY

Request #	FM00324395	Description	HAZMAT SURVEY-138
Parent WO #			

CP Number	CP00285940	BLATT PE CENTER FIRE ALARM UPGRADES
------------------	------------	-------------------------------------

State/Internal Project Number	H27-I851
--------------------------------------	----------

Requestor	FISHER,PETE	Project Manager	FISHER, PETER L.
Telephone	7-9346	Telephone	777-9346
Alternate		Estimated Cost	\$ 0.00
Telephone		Billing	FIXED PRICE
Non-Available Time		53100-W384-57120	(COLUMBIA CAMPUS FIRE ALARM UPGRADES)

Task List

SEE PRELIMINARY PLANS - PETE F 9607372

HAZMAT SURVEY(S) REQUESTED FOR THE FOLLOWING

- _____ FLOOR TILE
- _____ JOINT COMPOUND
- _____ WALLS
- _____ MASTIC
- _____ CEILING TILE
- _____ PIPE INSULATION
- _____ VINYL SHEET FLOORING
- _____ FIREPROOFING
- _____ FUME HOODS/TABLE TOPS
- _____ ROOFING MATERIALS
- _____ FIRE DOORS
- _____ GASKETS/VALVES
- _____ BOILER INSULATION
- _____ ACOUSTICAL POPCORN CEILING
- _____ DUCT WORK
- _____ OTHER (PLEASE DESCRIBE BELOW)

DATE WORK STARTED	CAUSE
--------------------------	--------------

DATE WORK COMPLETED	CONDITION
----------------------------	------------------

EQUIPMENT

CLOSING REMARKS

BENCHSTOCK MATERIALS

Qty	Description	Price Per Unit

Supervisor's Approval _____

Note Date	Title
------------------	--------------

23-FEB-11 HAZMAT SURVEY RESULTS

SURVEY DATE: PREVIOUS DATA

INSPECTOR #: D WASHINGTON II BI-00568

STATUS: THE FOLLOWING MATERIALS HAVE BEEN TESTED FOR ASBESTOS CONTAINING MATERIALS

SHEET ROCK- NEGATIVE FOR ASBESTOS CONTAINING MATERIALS

JOINT COMPOUND- POSITIVE FOR ASBESTOS CONTAINING MATERIALS

CEILING TILE- NEGATIVE FOR ASBESTOS CONTAINING MATERIALS

TEXTURED CEILING MATERIAL (HALLWAYS ON CEILINGS AND STAIRWAYS) -POSITIVE FOR ASBESTOS CONTAINING MATERIALS

BLACK MASTIC ON HVAC DUCT AND PIPES ABOVE CEILING- POSITIVE FOR ASBESTOS CONTAINING MATERIALS

ALL FLOORING AND MASTIC- POSITIVE FOR ASBESTOS CONTAINING MATERIALS

WHITE WALL PAINT- NEGATIVE FOR LEAD BASE PAINT

THE WORK REQUEST DID NOT HAVE ANY SAMPLING INFORMATION CHECKED ON IT. INSPECTORS GATHERED RECENT TESTING INFORMATION THAT THEY THOUGHT WOULD BE DISTURBED IN THE BUILDING FOR THIS JOB. IF ANY MATERIAL YOU COME INTO CONTACT WITH IS NOT LISTED ABOVE PLEASE STOP AND CALL TY RUSSELL FOR TESTING

IF YOU ENCOUNTER ANY SUSPECT MATERIALS IN PLACE AND DEEM IT SUSPECT FOR ASBESTOS PLEASE STOP WORK AND CALL THE ASBESTOS PROGRAM MANAGER FOR FURTHER TESTING

REFER TO THE SURVEY RESULTS DOCUMENT ATTACHED TO THE WO FOR DETAILED INFORMATION.

09-APR-04 ASBESTOS MAY BE PRESENT IN THIS BUILDING

WARNING - ASBESTOS EXPOSURE ALERT - EXPOSURE TO ASBESTOS MAY BE HARMFUL TO YOUR HEALTH.

AS OF 4/1/2004 THE FOLLOWING AREAS WITHIN THE BUILDING HAVE BEEN IDENTIFIED BY SURVEY TO CONTAIN ASBESTOS:

BLDG 138 P. E. CENTER
M2 --> HOT WATER TANK [250 SQ. FT.]
STEAM TUNNEL M2 M3 --> STEAM LINE [237 LIN. FT.]
M2 M3 --> STEAM FITTINGS [36 LIN. FT.]
M2 M3 --> CHILL WATER VALVES [82 SQ. FT.]
M2 M3 --> CHILL WATER ELBOWS [72 LIN. FT.]
--> HOT & COLD WATER LINES [291 LIN. FT.]
M2 M3 --> HOT WATER LINE [250 LIN. FT.]
2ND FLOOR MEN'S LOCKER ROOM --> SPRAY IN [51,312 SQ. FT.]
ALL FLOORS UNDER SIDE OF STAIRWELLS --> SPRAY IN [5,640 SQ. FT.]
M3 --> HOT WATER TANK [70 SQ. FT.]

PLEASE NOTE - IDENTIFICATION OF ASBESTOS CONTAINING COMPONENTS WITHIN THIS STRUCTURE DOES NOT SPECIFICALLY EXCLUDE THE PRESENCE OF ASBESTOS WITHIN OTHER AREAS.

THE FOLLOWING COMMON TYPES OF BUILDING COMPONENTS COULD CONTAIN MATERIALS THAT, WHEN DISTURBED, MIGHT EXPOSE YOU TO ASBESTOS:

1. FLOOR TILE
2. PIPE INSULATION
3. BLACK MASTIC
4. HVAC DUCT MASTIC
5. SPRAYED-ON FIREPROOFING
6. SPRAYED-ON CEILINGS
7. SHEETROCK JOINT COMPOUND

BEFORE DISTURBING THESE TYPES OF COMPONENTS, CONFIRM THAT THEY DO NOT CONTAIN ASBESTOS AND TAKE PROPER PRECAUTIONS AT ALL TIMES.

020906494



107 Haddon Avenue, Westmont, New Jersey 08108

1-800-220-3675

http://www.emsl.com

EMSL ANALYTICAL, Inc. CHAIN OF CUSTODY

EMSL Rep: Uniq S.C. Third Party Billing requires written authorization from third party

Your Name: _____ EMSL-Bill to: _____

Company: atn Ed Pitt Street: _____

Street: _____ Street: _____

Box #: _____ Box #: _____

City/State: _____ Zip: _____ City/State: _____ Zip: _____

Phone Results to: _____ Fax Results to: _____

Name: _____ Name: _____

Telephone #: _____ Fax #: _____

Project Name/Number: #138 Beatt PE Purchase Order #: _____

TURNAROUND TIME

3 Hours 6 Hours 12 Hours 24 Hours 48 Hours 72 Hours 4 Days 5 Days 6-10 Days

SAMPLE MATRIX

Air Bulk Soil Wipe Micro-Vac Drinking Water Wastewater Chips Other

ASBESTOS ANALYSIS

PCM - Air

NIOSH 7400 (A) Issue 2: August 1994

OSHA w/TWA

TEM AIR

AHERA 40 CFR, Part 763 Subpart E

NIOSH 7402 Issue 2

EPA Level II

PLM - Bulk

EPA 600/R-93/116

NY Stratified Point Count

California Air Resource Board (CARB) 435

NIOSH 9002

PLM NOB (Gravimetric) NYS 198.1

EPA Point Count (400 Points)

EPA Point Count (1,000 Points)

Standard Addition Point Count

SOILS

EPA Protocol Qualitative

EPA Protocol Quantitative

EMSL MSD 9000 Method fibers/gram

Superfund EPA 540-R097-028 (dust generation)

TEM BULK

Drop Mount (Qualitative)

Chatfield SOP-1988-02

TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC

ASTM D 5755-95 (Quantitative)

TEM WIPE

ASTM D-6480-99

Qualitative

TEM WATER

EPA 100.1

EPA 100.2

NYS 198.2

LEAD ANALYSIS

Flame Atomic Absorption

Wipe, SW846-7420 ASTM non ASTM

Soil, SW846-7420

Air, NIOSH 7082

Chips, SW846-7420 or AOAC 5.009 (974.02)

Wastewater, SW 846-7420

TCLP LEAD SW846-1311/7420

Graphite Furnace Atomic Absorption

Air, NIOSH 7105

Wastewater, SW846-7421

Soil, SW846-7421

Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma

Wipe, SW846-6010 ASTM non ASTM

Soil, SW846-6010

Air, NIOSH 7300

MATERIALS ANALYSIS

Full Particle Identification

Optical Particle Identification

Dust Mites and Insect Fragments

Particle Size & Distribution

Product Comparison

Paint Characterization

Failure Analysis

Corrosion Analysis

Glove Box Containment Study

Petrographic Examination of Concrete

Portland Cement in Workplace Atmospheres (OSHA ID-143)

Man Made Vitrous Fibers - MMVF's

Synthetic Fiber Identification

Other: _____

MICROBIAL ANALYSIS

Air Samples

Mold & Fungi by Air O Cell

Mold & Fungi by Agar Plate count & id

Bacterial Count and Gram Stain

Bacterial Count and Identification

Water Samples

Total Coliforms, Fecal Coliforms

Escherichia Coli, Fecal Streptococcus

Legionella

Salmonella

Giardia and Cryptosporidium

Wipe and Bulk Samples

Mold & Fungi - Direct Examination

Mold & Fungi - (Culture follow up to direct examination if necessary)

Mold & Fungi - Culture (Count & ID)

Mold & Fungi - Culture (Count only)

Bacterial Count & Gram Stain

Bacterial Count & Identification (3 most prominent types)

Other: _____

IAQ ANALYSIS

Nuisance Dust (NIOSH 0500 & 0600)

Airborne Dust (PM10, TSP)

Silica Analysis by XRD Niosh 7500

HVAC Efficiency

Carbon Black

Airborne Oil Mist

Other: _____

OTHER: _____

Client Sample # (S) _____ TOTAL SAMPLE # 22

Relinquished: _____ Date: _____ Time: _____

Received: _____ Date: _____ Time: _____

Relinquished: _____ Date: _____ Time: _____

Received: _____ Date: 11/6 Time: 10:00

Handwritten: 020906494

Handwritten: # 138

Handwritten: 1 of 3



Reset Form

Print Form

Building # BLATT PE CENTER

Type of Analysis: Lead / Asbestos Date: 11-02-2009

Sample Analysis Turn Around Time 3 DAYS

Area	Sample ID	Material Sampled	Material Location	F/NF	Cond	Quantity	Pot to Disturb
A	1	FIREPROOFING	ABOVE CEILING IN ROOM 202A HALL BEHIND FRONT DESK	F	GOOD	200 SQ FT	LOW
A	2	SHEET ROCK	ABOVE CEILING IN ROOM 202A HALL BEHIND FRONT DESK	F	GOOD	200 SQ FT	LOW
A	3	JOINT COMPOUND	ABOVE CEILING IN ROOM 202A HALL BEHIND FRONT DESK	F	GOOD	80 SQ FT	LOW
A	4	JOINT COMPOUND	ROOM 202 C	F	GOOD	50 SQ FT	LOW
A	5	CEILING TILE	ROOM 202 C	F	GOOD	50 SQ FT	LOW
A	6	SHEET ROCK	ROOM 202 C	F	GOOD	50 SQ FT	LOW
A	7	CEILING TILE	ROOM 212	F	GOOD	70 SQ FT	LOW
A	8	SHEET ROCK	ROOM 212	F	GOOD	70 SQ FT	LOW
A	9	JOINT COMPOUND	ROOM 212	F	GOOD	15 SQ FT	LOW
A	10	CEILING TILE	ROOM 218 C	F	GOOD	100 SQ FT	LOW

License # 00568 FM# FM00319713

Signature JEFF TAYLOR Requestor JEFF TAYLOR

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashinDH@fmc.sc.edu

Ty Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRussse@fmc.sc.edu

Fax # 803-777-3990

Handwritten signature

2 of 3



Reset Form Print Form

Building # Beedy

Type of Analysis: Lead / Asbestos Date:

Sample Analysis Turn Around Time _____

Area	Sample ID	Material Sampled	Material Location	F/NF	Cond	Quantity	Pot to Disturb
A	11	SHEET ROCK	218 C	F	GOOD	100 SQ FT	LOW
A	12	JOINT COMPOUND	218 C	F	GOOD	20 SQ FT	LOW
A	13	CEILING TILE	RM 218 K	F	GOOD	100 SQ FT	LOW
A	14	JOINT COMPOUND	RM 218 K	F	GOOD	20 SQ FT	LOW
A	15	SHEET ROCK	RM 218 K	F	GOOD	100 SQ FT	LOW
A	16	CEILING TILE	RM 216 B	F	GOOD	200 SQ FT	LOW
A	17	SHEET ROCK	RM 26 B	F	GOOD	200 SQ FT	LOW
A	18	JOINT COMPOUND	RM 216 B	F	GOOD	80 SQ FT	LOW
A	18	CEILING TILE	RM 11 D	F	GOOD	50 SQ FT	LOW
A	20	JOINT COMPOUND	RM 11 D	F	GOOD	50 SQ FT	LOW

License # _____ FM# _____ Signature _____ Requestor _____

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashinDH@fmc.sc.edu

Ty Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRusse@fmc.sc.edu

Fax # 803-777-3990



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
Customer PO:
Received: 10/22/10 11:00 AM
EMSL Order: 021007232
EMSL Proj:
Analysis Date: 10/25/2010

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **138 Blatt PE Center**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1-Linoleum <i>021007232-0001</i>	Vinyl	Gray/White Fibrous Heterogeneous		90% Non-fibrous (other)	10% Chrysotile
1-Mastic <i>021007232-0001A</i>	Vinyl	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
2 <i>021007232-0002</i>	Vinyl				Stop Positive (Not Analyzed)
3 <i>021007232-0003</i>	Vinyl				Stop Positive (Not Analyzed)
4-Cove Base <i>021007232-0004</i>	Vinyl Base Molding	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
4-Mastic <i>021007232-0004A</i>	Vinyl Base Molding	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
5-Floor Tile <i>021007232-0005</i>	Tile & Mastic	Beige Fibrous Heterogeneous		97% Non-fibrous (other)	3% Chrysotile

Initial report from 10/25/2010 09:27:49

Analyst(s)

James Cole (12)
Scott Combs (1)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.

706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
Customer PO:
Received: 10/22/10 11:00 AM
EMSL Order: 021007232
EMSL Proj:
Analysis Date: 10/25/2010

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **138 Blatt PE Center**


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
5-Mastic <i>021007232-0005A</i>	Tile & Mastic	Black Non-Fibrous Homogeneous		95% Non-fibrous (other)	5% Chrysotile
6-Cove Base <i>021007232-0006</i>	Vinyl Base Molding	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
6-Mastic <i>021007232-0006A</i>	Vinyl Base Molding	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
7 <i>021007232-0007</i>	Ceiling Tile	White/Beige Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected
8 <i>021007232-0008</i>	Ceiling Tile	White/Beige Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected
9 <i>021007232-0009</i>	Tile & Mastic				Stop Positive (Not Analyzed)
10 <i>021007232-0010</i>	HVAC Duct Mastic	Tan/Black/Silver Fibrous Heterogeneous	20% Cellulose 20% Glass	52% Non-fibrous (other)	8% Chrysotile

Initial report from 10/25/2010 09:27:49

Analyst(s)

James Cole (12)
Scott Combs (1)



Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
Customer PO:
Received: 10/22/10 11:00 AM
EMSL Order: 021007232
EMSL Proj:
Analysis Date: 10/25/2010

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **138 Blatt PE Center**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
12 021007232-0011	Ceiling Tile	Gray/White Fibrous Heterogeneous	45% Cellulose 30% Min. Wool	25% Non-fibrous (other)	None Detected
13 021007232-0012	HVA Duct Mastic				Stop Positive (Not Analyzed)
14 021007232-0013	Tile & Mastic				Stop Positive (Not Analyzed)
15 021007232-0014	HVAC Duct Mastic				Stop Positive (Not Analyzed)
16 021007232-0015	Textured Ceiling	White/Beige Non-Fibrous Heterogeneous		97% Non-fibrous (other)	3% Chrysotile
17 021007232-0016	Textured Ceiling				Stop Positive (Not Analyzed)
18 021007232-0017	Textured Ceiling				Stop Positive (Not Analyzed)

Initial report from 10/25/2010 09:27:49

Analyst(s)

James Cole (12)
Scott Combs (1)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
Customer PO:
Received: 10/22/10 11:00 AM
EMSL Order: 021007232
EMSL Proj:
Analysis Date: 10/25/2010

Fax: (803) 777-7334 Phone: (803) 777-7000
Project: **138 Blatt PE Center**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19 021007232-0018	Textured Ceiling				Stop Positive (Not Analyzed)
20 021007232-0019	Textured Ceiling				Stop Positive (Not Analyzed)
21 021007232-0020	Textured Ceiling				Stop Positive (Not Analyzed)
22 021007232-0021	Textured Ceiling				Stop Positive (Not Analyzed)
23 021007232-0022	Textured Ceiling				Stop Positive (Not Analyzed)
24 021007232-0023	Textured Ceiling				Stop Positive (Not Analyzed)
25 021007232-0024	Textured Ceiling				Stop Positive (Not Analyzed)

Initial report from 10/25/2010 09:27:49

Analyst(s)

James Cole (12)
Scott Combs (1)

Stephen Bennett, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC NVLAP Lab Code 102104-0, CA ELAP 2689, Virginia 3333-000228, West Virginia LT000321



EMSL Analytical, Inc.
 706 Gralin Street, Kernersville, NC 27284

Phone: (336) 992-1025 Fax: (336) 992-4175 Email: greensborolab@emsl.com

Attn: **Darryl Washington**
University of South Carolina
743 Greene Street
Columbia, SC 29208

Customer ID: UNSC62
 Customer PO:
 Received: 10/22/10 11:00 AM
 EMSL Order: 021007232
 EMSL Proj:
 Analysis Date: 10/25/2010

Fax: (803) 777-7334 Phone: (803) 777-7000
 Project: **138 Blatt PE Center**


**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM
 via EPA/600/R-93/116 Section 2.5.5.1**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
11-Cove Base 021007232-0025	Vinyl Base Molding	Black Non-Fibrous Homogeneous	100.0	None	No Asbestos Detected
11-Mastic 021007232-0025A	Vinyl Base Molding	Tan Non-Fibrous Heterogeneous	100.0	None	No Asbestos Detected

Initial report from 10/25/2010 09:27:49

Analyst(s)

 Stephen Bennett (2)



 Stephen Bennett, Laboratory Manager
 or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
 Samples analyzed by EMSL Analytical, Inc. 706 Gralin Street, Kernersville NC

7232



107 Haddon Avenue, Westmont, New Jersey 08108

1-800-220-3675

http://www.emsl.com

EMSL ANALYTICAL, Inc. CHAIN OF CUSTODY

EMSL Rep: Univ of South Carolina

Third Party Billing requires written authorization from third party

Your Name: att. 2010 Company: _____

EMSL-Bill to: _____

Street: _____

Street: _____

Box #: Dumont Washington

Box #: _____

City/State: 917-0391 Zip: _____

City/State: _____ Zip: _____

Phone Results to: 2-1 Pierre Name: _____

Fax Results to: _____ Name: _____

Telephone #: 917-0517

Fax #: _____

Project Name/Number: 138 Blatt Pc Center

Purchase Order #: _____

TURNAROUND TIME

- 3 Hours
- 6 Hours
- 12 Hours
- 24 Hours
- 48 Hours
- 72 Hours
- 4 Days
- 5 Days
- 6-10 Days

SAMPLE MATRIX

- Air
- Bulk
- Soil
- Wipe
- Micro-Vac
- Drinking Water
- Wastewater
- Chips
- Other

ASBESTOS ANALYSIS

PCM - Air

- NIOSH 7400 (A) Issue 2: August 1994
- OSHA W/TA

TEM AIR

- AHERA 40 CFR, Part 763 Subpart E
- NIOSH 7402 Issue 2
- EPA Level II

PLM - Bulk

- EPA 600/R-93/116
- NY Stratified Point Count
- California Air Resource Board (CARB) 435
- NIOSH 9002
- PLM NOB (Gravimetric) NYS 198.1
- EPA Point Count (400 Points)
- EPA Point Count (1,000 Points)
- Standard Addition Point Count

SOILS

- EPA Protocol Qualitative
- EPA Protocol Quantitative
- EMSL MSD 9000 Method fibers/gram
- Superfund EPA 540-R097-028 (dust generation)

TEM BULK

- Drop Mount (Qualitative)
- Chatfield SOP-1988-02
- TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC

- ASTM D 5755-95 (Quantitative)

TEM WIPE

- ASTM D-6430-99
- Qualitative

TEM WATER

- EPA 1631.1
- EPA 163.2
- NYS 198.2

OTHER: _____

LEAD ANALYSIS

Flame Atomic Absorption

- Wipe, SW846-7420 ASTM non ASTM
- Soil, SW846-7420
- Air, NIOSH 7082
- Chips, SW846-7420 or AOAC 5.009 (974.02)
- Wastewater, SW 846-7420
- TCLP LEAD SW846-1311/7420

Graphite Furnace Atomic Absorption

- Air, NIOSH 7105
- Wastewater, SW846-7421
- Soil, SW846-7421
- Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma

- Wipe, SW846-6010 ASTM non ASTM
- Soil, SW846-6010
- Air, NIOSH 7300

MATERIALS ANALYSIS

- Full Particle Identification
- Optical Particle Identification
- Dust Mines and Insect Fragments
- Particle Size & Distribution
- Product Comparison
- Paint Characterization
- Failure Analysis
- Corrosion Analysis
- Glove Box Containment Study
- Petrographic Examination of Concrete
- Portland Cement in Workplace Atmospheres (OSHA 10-143)
- Man Made Vitreous Fibers - MMVF's
- Synthetic Fiber Identification
- Other: _____

MICROBIAL ANALYSIS

Air Samples

- Mold & Fungi by Air O Cell
- Mold & Fungi by Agar Plate count
- Bacterial Count and Gram Stain
- Bacterial Count and Identification

Water Samples

- Total Coliforms, Fecal Coliforms
- Escherichia Coli, Fecal Streptococci
- Legionella
- Salmonella
- Giardia and Cryptosporidium

Wipe and Bulk Samples

- Mold & Fungi - Direct Examination
- Mold & Fungi - (Culture follow direct examination if necessary)
- Mold & Fungi - Culture (Count)
- Mold & Fungi - Culture (Count)
- Bacterial Count & Gram Stain
- Bacterial Count & Identification (3 most prominent types)
- Other: _____

IAQ ANALYSIS

- Nuisance Dust (NIOSH 0500 & 0501)
- Airborne Dust (PM10, TSP)
- Silica Analysis by XRD | Niue
- HVAC Efficiency
- Carbon Black
- Airborne Oil Mists
- Other: _____

Client Sample # (S) _____

TOTAL SAMPLE # 25

Relinquished: _____ Date: _____
 Received: mw Date: _____
 Relinquished: _____ Date: _____
 Received: _____ Date: _____

Date: _____ Time: _____
 Date: 10/22/10 Time: 11:00
 Date: _____ Time: _____
 Date: _____ Time: _____

perform
stop
positive



7232

Reset Form
Print Form

Building # BLATT PE CENTER Sample Analysis Date: 10-20-2010
Type of Analysis: Lead / Asbestos Turn Around Time 24 HRS

Area	Sample ID	Material Sampled	Material Location	F/NF	Cond	Quantity	Pot to Disturb
A	1	WHITE VINYL FLOORING	FLOORING OF BIG ROOM 108	NF	G	628 SQ FT	LOW
A	2	WHITE VINYL FLOORING	FLOORING OF BIG ROOM 108	NF	G	628 SQ FT	LOW
A	3	WHITE VINYL FLOORING	(From Wg) FLOORING OF BIG ROOM 108	NF	G	628 SQ FT	LOW
B	4	BLACK VINYL BASE MOLDING	ON BLOCK WALL MATERIAL OF RM 108	NF	G	85 LIN FT	LOW
C	5	GREEN 12X12 TILE AND MASTIC	SMALL WALKWAY OFF OF ROOM 108	NF	G	48 SQ FT	LOW
B	6	BLACK VINYL BASE MOLDING	SMALL WALKWAY OFF OF ROOM 108	NF	G	12 LIN FT	LOW
D	7	2X4 WHITE CEILING TILE	CEILING OF SMALL WALKWAY OFF RM 108	F	G	48 SQ FT	LOW
D	8	2X4 WHITE CEILING TILE	ROOM 108 A	F	G	528 SQ FT	LOW
C	9	GREEN 12X12 TILE AND MASTIC	ROOM 108A	F	G	528 SQ FT	LOW
E	10	HVAC BLACK DUCT MASTIC	ON HVAC DUCT ABOVE CEILING ROOM 108 A	NF	G	.5 CB FT	LOW

License # ASBI-00568 FM# FM00346872 Signature [Signature] Requestor JEFF ABRAMS

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296 Darryl Washington 803-777-2399 Ty Russell 803-777-1208
720 College St. 720 College St. 720 College St.
Columbia, SC 29208 Columbia, SC 29208 Columbia, SC 29208
EHP@fmc.sc.edu WashinDH@fmc.sc.edu NTRussse@fmc.sc.edu
Fax # 803-777-3990



7232

Reset Form Print Form

Building # _____ Sample Analysis Type of Analysis: Lead / Asbestos Date:

Turn Around Time _____

Area	Sample ID	Material Sampled	Material Location	F/NF	Cond	Quantity	Pot to Disturb
B	11	BLACK VINYL BASE MOLDING	(7cm) ON BLOCK WALL MATERIAL OF ROOM 108 A	NF	G	40 LIN FT	LOW
D	12	2X4 WHITE CEILING TILE	CEILING TILE FROM ROOM 108C	F	G	140 SQ FT	LOW
E	13	HVAC BLACK DUCT MASTIC	(7cm) ON HVAC DUCT ABOVE CEILING ROOM 108C	NF	G	.2 CB FT	LOW
C	14	GREEN 12X12 TILE AND MASTIC	(7cm) UNDER CARPET IN ROOM 108 B	NF	G	168 SQ FT	LOW
E	15	HVAC BLACK DUCT MASTIC	ON HVAC DUCT ABOVE CEILING IN ROOM 108 B	NF	G	.3 CB FT	LOW
F	16	TEXTURED CEILING MATERIAL	SPRAYED ON CEILING OUTSIDE LONG HALL LEFT SIDE	F	G	168 SQ FT	LOW
F	17	TEXTURED CEILING MATERIAL	SPRAYED ON CEILING OUTSIDE LONG HALL LEFT SIDE	F	G	168 SQ FT	LOW
F	18	TEXTURED CEILING MATERIAL	SPRAYED ON CEILING OUTSIDE LONG HALL LEFT SIDE	F	G	168 SQ FT	LOW
F	19	TEXTURED CEILING MATERIAL	SPRAYED ON CEILING OUTSIDE LONG HALL LEFT SIDE	F	G	168 SQ FT	LOW
F	20	TEXTURED CEILING MATERIAL	SPRAYED ON CEILING OUTSIDE LONG HALL LEFT SIDE	F	G	168 SQ FT	LOW

License # _____ FM# _____ Signature _____ Requestor _____

Send lab results in PDF format as soon as possible to:

Ed Pits 803-777-3296
720 College St.
Columbia, SC 29208
EHP@fmc.sc.edu

Darryl Washington 803-777-2399
720 College St.
Columbia, SC 29208
WashinDH@fmc.sc.edu

Ty Russell 803-777-1208
720 College St.
Columbia, SC 29208
NTRusse@fmc.sc.edu

Fax # 803-777-3990



Reset Form

Print Form

7232

Building # _____ Type of Analysis: Lead / Asbestos Date:

Sample Analysis Turn Around Time _____

Area	Sample ID	Material Sampled	Material Location	F/NF	Cond	Quantity	Pot to Disturb
F	21	TEXTURED CEILING MATERIAL	SPRAYED CEILING OF ROOM 108	F	G	628 SQ FT	LOW
F	22	TEXTURED CEILING MATERIAL	SPRAYED CEILING OF ROOM 108	F	G	628 SQ FT	LOW
F	23	TEXTURED CEILING MATERIAL	SPRAYED CEILING OF ROOM 108	F	G	628 SQ FT	LOW
F	24	TEXTURED CEILING MATERIAL	SPRAYED CEILING OF ROOM 108	F	G	628 SQ FT	LOW
F	25	TEXTURED CEILING MATERIAL	SPRAYED CEILING OF ROOM 108	F	G	628 SQ FT	LOW
			ALL CEILING TEXTURE APPEARS TO BE THE SAME				
			IN BOTH AREAS.				

License # _____ FM# _____ Signature _____ Requestor _____

Send lab results in PDF format as soon as possible to:

Ed Pitts 803-777-3296

720 College St.

Columbia, SC 29208

EHP@fmc.sc.edu

Darryl Washington 803-777-2399

720 College St.

Columbia, SC 29208

WashinDH@fmc.sc.edu


Ty Russell 803-777-1208

720 College St.

Columbia, SC 29208

NTRusse@fmc.sc.edu

Fax # 803-777-3990



University of South Carolina
Columbia, South Carolina

Pre Bid for Blatt PE Center Fire Alarm
Project Number: H27-1851-B
Pre Bid Date & Time: October 30, 2012, 10am

ATTENDEE'S NAME

COMPANY NAME & MAILING ADDRESS

Roger FARIAS

Precision Fire Solutions
2229 Lemphart Rd
W. Columbia, S.C. 29169

PHONE# 803 796 2722

FAX# 803 796 0144

EMAIL rafarias@PrecisionFireSolutions.com

Darrell Russell

Brad's Electric, Inc.

604 Greenwood Rd.

West Columbia, SC 29169

PHONE# 803-791-7344

FAX# 803-796-7455

EMAIL darrell.russell@bradselectricinc.com

MIKE MURRAY

SIMPLEXGRINWELL

3243 Sunset Blvd

West Columbia

PHONE# 803-476-0006

FAX# 803-476-0039

EMAIL micmurray@simplexgrinwell.com

Mark Mills

Priority One Security

14 Interchange Blvd.

Greenville SC 29607

PHONE# (864) 288-1900

FAX# (864) 281-9444

EMAIL mmills@priority1security.com

Make sure to include your company name (on this form) as registered with LLR.



University of South Carolina
Columbia, South Carolina

Pre Bid for Blatt PE Center Fire Alarm
Project Number: H27-1851-B
Pre Bid Date & Time: October 30, 2012, 10am

ATTENDEE'S NAME

Joe Land

Pete Ful

Maquana Brooks

COMPANY NAME & MAILING ADDRESS

Bella Engineering Assoc,
7 Clusters Court, Suite 201
Columbia, SC 29210

PHONE# (803) 731-0650

FAX# (803) 731-2880

EMAIL jwland@bellsouth.net
CSC

PHONE# 777 9346

FAX#

EMAIL llsc

PHONE# 777.3596

FAX#

EMAIL

PHONE#

FAX#

EMAIL

Make sure to include your company name (on this form) as registered with LLR.