



## STRUCTURAL REPAIRS WILLIAMS BRICE STADIUM UNIVERSITY OF SOUTH CAROLINA PROJECT NO: CP00394073 – FM00458985

## Addendum One July 25, 2014

This addendum modifies the Contract Documents only in the manner and to the extent stated herein and shown on any accompanying drawings and will become a part of the Contract Documents. Except as specified or otherwise indicated by this addendum, all work shall be in accordance with the basic requirements of the Contract Documents.

### **GENERAL:**

- 1. Attached is the *sign-in sheet* for the Pre-Bid meeting held Thursday, July 24, 2014, indicating all attendees.
- 2. Per the Pre-Bid Meeting on July 24, all questions regarding this project were to be submitted in writing to the architect no later than Friday, July 25. Email acceptable. Any questions received after this time will not be addressed.

The architect's email address: Keith Myhand: kmyhand@jcsarchitects.com

- 3. The contractor is responsible for providing his own dumpster.
- 4. The owner will designate a nearby restroom onsite for the contractor's use. The contractor is to leave the restroom as clean as he found it upon project completion.

### **DRAWINGS:**

1. <u>Sheet A201:</u> Delete Keynote #1 and related scope from this project. Owner has completed this work.

2. <u>Sheet A201; Photo #3 / Keynote #3:</u> Add the following photos to this scope. For bidding purposes, the contractor is to account for 150 linear feet of expired condensate piping to be replaced and provided with the continuous aluminum jacket as noted.










3. <u>Sheet A203; Photo #1</u>: The block low wall currently shown is being completed by the owner. Replace the current photo with the one below showing the adjacent vender low walls and repair this condition per Keynote#1.



4. Sheet A203; Add the following photos as Photos #3 along with the following Keynote #3 to this sheet. This area is located along the concourse wall panels between the 3<sup>rd</sup> and fourth bents. The area is approximately 20' long and about 16" wide. "Key Note #3 – Remove top area of concrete as required. Treat reinforcing steel with rust inhibitor, apply bonding agent and apply new concrete topping SIKA Top 122 Plus. Apply new concrete topping in a manner as to provide a slight cant to slope water away from the wall panel."







Jumper Carter Sease/Architects, P.A.
412 Meeting Street, West Columbia, South Carolina 29169
Phone 803.791.1020 Fax 803.791.1022
Page 4 of 5

5. Sheet A203: Add the following photo as Photo #4 along with the following Keynote #4 to this sheet. This area is on the northern end wall of lower deck and approximately 30' above the ground level. This wall is opposite of the northeast ramp. "Key Note #4 – Remove loose concrete and clean. Treat reinforcing steel with rust inhibitor, apply bonding agent and apply new concrete repair mortar SIKA Top 123 Plus and Armatec A110. Finish tomatch adjacent surface upon completion of repair."



**END OF ADDENDUM** 

# University of South Carolina

Columbia, South Carolina

Project Name: WBS Structural Repairs
Project Number: CP00394073
Pre Bid Date & Time: July 24, 2014 @ 3 pm

Name	Company Name	Address	Phone #	Email
Pat Lauro	Watertight Systems,	P.O. BOX 1625 Lexington, SC29071	5639	plauro @ watertightsystems.com
Don Rueter	215+ Century Waterposeing Columbia, 5,5, 20210	16,08) Lord Special BSOH	20210 20210 20210	20210 20210 (803) 451-2627 Devotor & 100.00
Eric Tolen	Southern Mechanicale	latick sc 28884	843-917-8799	Southern Mr & yakoo.com
	Contract Bld,	114 BUNKER D 83-552-564	883-855-4649	
CINTAN MIG	S, Stems LE WESTCHASS.	WESTCOLA SC.		WOAUSYZOSC.RR.Com
JER Bannon	Use - Hazmat		(853)917-4387	(853)917-4387 brannonno fuc. Sc. edu
FRIC MELARO USC HARVAST	USCHAMAS		509-3376	SUR-3376 Melaro @ mailbox, sc edu
CHRIS KRUEGER	AUTRADE SERVICES	III WOODRUFF CT AIKEN SC, 29803	(803)646-8472	(803)646-8472 ALLTRASECK & GMAIL. COM
HANDA CROUCH	CONTRACT BUILDING P.O. BOX 2237 SYSTEMS W. COLA., SC 291	7	605:743:21650	CHANCROUTIESC.RR.COM
Kip M=Coy	Watts + Associates		803-309-018	803-309-0193 Kip@wattswaterpreating. Com

<sup>\*\*\*\*</sup>By signing this sheet you agree to receive information electronically.

# University of South Carolina Columbia, South Carolina

Project Name: WBS Structural Repairs
Project Number: CP00394073
Pre Bid Date & Time: July 24, 2014 @ 3 pm

Name	Company Name	Address	Phone #	Email
KIRIN Blank	Store Wland	500 North Hozhans	724747	EBlack @ Struckland
1 acres	otay	Charlotte KC	121/2	waterproof way com
7	COMOLINA	1304 thymand	SM2-777 -2012	in the way box so point
いいまんないい	ATHLETICS	ST.	000 111 077	Commence of the Commence of th
2		47 Sxx1 0-8011	402021-JAN	
Johnie Downing	Pyramid Contracting	Imp 50 29063	0-1130 0000	Local Alexander Control
-		1512 XDB 07	803-751-8788	803-71/-8788 Till The Board of the start of the
Joel Dutton	CORE CONSTRUCTION	V. Colo SC 25171		
	<del>(</del>	412 Meeting St.	803-791-102	
Kell h Myhand	JCS Architects	W. Cola. SC 29169		Try handle Jesaf Chitecis. Com
	-1-	1	<i>b</i> .	II Division in the territory
Shelard Leavelette				Shearerette C) CSarchineris.com
Fraguero		743 Greenest	803,777.	HOW I Show St edil.
U Brookus	28n	Cola, SC	35%	I moderne Mc, screwe
( Phr. +	()(')	743 Green	90338815600	
COMOCOLIOS	750	(	(	

<sup>\*\*\*\*</sup>By signing this sheet you agree to receive information electronically.