

U.S.C.A. Pickens Salley House Renovation Aiken, South Carolina OSE Project No. H29-1336 MPS Project No. 10293.00 5-2 January 27, 2012

ADDENDUM NO. 1

The following clarifications, amendments, additions, deletions, revisions, and/or modifications are hereby made a part of the Contract Documents and change the original documents only in the manner and to the extent stated below:

GENERAL

ITEM No. 1 Pre-Bid Conference:

A list of attendees at the pre-bid conference held on January 24, 2012 at 10:00 AM EST is attached.

Request for Substitutions:

Per AIA Document A701 Instruction to Bidders 3.3.2, all requests for substitutions must be submitted 10 days prior to the bid date. Per Supplementary Instructions to Bidders 3.3.2.1, all requests for substitutions must be submitted on the Request for Substitute form.

Questions:

All questions must be submitted in writing to the Architect no later than 5:00 PM on January 30, 2012.

Addenda:

Per 00201-OSE Standard Supplemental Instruction to Bidders no addenda will be issued later than the fifth calendar day prior to the date set for receipt of bids.

Therefore, the final date for issuing an addendum is Wednesday February 1, 2012.

Project Manual

ITEM No. 2 **SE-330 – Bid Form**

Substitute the attached SE-330 Lump Sum Bid Form that has been modified to reflect the modification of 6.2 Bid Alternate #1 as follows:

The scope of work outlined on Sheet A1.4, in Item 13 shall be designated as an add alternate.

ITEM No. 3 Lead Based Paint Survey

Attached for your information and use is a copy of the lead based paint survey for the project performed by Alternative Construction & Environmental Solutions, Inc.; dated March 10, 2011.

DRAWINGS

ITEM No. 3 **S101 Structural Renovations, Plan Sections, Notes**

Attached is the S101 sheet noted on the cover sheet and the scope of work outlined on this sheet shall be added to the project.

A1.4 Reference Photos and Scope of Work

Item 13 New Roofing shall be an add alternate to the project and shall be addressed on the Bid Form as such.

A1.6 Reference Photos and Scope of Work

The scope of work Item 17, Rebuild Dormer shall be modified to include the following:

New roofing and flashing for dormers and modification of existing main roofing and flashing as required by new dormer construction.

End of Addendum No. 1

Attachments:

Pre-Bid Conference Attendees List	1 page
SE-330 Lump Sum Bid Form	6 Pages
Lead Based Paint Survey	5 pages
S101 – Structural Renovations Plan Sections and Notes	1 sheet

USCA Pickens Salley House Renovation Pre-Bid Attendees

January 24, 2012 MPS Project No. 10293.00

Frank S. Dahl Lindler Const Co. Inc 201 Oak Pointe Dr. Lexington, SC 29072 P O Box 5496 Columbia, SC 29250 803-479-1611 803-779-3609 (f) Hos1@bellsouth.net Frankdsr1@gmail.com

Larry Carraway
Carraway Construction
130 Cromer Dr.
Sumter, SC 29150
803-469-0550
803-469-0580 (f)
larrycarraway@yahoo.com

John Heape 4H Construction 551 Delafield Drive Summerville, SC 29483 843-697-0239 mgheape@aol.com

David McGhee
Sitec, LLC
217 Fairfield St., NE
Aiken, SC 29801
706-840-3980
803-644-7082 (f)
David.sitec@comcast.net
sitec@bellsouth.net

Chris Smyrl
Window – Works
P O Box 290866
Columbia, SC 29229
cmsmyrl@window-works.com

Lisa Groft USC Aiken 471 University Parkway Aiken, SC 29801 803-641-2856 (o) 803-295-6851 (c) 864-641-3516 (f) lisag@usca.edu

John Cumbee USC Aiken 471 University Parkway Aiken, SC 29801 803-507-3305 864-641-3516 (f) johnc@usca.edu

Juaquana Brookins
Lekita Hargrove
Kay Keisler
University of South Carolina
743 Greene St
Columbia SC 29208
803.777.3596
803.777.7334 (f)
jbrookin@fmc.sc.ed
Hargrave@sc.edu

Bidders shall submit bids on only Bid Form SE-330.
BID SUBMITTED BY: (Bidder's Name)
BID SUBMITTED TO:
(Owner's Name)
FOR PROJECT: PROJECT NAME USCA Pickens Salley House Renovation
PROJECT NUMBER <u>H29-I336</u>
<u>OFFER</u>
§ 1. In response to the Invitation for Construction Bids and in compliance with the Instructions to Bidders for the above-named Project, the undersigned Bidder proposes and agrees, if this Bid is accepted, to enter into a Contract with the Owner on the terms included in the Bidding Documents, and to perform all Work as specified or indicated in the Bidding Documents, for the prices and within the time frames indicated in this Bid and in accordance with the other terms and conditions of the Bidding Documents.
 § 2. Pursuant to Section 11-32-3030(1) of the SC Code of Laws, as amended, Bidder has submitted Bid Security as follows in the amount and form required by the Bidding Documents: Bid Bond with Power of Attorney Electronic Bid Bond Cashier's Check (Bidder check one)
§ 3. Bidder acknowledges the receipt of the following Addenda to the Bidding Documents and has incorporated the effects of said Addenda into this Bid: ADDENDUM No:
§ 4. Bidder accepts all terms and conditions of the Invitation for Bids, including, without limitation, those dealing with the disposition of Bid Security. Bidder agrees that this Bid, including all Bid Alternates, if any, may not be revoked or withdrawn after the opening of bids, and shall remain open for acceptance for a period of 60 Days following the Bid Date, or for such longer period of time that Bidder may agree to in writing upon request of the Owner. § 5. Bidder herewith offers to provide all labor, materials, equipment, tools of trades and labor, accessories, appliances, warranties and guarantees, and to pay all royalties, fees, permits, licenses and applicable taxes necessary to complete the following items of construction work: § 6.1 BASE BID WORK_(as indicated in the Bidding Documents and generally described as follows): Exterior improvements and renovations to the Pickens Salley House on the campus of USC Aiken,
, which sum is hereafter called the Base Bid. (Bidder - insert Base Bid Amount on line above)

§ 6.2 BID ALTERNATES - as indicated in the Bidding Documents and generally described as follows:
ALTERNATE # 1 (Brief Description): The scope of work outlined on Sheet A1.4, in Item 13 shall be designated as
an add alternate.
☐ ADD TO or ☐ DEDUCT FROM BASE BID:
(Bidder to Mark appropriate box to clearly indicate the price adjustment offered for each alternate)
ALTERNATE # 2 (Brief Description): ADD TO or DEDUCT FROM BASE BID: (Bidder to Mark appropriate box to clearly indicate the price adjustment offered for each alternate)
ALTERNATE # 3 (Brief Description):
ADD TO or DEDUCT FROM BASE BID:
(Bidder to Mark appropriate box to clearly indicate the price adjustment offered for each alternate)

§ 7. LISTING OF PROPOSED SUBCONTRACTORS PURSUANT TO SECTION 3020(b)(i), CHAPTER 35, TITLE 11 OF THE SOUTH CAROLINA CODE OF LAWS, AS AMENDED – (See Instructions on the following page BF-3A)

Bidder shall use the below-listed Subcontractors in the performance of the Subcontractor Specialty work listed:

SUBCONTRACTOR SPECIALTY By License Classification and/or Subclassification (Completed by Owner)	SUBCONTRACTOR'S PRIME CONTRACTOR'S NAME (Must be completed by Bidder) BASE BID	SUBCONTRACTOR'S PRIME CONTRACTOR'S SC LICENSE NUMBER
Painting		
Masonry		
	ALTERNATE 1	
	ALTERNATE 2	
	ALTERNATE 3	

If a Bid Alternate is accepted, Subcontractors listed for the Bid Alternate shall be used for the work of both the Alternate and the Base Bid work.

INSTRUCTIONS FOR SUBCONTRACTOR LISTING

- 1. Section 7 of the Bid Form sets forth a list of subcontractor specialties for which bidder is required to identify by name the subcontractor(s) Bidder will use to perform the work of each listed specialty. Bidder must identify only the subcontractor(s) who will perform the work and no others.
- 2. For purposes of subcontractor listing, a Subcontractor is an entity who will perform work or render service to the prime contractor to or about the construction site. Material suppliers, manufacturers, and fabricators that will not perform physical work at the site of the project but will only supply materials or equipment to the bidder or proposed subcontractor(s) are not subcontractors and Bidder should not insert their names in the spaces provided on the bid form. Likewise, Bidder should not insert the names of sub-subcontractors in the spaces provided on the bid form but only the names of those entities with which bidder will contract directly.
- 3. Bidder must only insert the names of subcontractors who are qualified to perform the work of the listed specialties as specified in the Bidding Documents and South Carolina Licensing Laws.
- **4.** If under the terms of the Bidding Documents, Bidder is qualified to perform the work of a specialty listed and Bidder does not intend to subcontract such work but to use Bidder's own employees to perform such work, the Bidder must insert its own name in the space provided for that specialty.
- 5. If Bidder intends to use multiple subcontractors to perform the work of a single specialty listing, Bidder must insert the name of each subcontractor Bidder will use, preferably separating the name of each by the word "and". If Bidder intends to use both his own employees to perform a part of the work of a single specialty listing and to use one or more subcontractors to perform the remaining work for that specialty listing, bidder must insert his own name and the name of each subcontractor, preferably separating the name of each with the word "and".
- 6. Bidder may not list subcontractors in the alternative nor in a form that may be reasonably construed at the time of bid opening as a listing in the alternative. A listing that requires subsequent explanation to determine whether or not it is a listing in the alternative is non-responsive. If bidder intends to use multiple entities to perform the work for a single specialty listing, bidder must clearly set forth on the bid form such intent. Bidder may accomplish this by simply inserting the word "and" between the name of each entity listed for that specialty. Owner will reject as non-responsive a listing that contains the names of multiple subcontractors separated by a blank space, the word "or", a virgule (that is a /), or any separator that the Owner may reasonably interpret as a listing in the alternative.
- 7. If Bidder is awarded the contract, bidder must, except with the approval of the owner for good cause shown, use the listed entities to perform the work for which they are listed.
- **8.** If bidder is awarded the contract, bidder will not be allowed to substitute another entity as subcontractor in place of a subcontractor listed in Section 7 of the Bid except for one or more of the reasons allowed by the SC Code of Laws.
- 9. Bidder's failure to insert a name for each listed specialty subcontractor will render the Bid non-responsive.

§ 8. LIST OF MANUFACTURERS, MATERIAL SUPPLIERS, AND SUBCONTRACTORS OTHER THAN SUBCONTRACTORS LISTED IN SECTION 7 ABOVE (FOR INFORMATION ONLY): Pursuant to instructions in the Invitation for Bids, if any, Bidder will provide to Owner upon the Owner's request and within 24 hours of such request, a listing of manufacturers, material suppliers, and subcontractors, other than those listed in Section 7 above, that Bidder intends to use on the project. Bidder acknowledges and agrees that this list is provided for purposes of determining responsibility and not pursuant to the subcontractor listing requirements of SC Code Ann § 11-35-3020(b)(i).

§ 9. TIME OF CONTRACT PERFORMANCE AND LIQUIDATED DAMAGES

- a. CONTRACT TIME: Bidder agrees that the Date of Commencement of the Work shall be established in a Notice to Proceed to be issued by the Owner. Bidder agrees to substantially complete the Work within <u>90</u> calendar days from the Date of Commencement, subject to adjustments as provided in the Contract Documents.
- b. LIQUIDATED DAMAGES: Bidder further agrees that from the compensation to be paid, the Owner shall retain as Liquidated Damages the sum of \$125.00 for each calendar day the actual construction time required to achieve Substantial Completion exceeds the specified or adjusted time for Substantial Completion as provided in the Contract Documents. This sum is intended by the parties as the predetermined measure of compensation for actual damages, not as a penalty for nonperformance.

§ 10. AGREEMENTS

- a. Bidder agrees that this bid is subject to the requirements of the law of the State of South Carolina.
- b. Bidder agrees that at any time prior to the issuance of the Notice to Proceed for this Project, this Project may be canceled for the convenience of, and without cost to, the State.
- c. Bidder agrees that neither the State of South Carolina nor any of its agencies, employees or agents shall be responsible for any bid preparation costs, or any costs or charges of any type, should all bids be rejected or the Project canceled for any reason prior to the issuance of the Notice to Proceed.

§ 11. ELECTRONIC BID BOND

By signing below, the Principal is affirming that the identified electronic bid bond has been executed and that the Principal and Surety are firmly bound unto the State of South Carolina under the terms and conditions of the AIA Document A310, Bid Bond, included in the Bidding Documents.

Electronic Bid Bond	Number:	
Signature and Title:		

TELEPHONE:____

EMAIL: _____

BID FORM	
BIDDER'S TAXPAYER IDENTIFICATION	
FEDERAL EMPLOYER'S IDENTIFICATION NUMBER:	
OR	
SOCIAL SECURITY NUMBER:	
CONTRACTOR'S CLASSIFICATIONS AND SUBCLASSIFICATIONS WITH LIMITA	TIONS
Classification(s)& Limits:	
Subclassification(s) & Limits:	
SC Contractor's License Number(s):	
CERTIFICATIONS MADE BY BOTH THE PERSON SIGNING AND THE BIDDER, INCL LIMITATION, THOSE APPEARING IN ARTICLE 2 OF THE INSTRUCTIONS TINVITATION FOR BIDS, AS DEFINED IN THE INSTRUCTIONS TO BIDDERS INCORPORATE BY REFERENCE. SIGNATURE	O BIDDER. THE
BIDDER'S LEGAL NAME:	
ADRESS:	
BY: DATE:	
(Signature)	



ALTERNATIVE CONSTRUCTION & ENVIRONMENTAL SOLUTIONS, INC.

2247 Wrightsboro Road Augusta, GA 30904

Mailing Address: PO Box 3229, Augusta, GA 30914-3229
Telephone: 706-262-2000 Facsimile: 706-262-3299 www.aces-usa.com

March 10, 2011

Client:

University of South Carolina Aiken

471 University Parkway

Aiken, South Carolina 29801

ATTN: Ms Lisa Groft

Project:

Lead-Based Paint Survey

Pickens-Salley House Campus of USC Aiken Aiken, South Carolina

Report Number: 1136-102-001

1.0 SCOPE

On March 10, 2011, a representative of Alternative Construction & Environmental Solutions, Inc. (ACES) conducted a lead-based paint survey of the exterior and interior of the above referenced building located on the campus of USC Aiken in Aiken, South Carolina.

The purpose of this work was to identify existing lead levels in paint by X-ray Fluorescence (XRF) located at this facilities.

2.0 SITE INSPECTION

A site inspection was performed to determine current condition of the painted surfaces. Most surfaces examined contained intact painted surfaces. The property is a single-story, wood-framed house constructed in 1828 which currently houses administrative office of the University of South Carolina Aiken.

3.0 SAMPLING AND ANALYSIS

Sampling was accomplished utilizing a Niton XRF analyzer. All paint schemes were identified and readings were taken of each. All results are included in Attachment I as readings 93 through 195.

4.0 ATTACHMENTS

Attachment I

XRF Measurements

Attachment II

Certifications

Alternative Construction & Environmental Solutions, Inc.

Report Number: 1136-102-001

5.0 CONCLUSION AND RECOMMENDATIONS

Of the 95 readings taken, 57 were found to contain greater than 1 mg/cm² concentration of lead, which constitutes lead-based paint. Please see Attachment I to identify room equivalents, components and testing combinations.

Although lead above the HUD threshold was found on many of the interior and
exterior painted surfaces, few of these surfaces showed signs of peeling or flaking and
most surfaces appeared to have been sealed by a new surface coat. Appropriate
measures should be taken to protect workers and occupants if any of these lead
containing components are to be disturbed by drilling, sanding, cutting, etc. in the
course of renovation activity.

OSHA regulation 29 CFR 1926.62 requires employers to provide adequate protection to their workers that may be exposed to lead dust in excess of the action level of 30 micrograms per cubic meter of air. Where lead is present at any level of concentration, the Federal regulation requires employers to perform assessment exposure monitoring during any demolition/renovation activity that would create lead dust. If no employee is exposed to the action level during this initial assessment, further monitoring can be suspended. Although OSHA does not accept XRF as an absolute negative result, it has been utilized as an immediate indicator for work practices.

OSHA recognizes that Housing and Urban Development (HUD) and the Environmental Protection Agency (EPA) find XRF analyzers acceptable for analyzing lead in paint at their clearance level of 1.0 mg/cm². OSHA also recognizes that some instruments can measure accurately at substantially lower levels. However, while XRF analyzers may be an acceptable method of analysis for meeting HUD/EPA requirements, OSHA's concerns are different from those of HUD and EPA. OSHA's mission is to provide a safe and healthful working environment for American workers. To accomplish this task in the area of lead, OSHA relies primarily on airborne measurements to determine employee exposure. OSHA does not consider any method that relies solely on the analysis of bulk materials or surface content of lead (or other toxic material) to be acceptable for safely predicting employee exposure to airborne contaminants.

If any new or conflicting information becomes available at a later date, please advise ACES and any appropriate revisions and/or comments will be made. This report was prepared for the client and should not be reproduced, except in whole, and only with the written approval of ACES.

ALTERNATIVE CONSTRUCTION & ENVIRONMENTAL SOLUTIONS, INC.

Dan D. Troutman

President'

Steve Connor Project Manager

Kelly Burntle

DDT/SPC/kmb

Attachments

Lead-Based Paint Survey Pickens-Salley House, USC Aiken, Aiken, SC

						Pickens-Salley	House, USC A	Aiken, Aiker	n, SC						
Reading No	Inspector	Location	Level	Room	Side	Component	Substrate	Color	Condition	Address	Results	Depth Index	Action Level	PbC	Units
93														5.63	mg/cn
94	Connor	Calibration							141	the same of the same of the same of	Negative	1.07	1	0.9	mg / cn
95	Connor	Exterior	N/A	N/A	A	Column	Wood	White	Intact	P-S HOUSE USCA	Positive	8.19	1	9.6	mg/cr
96	Connor	Exterior	N/A	N/A	Α	Column	Wood	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cn
97	Connor	Exterior	N/A	N/A	Ā	Column	Wood	White	Intact	P-S HOUSE USCA	Positive	6.84	1	3.3	mg/cr
98	Connor	Exterior	N/A	N/A	Α	Handrail	Wood	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cr
99	Connor	Exterior	N/A	N/A	Α	Handrail	Wood	White	intact	P-S HOUSE USCA	Negative	4.46	1	0.3	mg / cr
100	Connor	Exterior	N/A	N/A	Α	Handrail	Wood	White	Intact	P-S HOUSE USCA	Positive	9.35	31.0	5.3	mg / ci
101	Connor	Exterior	N/A	N/A	Α	Handrail	Wood	White	Intact	P-S HOUSE USCA	Positive	3.0	3,	5.4	mg/c
102	Connor	Exterior	N/A	N/A	A	Handrail	Wood	White	Intact	P-S HOUSE USCA	Positive	10	2	7.1	mg/c
103	Connor	Exterior	N/A	N/A	Ā	Column	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	8.2	mg/c
104	Connor	Exterior	N/A	Porch	Α	Stairs	Wood	Gray	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/c
105	Connor	Exterior	N/A	Porch	Α	Stair Riser	Wood	Gray	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cı
106	Connor	Exterior	N/A	Porch	Α	Wali	Wood	White	Intact	P-S HOUSE USCA	Negative	5	1	0.9	mg/c
107	Connor	Exterior	N/A	Porch	A	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	9.1	mg/c
108	Connor	Exterior	N/A	Porch	A	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	9	mg/c
109	Connor	Exterior	N/A	Porch	A	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	10.7	mg / c
110	Connor	Exterior	N/A	Porch	A	Window Frame	Wood	White	Cracking	P-S HOUSE USCA	Positive	10	1	9.7	mg/c
111	Connor	Exterior	N/A	Porch	Α	Window Shutter	Wood	Black	Cracking	P-S HOUSE USCA	Negative	3.98	1	0.01	mg/c
112	Connor	Exterior	N/A	Porch	Α	Window Shutter	Wood	Black	Cracking	P-S HOUSE USCA	Negative	1	1	0	mg/c
113	Connor	Exterior	N/A	Porch	Top	Ceiling	Wood	White	Cracking	P-S HOUSE USCA	Positive	10	1	9.6	mg/c
114	Connor	Exterior	N/A	Porch	Α	Door	Wood	White	Cracking	P-S HOUSE USCA	Negative	8.2	1	0.6	mg/c
115	Connor	Exterior	N/A	Porch	A	Door Frame	Wood	White	Cracking	P-S HOUSE USCA	Positive	4.98	1	3.1	mg/c
115	Connor	Interior	1st Floor	Conference Room	В	Fireplace Mantle	Wood	White	Intact	P-S HOUSE USCA	Positive	4.76	1	24.5	mg/c
117	Connor	Exterior	N/A	Porch	Bottom	Floor	Wood	Gray	Intact	P-S HOUSE USCA	Negative	2.76	1	0.03	mg / c
118	Connor	Exterior	N/A	Porch	Bottom	Floor	Wood	Gray	Intact	P-S HOUSE USCA	Negative	6.08	1	80.0	mg / c
119	Connor	Exterior	N/A	N/A	A	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	13.4	mg/c
120	Connor	Exterior	N/A	N/A	A	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	14.5	mg / c
121	Connor	Exterior	N/A	N/A	Δ	Trim-EAVES	Wood	White	Intact	P-S HOUSE USCA	Positive	10	3	12.5	mg/c
122	Connor	Exterior	N/A	N/A	D	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	12.7	mg/c
123	Connor	Exterior	N/A	N/A	D	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	12.1	mg/c
124	Connor	Exterior	N/A	N/A	. D	Trim	Wood	White	intact	P-S HOUSE USCA	Negative	1.36	1	0.19	mg / cı
125	Connor	Exterior	N/A	N/A	D	Trim	Wood	White	Intact	P-S HOUSE USCA	Negative	8.92	1	0.7	mg / c
126	Connor	Exterior	N/A	N/A	D	Trim	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	5.4	rng / ci
127	Connor	Exterior	N/A	N/A	C	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	5.8	mg / c
128	Connor	Exterior	N/A	N/A	С	Stairs	Wood	Gray	Peeling	P-S HOUSE USCA	Negative	1	1	0	mg / ci
129	Connor	Exterior	N/A	N/A	С	Handrail	ivietal	Black	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cr
130	Connor	Exterior	N/A	N/A	С	Gutter/Downspout	ivietal	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cı
132	Connor	Exterior	N/A	N/A	C	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	7.1	ing / ci
133	Connor	Exterior	N/A	N/A	С	Gutter/Downspout	Metal	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cr
134	Connor	Exterior	N/A	N/A	В	Wall	Wood	White	Intact	P-S HOUSE USCA	Negative	10	1	0.4	mg / cr
135	Connor	Exterior	N/A	N/A	В	Wall	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	8.9	mg / ci
136	Connor	Exterior	N/A	N/A	В	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	8.3	mg / c
137	Connor	Exterior	N/A	N/A	В	Trim-EAVES	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	9.5	mg / cr
		Interior	1st Floor	Chancellor's Office	A	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	1	1	C	mg / cn
138	Connor		1st Floor	Chancellor's Office	A	Door	Wood	White	Intact	P-S HOUSE USCA	Negative	4.48	1	0.5	mg / cm
140	Connor	Interior	Ter Floor	Chancellor 2 Office	A	10001	9+00u	varitee	muct	. 51,555 6561			_		5,


Lead-Based Paint Survey Pickens-Salley House, USC Aiken, Aiken, SC

						Pickens-Salley	House, USC A	aiken, Aiken	, SC						
142	Connor	Interior	1st Floor	Chancellor's Office	В	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	2.3	mg/cm²
143	Connor	Interior	1st Floor	Chancellor's Office	8	Trim Base Mildg	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	1.5	mg/cm²
144	Connor	Interior	1st Floor	Chancellor's Office	В	Window Sill	Wood	White	Intact	P-S HOUSE USCA	Negative	7.86	1	0.6	mg/cm²
145	Connor	Interior	1st Floor	Vice Chancellor's Office	Α	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	1.68	1	0	mg/cm²
146	Connor	Interior	1st Floor	Vice Chancellor's Office	C	Window Casing	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	1.6	mg / cm²
148	Connor	Interior	1st Floor	Vice Chancellor's Office	D	Door Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	7.19	1.	1.3	mg/cm²
149	Connor	Interior	1st Floor	Powder Room	С	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cm ²
150	Connor	Interior	1st Floor	Powder Room	Top	Ceiling	Drywall	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/cm ²
151	Connor	Interior	1st Floor	Powder Room	D	Window Sill	Wood	White	Intact	P-S HOUSE USCA	Negative	4.37	1	0.13	mg/cm²
152	Connor	Interior	1st Floor	Hall	С	Trim Base Mildg	Wood	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/cm ²
153	Connor	Interior	1st Floor	Administration Staff Office	Α	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	10	13.1	1.3	mg / cm²
154	Connor	Interior	1st Floor	Administration Staff Office	С	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/cm²
155	Connor	Interior	1st Floor	Administration Staff Office	D	Door Jamb	Wood	White	Intact	P-S HOUSE USCA	Positive	7.04	1	1.1	mg/cm ²
156	Connor	Interior	1st Floor	Conference Room	В	Wall	Drywall	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/cm ²
157	Connor	Interior	1st Floor	Conference Room	В	Cabinet Door	Wood	White	Intact	P-S HOUSE USCA	Positive	3.67	1	18.6	mg/cm²
158	Connor	Interior	1st Floor	Conference Room	୍ଦ	Trim Base Wildg	Wood	White	Intact	P-S HOUSE USCA	Positive	4.39	1 3	17.6	mg / cm ²
150	Connor	Interior	1st Floor	Conference Room	Тор	Trim Crown Wildg	Wood	\a/hite	Intact	P-S HOUSE USCA	Positive	4.69	1	25	mg/cm ²
161	Connor	Interior	1st Floor	Conference Room	8	Fireplace	Wood	White	Intact	P-S HOUSE USCA	Positive	7.29	1	24.7	mg/cm ²
162	Connor	interior	1st Floor	Conference Room	D	Wall Lower	Wood	White	Intact	P-S HOUSE USCA	Positive	6.3	1	15.1	mg / cm ²
163	Connor	Interior	1st Floor	Conference Room	D	Door	Wood	White	intact	P-S HOUSE USCA	Positive	10	1	22.9	mg / cm ²
164	Connor	Interior	1st Floor	Front Foyer	A	Door	Wood	White	intact	P-S HOUSE USCA	Positive	3.76	3.	23.7	mg/cm ²
165	Connor	Interior	1st Floor	Front Foyer	D	Wall Upper	Drywall	White	Intact	P-S HOUSE USCA	Negative	3.07	1	0.01	mg / cm ²
166	Connor	Interior	1st Floor	Front Foyer	D	Wall Lower	Wood	White	Intact	P-S HOUSE USCA	Positive	4.99	- I	21.3	mg / cm ² mg / cm ²
167	Connor	interior	1st Floor	Jamle Raynor's Office	A	Window Sill	Wood	White	Intact	P-S HOUSE USCA	Positive	3.1	*	2.5 12.8	mg / cm²
168	Connor	Interior	1st Floor	Jamie Raynor's Office	В	Wall Lower	Wood	White	Intact	P-S HOUSE USCA	Positive	9.15	- X - W	10.7	mg / cm²
169	Connor	Interior	1st Floor	Jamie Raynor's Office	D	Fireplace Mantie	Wood	White	intact	P-S HOUSE USCA	Positive	8.14 6.00	*	13.7	mg / cm ²
170	Connor	Interior	1st Floor	Jamie Raynor's Office	C	Shelves	Wood	White	Intact	P-S HOUSE USCA	Positive	6.09	¥	1.7	mg / cm²
171	Connor	Interior	1st Floor	Kitchen	B	Window Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	7.2	1	0	mg / cm ²
172	Connor	Interior	1st Floor	Kitchen	В	Cabinet	Wood	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cm ²
173	Connor	Interior	1st Floor	Kitchen	A	Wall	Drywall	Beige	Intact	P-S HOUSE USCA P-S HOUSE USCA	Negative Negative	1	1	0	mg / cm²
174	Connor	Interior	1st Floor	Rear Entrance	C	Door	Wood	White	Intact	P-S HOUSE USCA	Positive	2.32	*	4.4	mg / cm ²
175	Connor	Interior	1st Floor	Rear Entrance	A	Door Frame	Wood	White	Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cm ²
176	Connor	Interior	1st Floor	Judith Goodwin's Office	D	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	4.32	1	0.7	mg / cm²
177	Connor	Interior	1st Floor	Judith Goodwin's Office	В	Door Casing	Wood	White	Intact	P-S HOUSE USCA	Positive	3.56	i.	17.6	mg / cm²
178	Connor	Interior	1st Floor	Support Staff Office	C	Fireplace	Wood	White	Intact	P-S HOUSE USCA	Positive	4.84	1	16.6	mg / cm²
179	Connor	Interior	1st Floor	Support Staff Office	В	Trim Base Midg	Wood	White	Intact	P-S HOUSE USCA	Negative	1	177 1	0	mg / cm ²
180	Connor	Interior	1st Floor	Support Staff Office	В	Wall	Drywall	Beige White	Intact	P-S HOUSE USCA	Positive	2.49	1	5.7	rng / cm²
181	Connor	Interior	1st Floor	Bathroom	A	Window Sill	beoW booW	White	Intact	P-S HOUSE USCA	Positive	10	1	31	mg / cm ²
182	Connor	Interior	1st Floor	Bathroom	C	Trim Base Midg	Wood	White	Intact	P-S HOUSE USCA	Positive	3.38	1	3.8	mg / cm ²
183	Connor	Interior	1st Floor	Preston Sparks' Office	Α	Window Frame			Intact	P-S HOUSE USCA	Negative	1	1	0	mg / cm²
184	Connor	Interior	1st Floor	Preston Sparks' Office	A	Wall Door	Drywall Wood	White White	Intact	P-S HOUSE USCA	Positive	10	1	21.4	mg / cm²
185	Connor	Interior	1st Floor	Preston Sparks' Office	C			White	Intact	P-S HOUSE USCA	Positive	3.86	1	13.9	mg / cm²
186	Connor	Interior		Finance Office (Norma Toner)	C	Trim Door	Wood Wood	White	Intact	P-S HOUSE USCA	Negative	10	1	-0.28	mg / cm²
187	Connor	Interior		Finance Office (Norma Toner)	C	Window	Wood	White	Intact	P-S HOUSE USCA	Positive	8.6	1	28.9	mg / cm²
188	Cennor	Interior		Finance Office (Norma Toner)	D B	Trim Base Midg	Wood	White	Intact	P-S HOUSE USCA	Positive	3.54	1	19.9	rng / cm²
189	Connor	Interior		Finance Office (Norma Toner)		Door Frame	Wood	White	Intact	P-S HOUSE USCA	Positive	1.91	1	4.1	mg/cm²
190	Connor	interior	1st Floor	D. Boggs' Office	A	DOOL LIGHT	WI STATE	eringe.	intact	a reason addr.	G. H.				

Lead-Based Paint Survey

Pickens-Salley House, USC Aiken, Aiken, SC

191	Connor	Interior	1st Floor	D. Boggs' Office	D	Window Sill	Wood	White	Intact	P-S HOUSE USCA	Positive	10	1	16.9	mg / cm²
192	Connor	Interior	1st Floor	D. Boggs' Office	Č	Window Casing	Wood	White	intact	P-S HOUSE USCA	Positive	10	1	20	mg/cm²
193	Connor	Interior	1st Floor	D. Boggs' Office	В	Trim Base Mildg	Wood	White	Intact	P-S HOUSE USCA	Positive	2.14	2	2.7	mg/cm²
194	Connor	Interior	1st Floor	D. Boggs' Office	В	Wall	Drywall	Beige	Intact	P-S HOUSE USCA	Negative	1	1	0	mg/cm²
195	Connor	Calibration				•					Positive	1.12	1	1	mg/cm²



- MND.

 A MOGRICATIONS FOR THE BUILDING DO NOT BIONERCANTLY ALTER THE MAIN WIND FORCE RESSTING SYSTEM

 B THEREFORE THE EXISTING LATERAL (WIND) FORCE RESISTING SYSTEM IS NOT UPGRADED TO CURPENT BUL DODE STANDARDS

 SE SMIC

 MODRICATIONS FOR THE BUILDING DO NOT SIGNAFICANTLY ALTER THE MAIN SEISMIC RESISTING SYSTEM ADDITIONALLY THEY

 DO NOT INCREASE THE STRUCTURES MASS BY MOSE THAN 5 FERFENT

 THEREFORE THE EXISTING LATERAL (SEISMIC) FORCE PESISTING SYSTEM IS NOT UPGRADED TO CURPENT BE CODE STANDARD

UVE LOADS: PEP 2006 IBC

- 8 OLITING OF LCAD-BEARING WOOD STUDS IS NOT PERMITTED WITHOUT SPECER, APARQUAL FROM THE ENGINEER OF PECCED

an smith cmillan | pazd 0 E

USCA Pickens Salley Hous Renovation State Project No. H29-1336

964 O OWNER REVIEW

STRUCTURAL RENOVATIONS PLAN, SECTIONS & NOTES

10293.00

S-101