

# Work Order Cost Summary

Selected Date Range for Request Dates:7/1/2016 - 12/31/2016 Order By Location

WOID	Description	Location	Labor Hours	Labor Cost	Purchase Cost	Inventory Cost	Total Costs	
2703	build a wall dividing the 200 main office into 2 separate offices. wall with insulation and a 3/0 door right swing put wall under the drop in the ceiling and meet the wall to the right where the corner is a 45 degree angle	Pacer Commons (928)	0	\$0.00	\$0.00	\$0.00	\$0.00	
3106	paint bad spots in all rooms and LR from water damage	Pacer Commons (928)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4605	A/c not working	Pacer Commons (928)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4700	Hall way A/C seems to be not working on 4th floor low end side	Pacer Commons (928)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5360	There is a round cover missing over the sprinkler across from room M207.	Pacer Commons (928)	0	\$0.00	\$0.00	\$0.00	\$0.00	
3961	Please fix air conditioning unit in Pacer Crossings Laundry Room. We propped open the door to keep the room ventilated.	Pacer Crossing (929)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4220	erv 3 crossing not working correctly Fan is bypassed in the controller	Pacer Crossing (929)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4308	Fire Loop Trouble called in by alarm company.	Pacer Crossing (929)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5385	Elevator on the left bar is broken	Pacer Crossing (929)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4103	Every since last week, starting Sunday, September 4, 2016, I've been getting bit up by something but never could figure out what was biting me. Here it is 1:30 in the morning and I get bit once again. I finally saw what bit me. BED BUGS!!!! I killed something earlier but wasn't thinking bed bugs until I actually looked at this one.	Pacer Downs (927)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4312	EHS Inspection deficiency - Housing - all outside electrical receptacles must be GFCI or on a GFCI breaker (see photo page 8 Housing storage and work area)	Pacer Downs (927)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5236	AC is out again	Pacer Downs (927)	0	\$0.00	\$0.00	\$0.00	\$0.00	
4928	Monthly - 927A-Quarterly HVAC/Mech Check - Refer to PM schedule details.	Pacer Downs Community Building (927A)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5168	Door handle broke at Pacer Market	Pacer Downs Community Building (927A)	1	\$14.82	\$0.00	\$0.00	\$14.82	
5289	Door Handle popped off half door, on Officer side.	Pacer Downs Community Building (927A)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5544	We need a new battery for the police vehicle. It is a Dodge Durango.	Pacer Downs Community Building (927A)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5729	The panic bar on the front door of the Pacer Market has been missing for several weeks and needs to be replaced. See Santana	Pacer Downs Community Building (927A)	0	\$0.00	\$0.00	\$0.00	\$0.00	
5766	Monthly - 927A-Quarterly HVAC/Mech Check - Refer to PM schedule details.	Pacer Downs Community Building (927A)	0	\$0.00	\$0.00	\$0.00	\$0.00	
<b>Count: 18 Work Orders</b>			<b>Grand Total:</b>	1	\$14.82	\$0.00	\$0.00	\$14.82